District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Page 1 of 5

| Incident ID | NAPP2221727230 |
|----------------|----------------|
| District RP | |
| Facility ID | |
| Application ID | |

Release Notification

Responsible Party

| Responsible Party: Enterprise Field Services, LLC | OGRID: 241602 |
|---------------------------------------------------------------|---------------------------------------------|
| Contact Name: Thomas Long | Contact Telephone: 505-599-2286 |
| Contact email:tjlong@eprod.com | Incident # (assigned by OCD) nAPP2221727230 |
| Contact mailing address: 614 Reilly Ave, Farmington, NM 87401 | |

Location of Release Source

Latitude 36.597674

Longitude -107.776343

_NAD 83 in decimal degrees to 5 decimal places)

| Site Name: Lateral C-28 | Site Type Natural Gas Gathering Pipeline |
|-------------------------------------|---------------------------------------------|
| Date Release Discovered: 08/04/2022 | Serial # (if applicable) N/A |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|----------|
| N | 3 | 27N | 9W | San Juan |

Surface Owner: State Federal Tribal Private (Name: BLM)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

| Crude Oil | Volume Released (bbls) | Volume Recovered (bbls) |
|------------------|--------------------------------------------------------------------------------|-----------------------------------------|
| Produced Water | Volume Released (bbls) | Volume Recovered (bbls) |
| | Is the concentration of dissolved chloride in the produced water >10,000 mg/l? | Yes No |
| Condensate | Volume Released (bbls): Estimated 5 BBLs | Volume Recovered (bbls): None |
| 🛛 Natural Gas | Volume Released (Mcf): 28 | Volume Recovered (Mcf): None |
| Other (describe) | Volume/Weight Released (provide units) | Volume/Weight Recovered (provide units) |
| Lubrication Oil | | |

Cause of Release: On July 5, 2022, Enterprise had a release of natural gas from the Lateral C-28 pipeline. The pipeline was isolated, depressurized, locked and tagged out. No liquids were released to the ground surface. No washes were affected. No fire nor injuries occurred. Due to the road conditions, Enterprise began repairs and remediation on August 4, 2022 at which time determined that this release was reportable per NMOCD regulation due to the volume of impacted subsurface soil. A third party corrective action report will be submitted with the "Final C-141."

| v | | | NAPP2221727230 |
|---------------------------------------------------------------------|------------------------------------------------------------------|----------------------|----------------|
| | | | |
| | | | |
| Was this a major release as defined by 19.15.29.7(A) NMAC? | If YES, for what reason(s) does the responsible party consider t | his a major release? | |
| 🗌 Yes 🗌 No | | | |
| If YES, was immediate no | tice given to the OCD? By whom? To whom? When and by wh | at means (phone, em | ail, etc)? |
| | Initial Response | | |

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \boxtimes The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have <u>not</u> been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| Printed Name: | Thomas J. Long | Title: Senior Environmental Scientist | |
|-----------------------------------------|-------------------------|-----------------------------------------------------------|--|
| Signature: email: tjlon <u>g@epr</u> | Thomas Long- rod.com | Date: <u>08-05-22</u> Telephone: _ <u>505-599-2286</u> | |
| OCD Only Received by: | Jocelyn Harimon | 08/05/2022 Date: | |

| 🕄 GasCal - [mvolume] | | | | - [| x c |
|----------------------|-----------------------|----------|-------------------------|---------------|---------|
| 🖏 File | | | | | - 8 × |
| | Gas | Voluma | e Calculations | | |
| | | | Factors | | |
| | Meter Tube Size : | 4 | Orifice Factor : | 28.34945 | |
| PSIG PSIA | Orifice Plate Size : | .375 | Temperature Factor : | 1.00000 | |
| | Pressure: (PSIG) : | 73 | Gravity Factor : | 1.24611 | |
| Static Pressure | Differential : | 2022 | Fpv Factor : | 1.00664 | |
| Up Down | Temperature : | 60 | Reynolds Number : | 1.00021 | |
| | Gravity : | .644 | Expansion Factor : | .73763 | |
| | Mole % CO2 : | 0 | C Prime : | 26.23652 | |
| | Mole % N2 : [| 0 | Beta Ratio : | .0938 | |
| | Pressure Base : | 14.73 | Pressure Base Factor : | 1.00000 | |
| | Temperature Base : | 60 | | | |
| Hours Minutes | Barometric Pressure : | 12 | | | |
| | Flow Time: (Hours) | 2 | Volume (MCF) : | 21.754 | |
| | BTU Value : | 1034.0 | Volume (MMBTU) : | 22.493 | |
| | 1 | | | | |
| | | | | | |
| | | Input BT | U Value | | |
| | , | | | | |
| Main Menu [| Diff/Volume Plate Cha | nge Weyn | nouth Analysis Retro/Se | tpoint Blowdo | wn Cal. |

Released to Imaging: 8/5/2022 10:35:06 AM

.



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

| Operator: | OGRID: |
|--------------------------------|-------------------------------------------|
| Enterprise Field Services, LLC | 241602 |
| PO Box 4324 | Action Number: |
| Houston, TX 77210 | 131806 |
| | Action Type: |
| | [C-141] Release Corrective Action (C-141) |

CONDITIONS

| Created By | | Condition Date |
|------------|------|-------------------|
| jharimon | None | 8/5/2022 |

Page 5 of 5

Action 131806