

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2230526211
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Chevron U.S.A., Inc.	OGRID: 4323
Contact Name: Jessica Zemen	Contact Telephone: 432-530-9187
Contact email: jessicazemen@chevron.com	Incident # (assigned by OCD)
Contact mailing address: 6301 Deauville Blvd Midland, TX 79706	

Location of Release Source

Latitude: 32.40448 _____ Longitude: -103.55576 _____
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: DL 10 15 OGOPOGO FEDERAL COM #422H	Site Type: Oil
Date Release Discovered: 10/20/2022	API# (if applicable): 30-025-49906

Unit Letter	Section	Township	Range	County
I	10	22S	33E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls): 1091 bbls	Volume Recovered (bbls): 1000 bbls
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

A third party's main water supply line to the frac operations had an equipment failure when the manifold slid out of the manifold head clamp.

Incident ID	nAPP2230526211
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Release volume was over 25 bbls.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Jessica Zemen sent an email to Mike Bratcher on 10/21/2022 detailing the release information.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Jessica Zemen</u>	Title: <u>Lead Environmental Specialist, Field Support</u>
Signature: <u>Jessica K Zemen</u>	Date: <u>10/31/2022</u>
email: <u>jessicazemen@chevron.com</u>	Telephone: <u>432-530-9187</u>
<u>OCD Only</u>	
Received by: <u>Jocelyn Harimon</u>	Date: <u>11/01/2022</u>

State of New Mexico
Oil Conservation Division

Page 3

Incident ID	nAPP2230526211
District RP	
Facility ID	
Application ID	

Spill Calculations:

Area	Standing Liquid	In Soil	dimensions / shape	Oil Volume	Water Volume
1	2 inches		rectangular (169*72*0.1667)		361.27
2	0.25 inches		rectangular (135*20*0.0208)		10.02
3					
4					
5					
6					
7					
8					
Total Fluid				0	371

6 Vacuum Trucks Loads

6 x 120 bbls. = 720 bbls.

Total Fluid Released

720 bbls. + 371 bbls. = **1091 bbls.**

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 155118

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 155118
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	11/1/2022