District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

_)

| Incident ID | NAPP2230754633 |
|----------------|----------------|
| District RP | |
| Facility ID | |
| Application ID | |

Release Notification

Responsible Party

| Responsible Party: Maverick Permian, LLC | OGRID: 331199 |
|---|---|
| Contact Name: Bryce Wagoner | Contact Telephone: 928-241-1862 |
| Contact email: Bryce.Wagoner@mavresources.com | Incident # (assigned by OCD) NAPP2230754633 |
| Contact mailing address: 1410 NW County Road Hobbs, NM 88240 | |

Location of Release Source

Latitude 32.549475_____

Longitude -103.190427_____

| (NAD 83 in decimal degrees to 5 decimal places) | |
|---|--|
|---|--|

| Site Name SEMU Permian South Header | Site Type |
|--|-----------------------------------|
| Date Release Discovered October 10, 2022 | API# (if applicable) 30-025-07861 |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|--------|
| С | 30 | 20 S | 38 E | Lea |

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

| eased (bbls) 4.55 bbls | |
|--|---|
| cascu (0018) 4.55 0018 | Volume Recovered (bbls) 0 |
| ntration of dissolved chloride in the ater >10,000 mg/l? | ☐ Yes ⊠ No |
| eased (bbls) | Volume Recovered (bbls) |
| eased (Mcf) | Volume Recovered (Mcf) |
| ight Released (provide units) | Volume/Weight Recovered (provide units) |
| | ight iceleased (provide units) |

Cause of Release

The release was caused by valve malfunction on a flow line resulting in a minor release. The release occurred off pad. The source of the release has been stopped and the impacted area has been secured.

| | Page 2 of |
|----------------|----------------|
| Incident ID | NAPP2230754633 |
| District RP | |
| Facility ID | |
| Application ID | |

| Was this a major release as defined by 19.15.29.7(A) NMAC? | If YES, for what reason(s) does the responsible party consider this a major release? |
|--|---|
| 🗌 Yes 🖾 No | |
| If YES, was immediate no | otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? |

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| Printed Name:Bryce Wagoner | Title:Permian HSE Specialist II |
|--------------------------------------|---------------------------------|
| Signature: | Date:10/242022 |
| email:Bryce.Wagoner@mavresources.com | Telephone:928-241-1862 |
| | |
| OCD Only | |
| Received by: Jocelyn Harimon | Date:11/03/2022 |

| Pooled Fluids on the Surface | | | | | | | | | | |
|------------------------------|-------------------------------------|----------------|---------------|--|------------------------|-----------------------------------|--|-------------------------|---|---|
| | Length (ft.) | Width (ft.) | Depth (in) | # of Boundaries *edges of pool where depth is 0. don't count shared boundaries | Oil-Water Ratio (%) | Pooled Area (ft ²) | Estimated Average Depth (ft.) | Pooled Volume (bbl.) | Volume of Oil in Subsurface (bbl.) | Volume of Water in Subsurface (bbl.) |
| Rectangle A | 4.0 | 4.0 | 2.0 | 4.0 | 0.01 | 16.0 | 0.0 | 0.1 | 0.00 | 0.12 |
| Rectangle B | 4.0 | 4.0 | 2.0 | 4.0 | 0.01 | 16.0 | 0.0 | 0.1 | 0.00 | 0.12 |
| Rectangle C | 4.0 | 4.0 | 2.00 | 4.00 | 0.01 | 16.000 | 0.042 | 0.119 | 0.00 | 0.12 |
| Rectangle D | | | | | | 0.000 | #DIV/0! | #DIV/0! | #DIV/0! | #DIV/0! |
| Rectangle E | | | | | | 0.000 | #DIV/0! | #DIV/0! | #DIV/0! | #DIV/0! |
| | Total Volume (bbls): 0.36 0.01 0.35 | | | | | | | | | |

| | | | | Sul | osurface Fluids | 6 | | | | |
|-------------|-------------------------------------|----------------|----------------|--|------------------------|----------------------------|------------------|--|---|---|
| | Length (ft.) | Width (ft.) | Depth (in.) | Saturation (%) *10% in consolidated sediments after rain to 50% in sand with no precipitation | Oil-Water Ratio (%) | Area (ft ²) | Volume (bbl.) | Estimated Volume in Subsurface (bbl.) | Volume of Oil in Subsurface (bbl.) | Volume of Water in Subsurface (bbl.) |
| Rectangle A | 20.0 | 45.0 | 1.0 | 0.1 | 0.01 | 900.0 | 13.4 | 1.1 | 0.01 | 1.1 |
| Rectangle B | 63.0 | 31.0 | 1.0 | 0.1 | 0.01 | 1953.0 | 29.0 | 2.3 | 0.02 | 2.3 |
| Rectangle C | 24.0 | 15.0 | 2.0 | 0.1 | 0.01 | 360.0 | 10.7 | 0.9 | 0.01 | 0.8 |
| Rectangle D | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| Rectangle E | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| Rectangle F | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| Rectangle G | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| Rectangle H | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| Rectangle I | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| Rectangle J | | | | | | 0.0 | 0.0 | 0.0 | 0.00 | 0.0 |
| - | Total Volume (bbls): 4.24 0.04 4.20 | | | | | | | | | |

TOTAL RELEASE VOLUME (bbls): 4.6

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

| Operator: | OGRID: |
|------------------------------|---|
| Maverick Permian LLC | 331199 |
| 1111 Bagby Street Suite 1600 | Action Number: |
| Houston, TX 77002 | 156196 |
| | Action Type: |
| | [C-141] Release Corrective Action (C-141) |
| | |

CONDITIONS

| Created | | Condition Date |
|---------|--------|-------------------|
| jharim | n None | 11/3/2022 |

Page 4 of 4

Action 156196