

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	nAPP2235054891
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party Flat Creek Resources, LLC	OGRID 374034
Contact Name John Wierzowiecki	Contact Telephone
Contact email john.wierzowiecki@flatcreekresources.com	Incident # (assigned by OCD)
Contact mailing address 777 Main St. Suite 3600 Fort Worth, TX 76102	

### Location of Release Source

Latitude 32.002387 Longitude -103.807701  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Phantom Bank 31 Federal Com CTB	Site Type: Tank Battery
Date Release Discovered 12/15/2022	API# (if applicable): NA

Unit Letter	Section	Township	Range	County
E	32	26S	31E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: DK Farms, Inc.)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls): 344.4	Volume Recovered (bbls) 240
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)


Cause of Release: Failure of packing material of the produced water disposal pump.

Incident ID	nAPP2235054891
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Spill is over 25 BBLS
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Becky Haskell with NTGE gave notification on 12/15/22 at 4:46 via email to <a href="mailto:ocd.enviro@state.nm.us">ocd.enviro@state.nm.us</a> , Rosa Romero and Mike Bratcher.	

## Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:          	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>John Wierzowiecki</u>	Title: <u>Operations Manager</u>
Signature: <u></u>	Date: <u>12/19/2022</u>
email: <u>john.wierzowiecki@flatcreekresources.com</u>	Telephone: <u>817-550-3565</u>
<b><u>OCD Only</u></b>	
Received by: <u>Jocelyn Harimon</u>	Date: <u>12/20/2022</u>

## \*\*\*\*\* LIQUID SPILLS - VOLUME CALCULATIONS \*\*\*\*\*

Location of spill: Phantom Bank 31 Federal Com CTB

Date of Spill: 15-Dec-2022

If the leak/spill is associated with production equipment, i.e. - wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here: ☒

## Input Data:

If spill volumes from measurement, i.e. metering, tank volumes, etc. are known enter the volumes here:

OIL:

0.0 BBL

WATER:

0.0 BBL

If "known" spill volumes are given, input data for the following "Area Calculations" is optional. The above will override the calculated volumes.

## Total Area Calculations

## Standing Liquid Calculations

Wet Soil Calculations						Standing Liquid Calculations					
Total Surface Area	width	length		wet soil depth	oil (%)	Standing Liquid Area	width	length	liquid depth	oil (%)	
Rectangle Area #1	134 ft	250 ft	X	1.50 in	0%	Rectangle Area #1	0 ft X	0 ft X	0 in	0%	
Rectangle Area #2	0 ft X	0 ft X		0 in	0%	Rectangle Area #2	0 ft X	0 ft X	0 in	0%	
Rectangle Area #3	0 ft X	0 ft X		0 in	0%	Rectangle Area #3	0 ft X	0 ft X	0 in	0%	
Rectangle Area #4	0 ft X	0 ft X		0 in	0%	Rectangle Area #4	0 ft X	0 ft X	0 in	0%	
Rectangle Area #5	0 ft X	0 ft X		0 in	0%	Rectangle Area #5	0 ft X	0 ft X	0 in	0%	
Rectangle Area #6	0 ft X	0 ft X		0 in	0%	Rectangle Area #6	0 ft X	0 ft X	0 in	0%	
Rectangle Area #7	0 ft X	0 ft X		0 in	0%	Rectangle Area #7	0 ft X	0 ft X	0 in	0%	
Rectangle Area #8	0 ft X	0 ft X		0 in	0%	Rectangle Area #8	0 ft X	0 ft X	0 in	0%	

okay

## production system leak - DAILY PRODUCTION DATA REQUIRED

Average Daily Production: Oil 0 BBL Water 0 BBL 0 Gas (MCFD)

Total Hydrocarbon Content in gas: 0% (percentage)

Did leak occur before the separator?: ☒ YES ☒ N/A (place an "X")

H2S Content in Produced Gas: 0 PPM

H2S Content in Tank Vapors: 0 PPM

Amount of Free Liquid Recovered: 0 BBL okay

Percentage of Oil in Free Liquid Recovered: 0% (percentage)

Liquid holding factor \*: 0.14 gal per gal

Use the following when the spill wets the grains of the soil.

Use the following when the liquid completely fills the pore space of the soil:

\* Sand = 0.08 gallon (gal.) liquid per gal. volume of soil.

Occurs when the spill soaked soil is contained by barriers, natural (or not).

\* Gravelly (caliche) loam = 0.14 gal. liquid per gal. volume of soil.

\* Clay loam = 0.20 gal. liquid per gal. volume of soil.

\* Sandy clay loam soil = 0.14 gal liquid per gal. volume of soil.

\* Gravelly (caliche) loam = 0.25 gal. liquid per gal. volume of soil.

\* Clay loam = 0.16 gal. liquid per gal. volume of soil.

\* Sandy loam = 0.5 gal. liquid per gal. volume of soil.

Total Solid/Liquid Volume: 33,500 sq. ft. 4,188 cu. ft. cu. ft.

Total Free Liquid Volume: sq. ft. cu. ft. cu. ft.

## Estimated Volumes Spilled

	H2O	OIL
Liquid in Soil:	104.4 BBL	0 BBL
Free Liquid:	0.0 BBL	0.0 BBL
Totals:	104.4 BBL	0 BBL

## Estimated Production Volumes Lost

	H2O	OIL
Estimated Production Spilled:	0.0 BBL	0.0 BBL

## Estimated Surface Damage

Surface Area: 33,500 sq. ft.

Surface Area: .7691 acre

Total Liquid Spill Liquid: 104.4 BBL 0.0 BBL

## Recovered Volumes

Estimated oil recovered: BBL check - okay  
Estimated water recovered: BBL check - okay

## Estimated Weights, and Volumes

Saturated Soil = 469,000 lbs 4,188 cu. ft. 155 cu. yds.  
Total Liquid = 104 BBL 4,385 gallon 36,484 lbs

## Air Emission from flowline leaks:

Volume of oil spill: - BBL  
Separator gas calculated: - MCF  
Separator gas released: - MCF  
Gas released from oil: - lb  
H2S released: - lb  
Total HC gas released: - lb  
Total HC gas released: - MCF

## Air Emission of Reporting Requirements:

New Mexico  
HC gas release reportable? NO  
H2S release reportable? NO  
Texas  
NO  
NO

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 168765

CONDITIONS

Operator: Flat Creek Resources, LLC 777 Main St. Fort Worth, TX 76102	OGRID: 374034
	Action Number: 168765
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	12/20/2022