Incident ID nAPP2222844442
District RP
Facility ID
Application ID

### Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items	s must be included in the closure report.					
□ A scaled site and sampling diagram as described in 19.15.29.11 NMAC						
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)						
☐ Laboratory analyses of final sampling (Note: appropriate ODC Di	strict office must be notified 2 days prior to final sampling)					
□ Description of remediation activities						
I hereby certify that the information given above is true and complete to and regulations all operators are required to report and/or file certain remay endanger public health or the environment. The acceptance of a C should their operations have failed to adequately investigate and remed human health or the environment. In addition, OCD acceptance of a C-compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the condit accordance with 19.15.29.13 NMAC including notification to the OCD	lease notifications and perform corrective actions for releases which -141 report by the OCD does not relieve the operator of liability interest contamination that pose a threat to groundwater, surface water, 141 report does not relieve the operator of responsibility for its. The responsible party acknowledges they must substantially items that existed prior to the release or their final land use in					
Printed Name: Melodie Sanjari	Title: Environmental Professional					
Signature: <u>Melodie Sanjari</u>	Date: 2/17/2020					
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>					
OCD Only						
Received by:Jocelyn Harimon	Date:10/31/2022					
	iability should their operations have failed to adequately investigate and er, human health, or the environment nor does not relieve the responsible egulations.					
Closure Approved by: Robert Hamlet	Date: <u>1/4/2023</u>					
Printed Name: Robert Hamlet	Title: Environmental Specialist - Advanced					



# CLOSURE REQUEST MARATHON OIL COMPANY

Created for submission to New Mexico Oil Conservation Division on 10/12/2022

ASHLEY GIOVENGO
Project Environmental Scientist

**ENERGIZING AMERICA** 

October 12, 2022

#### **Environmental Incident Group**

State of New Mexico
Energy, Minerals, and Natural Resources
New Mexico Oil Conservation Division
811 South First Street
Artesia, New Mexico 88210

#### RE: CLOSURE REQUEST

**COMPANY** Marathon Oil Company

**LOCATION** Parkway 19 18 Federal Com #001H

**API** 30-015-42545

PLSS Unit M Sec 19 T19S R30E

**GPS** 32.6391029, -104.0187531

INCIDENT ID nAPP2222844442

#### BACKGROUND

Wescom, Inc., hereafter referred to as Wescom, has prepared this Closure Request on behalf of Marathon Oil Company, hereafter referred to as Marathon, regarding the release at the Parkway 19 18 Federal Com #001H (Site) located in Unit M, Section 19 Township 19 South and Range 30 East in Eddy County, New Mexico. The GPS coordinates are as follows: North 32.019665 and West -104.0187531. Surface owner of the Site is Bureau of Land Management (BLM).

On July 8, 2022, a pinhole on the heater treater water leg resulted in the release of approximately 36.2 barrels (bbls) of produced water to lined secondary containment and 1.1 bbls of overspray onto the caliche pad. A small off-pad area was affected by the overspray event. Marathon immediately isolated the source of the leak and 35.1 bbls of produced water were recovered from the lined secondary containment. The spill area is located on the South and West sides of the heater treater containment. The off-pad area is located on the Northwest side of the heater treater containment as shown in Figure 1.

On September 01, 2022, Wescom personnel arrived onsite to begin delineation of the impacted areas.
 Wescom personnel returned onsite on September 22, 2022, to conduct a liner inspection, excavate the impacted areas and to collect confirmation samples. All confirmation samples were below applicable Recommended Remediation Action Levels (RRALs) for the Site.

#### SURFACE & GROUND WATER

The New Mexico Office of the State Engineer (OSE) records indicates the nearest depth to groundwater measurement is greater than 90 feet below ground surface (bgs) and is 0.81 miles South of the Site. No playas or lakes are located within a one-mile radius of this Site (Attachment C).

#### KARST POTENTIAL

According to data from the Bureau of Land Management, this Site is located within high karst potential as shown in Attachment D. There are no indicators of karst around the Site surface.

#### TARGET REMEDIAL LEVELS

The target cleanup levels are determined using the NMOCD Closure Criteria (19.15.29.12.B(4) and Table 1 NMAC, inserted below) including karst guidelines from the Bureau of Land Management. This Site is in the high karst potential zone and therefore, the applicable RRALs are 10 parts per million (ppm) Benzene, 50 ppm combined benzene, toluene, ethyl benzene, and xylene (BTEX) and 100 ppm Total Petroleum Hydrocarbons (TPH). A chloride concentration at or below 600 mg/kg (ppm) in the soil is also required.

Closure Crite	Closure Criteria (19.15.29.12.B(4) and Table 1 NMAC)							
Parkway 19 18 F	Parkway 19 18 Federal Com #001H — 32.6391029, -104.0187531							
Depth to Groundwater		Cle	osure Criteria	(unites in mg	/kg)			
		Chloride * numberical						
		limit or background,						
		whichever is greater	TPH	GRO+DRO	BTEX	Benzene		
Based on high karst potential	High	600	100		50	10		
No water data within 0.5 mile radius	0.81 Mi	600	100		50	10		
less than 50 ft bgs		600	100		50	10		
51 ft to 100 ft bgs		10000	2500	1000	50	10		
greater than 100 ft bgs		20000	2500	1000	50	10		
Surface Water	Yes or No		If ye	s, then				
< 300 feet from continuously flowing watercourse or other	No							
significant watercourse?								
< 200 feet from lakebed, sinkhole or playa lake	No							
Water Well or Water Source								
< 500 feet from spring or a private, domestic fresh water								
well used by less than 5 households for domestic or stock	No							
watering purposes?								
< 1000 feet from fresh water well or spring?	No							
Human and Other Areas								
< 300 feet from an occupied permanent residence, school,	No							
hospital, institution or church?	INO							
Within incorporated municipal boundaries or within a	No							
defined municipal fresh water well field?	INO							
< 100 feet from wetland?	No							
Within area overlying a subsurface mine?	No							
Within an unstable area?	No							
Within a 100-year floodplan?	No							

Table: Closure Criteria Statistics

#### SITE ASSESSMENT AND DELINEATION

On September 01, 2022, Marathon contracted Wescom to complete horizontal and vertical delineation of the impacted areas. A total of nine samples were jarred and sent to Hall Environmental, for laboratory analysis and all samples were below the applicable RRALs for the Site. A background sample, BG01, was collected 50 feet to the West of the caliche pad, as shown in Figure 1. Delineation sample locations are presented in Figure 1; laboratory analysis results are presented in Table 1 and laboratory analytical reports are included in Attachment E.

Wescom personnel conducted a liner inspection on September 22, 2022, and seven potential release points were identified along the containment walls. During this inspection, there were 7 areas within the containment where the liner had pulled away from the top of the containment wall but did not impact the containment's ability to contain the release in question. Photo documentation of potential liner compromises and completed repairs are shown in Attachment B.

#### REMEDIATION ACTIVITES

Beginning on September 22, 2022, Wescom personnel arrived onsite to oversee the removal of impacted soil and to conduct confirmation sampling. A backhoe was used to remove contaminated soil from the spill area to a depth of three feet bgs. Impacted material from the spill area was hauled to an approved disposal facility.

Wescom personnel collected 12 composite confirmation samples over the three-day sampling and excavation period. All the confirmation samples were below the applicable RRALs for the Site, as shown in Table 2. All soil samples were properly packaged, preserved, and transported to Hall Environmental by chain of custody, and analyzed for Total Petroleum Hydrocarbons, or TPH, —Method 8015D, BTEX—Method 8021B, and Chlorides—Method 300.0. Confirmation sample locations are presented in Figure 2 and laboratory analytical reports are included in Attachment E.

The required 48-hour confirmation sampling and liner inspection notifications were sent on September 19, 2022, and September 22, 2022, to <a href="https://occupies.org/length/98/2022">OCD.Enviro@state.nm.us</a> and are included in Attachments F and G.

#### REQUEST FOR CLOSURE

On behalf of Marathon, Wescom hereby requests closure for the release associated with incident number nAPP2222844442 based on the logic below.

- The spill area has been horizontally and vertically delineated.
- All confirmation areas and samples are below applicable RRALs for the Site.
- The liner/containment had the ability to containment the release in question and there was no evidence of it not doing so.
- Impacted material was removed and properly disposed of at an approved facility.

If you have any questions or comments, please do not hesitate to call Ms. Ashley Giovengo at (505) 382-1211.

Sincerely,

Wescom, Inc.

#### **Ashley Giovengo**

Project Environmental Scientist

cc: Melodie Sanjari, Marathon Oil Company

Environmental Incident Group, NMOCD

# REFERENCE MATERIALS

#### FIGURES

**FIGURE 1.** Delineation Sampling **FIGURE 2.** Confirmation Sampling

#### TABLES

**TABLE 1.** Laboratory Analysis Results: Delineation Samples **TABLE 2.** Laboratory Analysis Results: Confirmation Samples

#### ATTACHMENTS

**ATTACHMENT A.** C-141

**ATTACHMENT B.** Site Photos

**ATTACHMENT C.** Closure Criteria Supporting Documents


**ATTACHMENT D.** Karst Map

**ATTACHMENT E.** Hall Environmental Laboratory Analysis Reports

ATTACHMENT F. 48-hour Confirmation Notification Emails

**ATTACHMENT G.** 48-hour Liner Inspection Notification Emails

# **FIGURES**



#### FIGURE 1. DELINEATION SAMPLING


Parkway 19 18 Federal Com #001H Incident ID: nAPP2222844442

API: 30-015-42545

GPS Coordinates: 32.6391029, -104.0187531


Eddy County, New Mexico

Marathon Oil Company Released to Imaging: 1/4/2023 10:56:18 AM









#### FIGURE 2. CONFIRMATION SAMPLING

Parkway 19 18 Federal Com #001H Incident ID: nAPP2222844442

API: 30-015-42545

GPS Coordinates: 32.6391029, -104.0187531

Eddy County, New Mexico

Marathon Oil Company Released to Imaging: 1/4/2023 10:56:18 AM

#### **LEGEND**

Confirmation Sample Spill Area Locations





### TABLE

Parkway 19 18 Federal Com #001H   nAPP2222844442							
	Marathon Oil Company   10.06.2022						
Та	ble 1. Lab	oratory An	alysis Re	sults: Deline	eation Samp	es	
Sar	nple Descri <sub>l</sub>	otion	Pet	troleum Hydro	carbons	Inorganic	
			V	olatile	Extractable		
			Benzene	Total BTEX	TPH	Chloride	
Sample ID	Depth (ft.)	Date	(mk/kg)	(mk/kg)	(mk/kg)	(mk/kg)	
Closure Cri	teria		10	50	100	600	
BG01	0	9/2/2022	ND	ND	ND	ND	
BG01	1	9/2/2022	ND	ND	ND	ND	
SS01B	0	9/2/2022	ND	ND	ND	ND	
SS02C	0	9/2/2022	ND	ND	ND	ND	
SS03D	0	9/2/2022	ND	ND	ND	ND	
SS04C	0	9/2/2022	ND	ND	ND	240	
SS05	0	9/2/2022	ND	ND	ND	ND	
SS06	0	9/2/2022	ND	ND	ND	ND	
SS07	0	9/2/2022	ND	ND	ND	96	
SS08	2	9/2/2022	ND	ND	ND	96	
SS09	2	9/2/2022	ND	ND	ND	220	
ABBREVIAT	IONS						
BTEX — Benzei	ne, Toluene, Eth	ıylene, Xylene		GRO — Gasoline Ra	ange Organics		
DRO — Diesel	Range Organics			ND — Non-detect			
ft. — Feet				mg/kg — Milligram	s per Kilogram		
TPH — Total Petroleum Hydrocarbons							
Notes							
Bold Red - Res	Bold Red - Results are above closure criteria						
Gray Highlight	- Background S	amples					

Parkway 19 18 Federal Com #001H   nAPP2222844442							
Marathon Oil Company   10.06.2022							
Tabl	e 2. Labor	atory Anal	ysis Resu	ılts: Confirm	ation Sampl	es	
Sam	ple Descript	tion	Pet	troleum Hydro	carbons	Inorganic	
			V	olatile	Extractable		
			Benzene	Total BTEX	TPH	Chloride	
Sample ID	Depth (ft.)	Date	(mk/kg)	(mk/kg)	(mk/kg)	(mk/kg)	
<b>Closure Criter</b>	ia		10	50	100	600	
CONF01	3	9/23/2022	ND	ND	ND	150	
CONF02	3	9/23/2022	ND	ND	ND	170	
CONF03	3	9/23/2022	ND	ND	ND	ND	
CONF04	3	9/23/2022	ND	ND	ND	62	
CONF05	1.5	9/23/2022	ND	ND	ND	200	
CONF06	2	9/26/2022	ND	ND	ND	110	
CONF07	2	9/26/2022	ND	ND	ND	230	
CONF08	3	9/26/2022	ND	ND	ND	140	
CONF09	1.5	9/26/2022	ND	ND	21	430	
CONF10	1.5	9/26/2022	ND	ND	21	380	
CONF11 Wall	1	9/26/2022	ND	ND	ND	160	
CONF12 Wall	1	9/26/2022	ND	ND	979	110	
ABBREVIATIO	NS						
BTEX — Benzene,	Toluene, Ethylei	ne, Xylene		GRO — Gasoline Ra	inge Organics		
DRO — Diesel Ran	ge Organics			ND — Non-detect			
ft. — Feet mg/kg — Milligrams per Kilogram							
TPH — Total Petroleum Hydrocarbons							

Notes

Bold Red - Results are above closure criteria

Gray Highlight - Background Samples

# ATTACHMENT A

C-141

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	'nAPP2222844442
District RP	
Facility ID	
Application ID	

### **Release Notification**

#### **Responsible Party**

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

#### **Location of Release Source**

Latitude	32.6391029	Longitude -104.0187531
----------	------------	------------------------

(NAD 83 in decimal degrees to 5 decimal places)

Site Name PARKWAY 19 18 FEDERAL COM #001H			Site Type Oil & Gas Facili	ty			
Date Release Discovered: 8/16/2022			API# (if applicable) 30-015-425	545			
	T	I	T _			1	
Unit Letter	Section	Township	Range	County			
M	19	19S	30E	Eddy			
Surface Owner: State Federal Tribal Private (Name:					)		

#### **Nature and Volume of Release**

Material	(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 36.2	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	⊠ Yes □ No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
	g off the heater treater resulted in the release of approx. red pad. The facility was shut in for repairs and a truck	•

Received by OCD: 10/31/2022 9:34:14 AM Form C-141 State of New Mexico Page 2 Oil Conservation Division Page 15 of 73

Incident ID nAPP2222844442
District RP
Facility ID
Application ID

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes, NOR submitted 8/16/2022  Initial Response  The responsible party must undertake the following actions immediately unless they could create a safety bacard that would result in injury  In the source of the release has been stopped.  The impacted area has been scoured to protect human health and the environment.  Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.  All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remediate of the production of the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD roles and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. In addition, OCD acceptance of a C-141 report by the OCD does not releave the operator of liability should their operations have failed to adequately investigate and remediate containmation that pase a threat to groundware, surface water, human health of the environment. In addition, OCD acceptance of a C-141 report does not releave the operator of responsibility for compliance with any other federal, state, or local tawa and or regulations.  Printed Name: Melodie Sanijari Title: Environmental Professional  Date: 8/17/2022  cmail: msanjari@marathonoil.com Title Professional	Was this a major release as defined by	If YES, for what reason(s) does the respon Volume	sible party consider this a major release?
Initial Response  Initial Response  The responsible party must undertake the following actions inmediately unless they could crease a sofety hazard that would result in injury  In the impacted area has been stopped.  The source of the release has been stopped.  The impacted area has been secured to protect human health and the environment.  Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.  All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remediate efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may enduager public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have falled to adequately investigate and remediate containmation that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report dy the OCD Does not relieve the operator of liability should their operations have falled to adequately investigate and remediate containmation that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report dy the OCD Does not relieve the operator of liability should their operations have falled to adequately investigate	19.15.29.7(A) NMAC?		
Initial Response  The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury  The source of the release has been stopped.  The impacted area has been secured to protect human health and the environment.  Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.  All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A),(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of institute water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari Title: Environmental Professional  Telephone: 575-988-8753  OCD Only	⊠ Yes □ No		
Initial Response  The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury  The source of the release has been stopped.  The impacted area has been secured to protect human health and the environment.  Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.  All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A),(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of institute water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari Title: Environmental Professional  Telephone: 575-988-8753  OCD Only			
Initial Response  The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury  The source of the release has been stopped.  The impacted area has been secured to protect human health and the environment.  Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.  All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A),(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of institute water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari Title: Environmental Professional  Telephone: 575-988-8753  OCD Only	If VEC in diete a	estina sincer to the OCD? December ? To sub	2 Wilson and have that are are (all one a small sets)?
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury  The source of the release has been stopped. The impacted area has been secured to protect human health and the environment. Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator for the environment. The acceptance of a C-141 report by the OCD does not relieve the operator when the operators are required to reduce the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Date: 8/17/2022  email: _msanjari@marathonoil.com Telephone: 575-988-8753			om? when and by what means (phone, email, etc)?
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury  The source of the release has been stopped. The impacted area has been secured to protect human health and the environment. Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator for the environment. The acceptance of a C-141 report by the OCD does not relieve the operator when the operators are required to reduce the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Date: 8/17/2022  email: _msanjari@marathonoil.com Telephone: 575-988-8753			
☑ The source of the release has been stopped. ☑ The impacted area has been secured to protect human health and the environment. ☑ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. ☑ All free liquids and recoverable materials have been removed and managed appropriately. If all the actions described above have not been undertaken, explain why: Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Printed Name: Melodie Sanjari Title: Environmental Professional Date: 8/17/2022 email: _msanjari@marathonoil.com Telephone: _575-988-8753 OCD Only		Initial Re	esponse
☑ The impacted area has been secured to protect human health and the environment. ☑ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. ☑ All free liquids and recoverable materials have been removed and managed appropriately. If all the actions described above have not been undertaken, explain why: Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Printed Name: Melodie Sanjari Title: Environmental Professional Signature: Melodie Sanjari Title: Environmental Professional Date: 8/17/2022 email: _msanjari@marathonoil.com Telephone: _575-988-8753	The responsible p	party must undertake the following actions immediately	unless they could create a safety hazard that would result in injury
☑ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.         ☑ All free liquids and recoverable materials have been removed and managed appropriately.         If all the actions described above have not been undertaken, explain why:    Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of releases which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Printed Name: Melodic Sanjari Title: Environmental Professional Signature: Melodic Sanjari Title: Environmental Professional Signature: Melodic Sanjari Ticlephone: 575-988-8753 OCD Only	☐ The source of the rele	ease has been stopped.	
All free liquids and recoverable materials have been removed and managed appropriately.  If all the actions described above have not been undertaken, explain why:  Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Telephone: 575-988-8753  OCD Only	☐ The impacted area ha	s been secured to protect human health and	the environment.
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari  Date: 8/17/2022  email:msanjari@marathonoil.com  Telephone:575-988-8753	Released materials ha	we been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari Date: 8/17/2022  email: msanjari@marathonoil.com Telephone: 575-988-8753	All free liquids and re	ecoverable materials have been removed and	I managed appropriately.
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Telephone: 575-988-8753  OCD Only	If all the actions described	d above have <u>not</u> been undertaken, explain v	vhy:
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Date: 8/17/2022  email: msanjari@marathonoil.com  Telephone: 575-988-8753			
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Date: 8/17/2022  email: msanjari@marathonoil.com  Telephone: 575-988-8753			
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Telephone: 575-988-8753  OCD Only			
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Telephone: 575-988-8753  OCD Only			
within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari@marathonoil.com  Telephone: 575-988-8753  OCD Only	Per 19.15.29.8 B. (4) NM	AC the responsible party may commence re	emediation immediately after discovery of a release. If remediation
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari Title: Environmental Professional  Signature: Melodie Sanjari  Date: 8/17/2022  email: msanjari@marathonoil.com  Telephone: 575-988-8753			
public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Melodie Sanjari  Title: Environmental Professional  Signature: Melodie Sanjari  Date: 8/17/2022  email: msanjari@marathonoil.com  Telephone: 575-988-8753			
addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name:Melodie Sanjari Title:Environmental Professional  Signature:Melodie Sanjari Date: 8/17/2022  email:msanjari@marathonoil.com Telephone:575-988-8753  OCD Only	public health or the environn	ment. The acceptance of a C-141 report by the O	CD does not relieve the operator of liability should their operations have
Printed Name: Melodie Sanjari  Signature: Melodie Sanjari  Date: 8/17/2022  email: msanjari@marathonoil.com  Title: Environmental Professional  Date: 8/17/2022			
Signature:Melodie Savjavi Date: 8/17/2022  email:msanjari@marathonoil.com Telephone:575-988-8753  OCD Only	and/or regulations.		
email:msanjari@marathonoil.com Telephone:575-988-8753  OCD Only	Printed Name:Mel	odie Sanjari	Title:Environmental Professional
OCD Only	Signature: Melod	<u>lie Sanjari</u>	Date: 8/17/2022
	email: <u>msanjari@marat</u>	thonoil.com	Telephone: 575-988-8753
Received by:  Date:	OCD Only		
Need, ed 6,1	Received by:		Date:

	Page 16 of	73
Incident ID	nAPP2222844442	
District RP		
Facility ID		
Application ID		

### Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

90 (ft bgs)
☐ Yes ⊠ No
ical extents of soil
s.
i

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 10/31/2022 9:34:14 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

Page 17 of 73

Incident ID	nAPP2222844442
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name: Melodie Sanjari	Title: Environmental Professional	
Signature: <u>Melodie Sanjari</u>	Date:	
email:msanjari@marathonoil.com	Telephone: <u>575-988-8753</u>	
OCD Only		
Received by:	Date:10/31/2022	

Received by OCD: 10/31/2022 9:34:14 AM Form C-141 State of New Mexico Oil Conservation Division Page 6

Page 18 of 73 Incident ID nAPP2222844442 District RP Facility ID Application ID

### Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.			
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)			
☐ Description of remediation activities			
I hereby certify that the information given above is true and complete to and regulations all operators are required to report and/or file certain re may endanger public health or the environment. The acceptance of a C should their operations have failed to adequately investigate and remed human health or the environment. In addition, OCD acceptance of a C compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the condit accordance with 19.15.29.13 NMAC including notification to the OCD	clease notifications and perform corrective actions for releases which C-141 report by the OCD does not relieve the operator of liability liate contamination that pose a threat to groundwater, surface water, -141 report does not relieve the operator of responsibility for ms. The responsible party acknowledges they must substantially tions that existed prior to the release or their final land use in		
Printed Name: Melodie Sanjari	Title: Environmental Professional		
Signature: <u>Melodíe Sanjarí</u>	Date: 2/17/2020		
email:msanjari@marathonoil.com	Telephone:575-988-8753		
OCD Only			
Received by:	Date:10/31/2022		
11 1	iability should their operations have failed to adequately investigate and er, human health, or the environment nor does not relieve the responsible egulations.		
Closure Approved by:	Date:		
Printed Name:	Title:		

# ATTACHMENT B

Site Photos



Southeast Side of Spill Area



Northwest Side of Spill Area



Spill Area



Spill Area



Spill Area



Spill Area



Liner Inspection



Liner Inspection



Liner Inspection



Liner Inspection



Liner Inspection




Liner Inspection



Excavation Area - Off Pad



Excavation Area - South of Heater Treater



Excavation Area - West of Heater Treater



Removal of Production Pipe



Excavation Area - South of Heater Treater



Excavation Area



Excavation Area - CONF09 Rescrape



Removal of Contaminated Soil



Containment Wall Repaired



Containment Wall Repaired



Containment Wall Repaired



Containment Wall Repaired



Containment Wall Repaired

### ATTACHMENT C

Closure Criteria Supporting Documents

### New Mexico Office of the State Engineer



?

### **Wells with Well Log Information**

(A CLW#### in the (R=POD has POD suffix indicates the been replaced, POD has been replaced O=orphaned, C=the file is (quarters are 1=NW 2=NE 3=SW 4=SE) & no longer serves a (NAD83 UTM in meters) (quarters are smallest to largest) (in feet) water right closed) POD License qqq Log File Depth Depth **POD Number** Subbasin County Source 6416 4 Sec Tws Rng Finish Date Date Water Driller Number Code X **Distance Start Date** Well CP 00522 CP ED Shallow 3 30 19S 30E 592347 3610451\* 1290 08/28/1973 09/01/1973 09/08/1975 120 90 VAN NOY, W.L. 208 CP 00703 POD1 CP ED Shallow 4 1 36 19S 29E 591050 3609382 2523 12/02/1986 12/02/1986 12/10/1986 225 115 GLENN, CLARK 421 A."CORKY" (LD) CP 00742 CP 3 3 31 19S 30E 3608940 08/04/1989 08/10/1989 115 GLENN, CLARK ED Shallow 592208 2769 08/04/1989 223 421 A."CORKY" (LD) CP 00739 POD1 CP ED Shallow 3 4 4 35 19S 29E 590068 3608622 3657 12/09/1988 12/10/1988 12/20/1988 200 110 COLLIS, ROBERT E. (LD) 1184 CP 00741 CP Shallow 1 3 2 34 19S 29E 4557 04/17/1989 04/20/1989 04/24/1989 60 DUBOSE, BILL M. JR. 1107

Record Count: 5

**UTMNAD83 Radius Search (in meters):** 

Easting (X): 592037.26 Northing (Y): 3611704.12 Radius: 5000

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

9/29/22 11:32 AM WELLS WITH WELL LOG INFORMATION



# New Mexico Office of the State Engineer

### **Point of Diversion Summary**

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

**Well Tag POD Number** 

Q64 Q16 Q4 Sec Tws Rng

X

CP 00522 3 30 19S 30E

592347 3610451\*



Shallow

**Driller License: 208** Driller Company: VAN NOY, W.L.

**Driller Name:** VAN NOY, W.L.

**Drill Start Date:** 08/28/1973

09/08/1975

Log File Date:

**Drill Finish Date:** Plug Date: 09/01/1973

**PCW Rcv Date:** Source:

**Pump Type:** Pipe Discharge Size: **Estimated Yield:** 


**Casing Size: Depth Well:** 6.63 120 feet **Depth Water:** 90 feet

> Water Bearing Stratifications: **Top Bottom Description**

> > 120 Sandstone/Gravel/Conglomerate 90

Casing Perforations: Top Bottom

> 90 115



- Freshwater Pond 5,002 Ft



September 29, 2022

#### Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake


Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Parkway 19 18 Federal Com #001H Page 37 of 73

- Riverine 3,837 Ft



September 29, 2022

#### Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake

Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

U.S. Fish and Wildlife Service National Wetlands Inventory

Parkway 19 18 Federal Com #001 Page 38 of 73 - Wetland 4,208 Ft



September 29, 2022

#### Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland


Freshwater Pond

Lake

Riverine

Other

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.




# National Flood Hazard Layer FIRMette





SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT




This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards


The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 9/29/2022 at 1:42 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

an authoritative property location.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.



### Active Mines Near Parkway 19 18 Federal Com #001H




9/29/2022, 1:57:51 PM

Registered Mines

Aggregate, Stone etc.


Potash



Sources: Esri, USGS, NOAA, Sources: Esri, Garmin, USGS, NPS

# ATTACHMENT D

Karst Map



# ATTACHMENT E

Hall Environmental Laboratory Analysis Reports

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS01B-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 12:58:00 PM

 Lab ID:
 2209226-001
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE C	RGANICS				Analyst: <b>DGH</b>
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/10/2022 12:10:41 AM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/10/2022 12:10:41 AM
Surr: DNOP	98.0	21-129	%Rec	1	9/10/2022 12:10:41 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	9/10/2022 1:38:20 AM
Surr: BFB	100	37.7-212	%Rec	1	9/10/2022 1:38:20 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 1:38:20 AM
Toluene	ND	0.050	mg/Kg	1	9/10/2022 1:38:20 AM
Ethylbenzene	ND	0.050	mg/Kg	1	9/10/2022 1:38:20 AM
Xylenes, Total	ND	0.10	mg/Kg	1	9/10/2022 1:38:20 AM
Surr: 4-Bromofluorobenzene	94.4	70-130	%Rec	1	9/10/2022 1:38:20 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	ND	59	mg/Kg	20	9/13/2022 10:04:01 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 1 of 0

### **Analytical Report**

Lab Order 2209226

### Hall Environmental Analysis Laboratory, Inc.

Date Reported:

CLIENT: Marathon Oil Company Client Sample ID: SS02C-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 2:16:00 PM

 Lab ID:
 2209226-002
 Matrix:
 SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	ial Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OR	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/10/2022 12:21:54 AM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/10/2022 12:21:54 AM
Surr: DNOP	91.8	21-129	%Rec	1	9/10/2022 12:21:54 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 3:12:10 AM
Surr: BFB	99.3	37.7-212	%Rec	1	9/10/2022 3:12:10 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 3:12:10 AM
Toluene	ND	0.049	mg/Kg	1	9/10/2022 3:12:10 AM
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 3:12:10 AM
Xylenes, Total	ND	0.098	mg/Kg	1	9/10/2022 3:12:10 AM
Surr: 4-Bromofluorobenzene	93.8	70-130	%Rec	1	9/10/2022 3:12:10 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	ND	60	mg/Kg	20	9/13/2022 10:16:25 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 2 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

**CLIENT:** Marathon Oil Company

**Project:** Parkway 1918 Federal Com 001H 08162

**Lab ID:** 2209226-003

Client Sample ID: SS03D-0'

**Collection Date:** 9/2/2022 2:15:00 PM

**Received Date:** 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OR	GANICS				Analyst: <b>DGH</b>
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/10/2022 12:33:04 AM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/10/2022 12:33:04 AM
Surr: DNOP	96.5	21-129	%Rec	1	9/10/2022 12:33:04 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	9/10/2022 3:35:35 AM
Surr: BFB	102	37.7-212	%Rec	1	9/10/2022 3:35:35 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 3:35:35 AM
Toluene	ND	0.050	mg/Kg	1	9/10/2022 3:35:35 AM
Ethylbenzene	ND	0.050	mg/Kg	1	9/10/2022 3:35:35 AM
Xylenes, Total	ND	0.099	mg/Kg	1	9/10/2022 3:35:35 AM
Surr: 4-Bromofluorobenzene	96.3	70-130	%Rec	1	9/10/2022 3:35:35 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	ND	60	mg/Kg	20	9/13/2022 4:20:55 PM

Matrix: SOIL

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 3 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS04C-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 2:20:00 PM

 Lab ID:
 2209226-004
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed		
EPA METHOD 8015M/D: DIESEL RANGE ORG	EPA METHOD 8015M/D: DIESEL RANGE ORGANICS						
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/10/2022 12:44:13 AM		
Motor Oil Range Organics (MRO)	ND	49	mg/Kg	1	9/10/2022 12:44:13 AM		
Surr: DNOP	85.1	21-129	%Rec	1	9/10/2022 12:44:13 AM		
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB		
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 3:58:54 AM		
Surr: BFB	99.5	37.7-212	%Rec	1	9/10/2022 3:58:54 AM		
EPA METHOD 8021B: VOLATILES					Analyst: NSB		
Benzene	ND	0.024	mg/Kg	1	9/10/2022 3:58:54 AM		
Toluene	ND	0.049	mg/Kg	1	9/10/2022 3:58:54 AM		
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 3:58:54 AM		
Xylenes, Total	ND	0.097	mg/Kg	1	9/10/2022 3:58:54 AM		
Surr: 4-Bromofluorobenzene	93.4	70-130	%Rec	1	9/10/2022 3:58:54 AM		
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>		
Chloride	240	60	mg/Kg	20	9/13/2022 4:33:20 PM		

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 4 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS05-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 11:47:00 AM

 Lab ID:
 2209226-005
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed		
EPA METHOD 8015M/D: DIESEL RANGE ORG	EPA METHOD 8015M/D: DIESEL RANGE ORGANICS						
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/10/2022 12:55:14 AM		
Motor Oil Range Organics (MRO)	ND	49	mg/Kg	1	9/10/2022 12:55:14 AM		
Surr: DNOP	95.4	21-129	%Rec	1	9/10/2022 12:55:14 AM		
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB		
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 4:22:26 AM		
Surr: BFB	95.2	37.7-212	%Rec	1	9/10/2022 4:22:26 AM		
EPA METHOD 8021B: VOLATILES					Analyst: NSB		
Benzene	ND	0.025	mg/Kg	1	9/10/2022 4:22:26 AM		
Toluene	ND	0.049	mg/Kg	1	9/10/2022 4:22:26 AM		
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 4:22:26 AM		
Xylenes, Total	ND	0.098	mg/Kg	1	9/10/2022 4:22:26 AM		
Surr: 4-Bromofluorobenzene	90.6	70-130	%Rec	1	9/10/2022 4:22:26 AM		
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>		
Chloride	ND	60	mg/Kg	20	9/13/2022 4:45:44 PM		

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 5 of 0

### **Analytical Report**

Lab Order 2209226

#### Date Reported:

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS06-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 12:05:00 PM

 Lab ID:
 2209226-006
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/10/2022 1:06:27 AM
Motor Oil Range Organics (MRO)	ND	47	mg/Kg	1	9/10/2022 1:06:27 AM
Surr: DNOP	85.5	21-129	%Rec	1	9/10/2022 1:06:27 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	9/10/2022 4:46:00 AM
Surr: BFB	98.4	37.7-212	%Rec	1	9/10/2022 4:46:00 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 4:46:00 AM
Toluene	ND	0.050	mg/Kg	1	9/10/2022 4:46:00 AM
Ethylbenzene	ND	0.050	mg/Kg	1	9/10/2022 4:46:00 AM
Xylenes, Total	ND	0.099	mg/Kg	1	9/10/2022 4:46:00 AM
Surr: 4-Bromofluorobenzene	92.2	70-130	%Rec	1	9/10/2022 4:46:00 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	65	60	mg/Kg	20	9/13/2022 4:58:08 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 6 of 0

Date Reported:

#### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS07-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 12:10:00 PM

 Lab ID:
 2209226-007
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	ial Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OF	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/10/2022 1:17:39 AM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/10/2022 1:17:39 AM
Surr: DNOP	109	21-129	%Rec	1	9/10/2022 1:17:39 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 5:09:25 AM
Surr: BFB	98.4	37.7-212	%Rec	1	9/10/2022 5:09:25 AM
<b>EPA METHOD 8021B: VOLATILES</b>					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 5:09:25 AM
Toluene	ND	0.049	mg/Kg	1	9/10/2022 5:09:25 AM
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 5:09:25 AM
Xylenes, Total	ND	0.098	mg/Kg	1	9/10/2022 5:09:25 AM
Surr: 4-Bromofluorobenzene	92.7	70-130	%Rec	1	9/10/2022 5:09:25 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	96	60	mg/Kg	20	9/13/2022 5:10:34 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 7 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS08-2'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 9:15:00 AM

 Lab ID:
 2209226-008
 Matrix:
 SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE O	RGANICS				Analyst: <b>DGH</b>
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/10/2022 1:28:50 AM
Motor Oil Range Organics (MRO)	ND	49	mg/Kg	1	9/10/2022 1:28:50 AM
Surr: DNOP	97.9	21-129	%Rec	1	9/10/2022 1:28:50 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 5:32:52 AM
Surr: BFB	98.1	37.7-212	%Rec	1	9/10/2022 5:32:52 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 5:32:52 AM
Toluene	ND	0.049	mg/Kg	1	9/10/2022 5:32:52 AM
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 5:32:52 AM
Xylenes, Total	ND	0.099	mg/Kg	1	9/10/2022 5:32:52 AM
Surr: 4-Bromofluorobenzene	93.1	70-130	%Rec	1	9/10/2022 5:32:52 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	96	59	mg/Kg	20	9/13/2022 5:22:58 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 8 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: SS09-2'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 9:40:00 AM

 Lab ID:
 2209226-009
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OF	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	13	mg/Kg	1	9/10/2022 1:40:01 AM
Motor Oil Range Organics (MRO)	ND	44	mg/Kg	1	9/10/2022 1:40:01 AM
Surr: DNOP	93.9	21-129	%Rec	1	9/10/2022 1:40:01 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 5:56:16 AM
Surr: BFB	98.4	37.7-212	%Rec	1	9/10/2022 5:56:16 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.024	mg/Kg	1	9/10/2022 5:56:16 AM
Toluene	ND	0.049	mg/Kg	1	9/10/2022 5:56:16 AM
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 5:56:16 AM
Xylenes, Total	ND	0.097	mg/Kg	1	9/10/2022 5:56:16 AM
Surr: 4-Bromofluorobenzene	93.0	70-130	%Rec	1	9/10/2022 5:56:16 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	220	60	mg/Kg	20	9/13/2022 5:35:23 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

 $ND \qquad Not \ Detected \ at \ the \ Reporting \ Limit$ 

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 9 of 0

Date Reported:

#### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company

Client Sample ID: BG01-0'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 10:05:00 AM

 Lab ID:
 2209226-010
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/10/2022 1:51:10 AM
Motor Oil Range Organics (MRO)	ND	50	mg/Kg	1	9/10/2022 1:51:10 AM
Surr: DNOP	87.9	21-129	%Rec	1	9/10/2022 1:51:10 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	9/10/2022 6:19:40 AM
Surr: BFB	101	37.7-212	%Rec	1	9/10/2022 6:19:40 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 6:19:40 AM
Toluene	ND	0.050	mg/Kg	1	9/10/2022 6:19:40 AM
Ethylbenzene	ND	0.050	mg/Kg	1	9/10/2022 6:19:40 AM
Xylenes, Total	ND	0.10	mg/Kg	1	9/10/2022 6:19:40 AM
Surr: 4-Bromofluorobenzene	95.1	70-130	%Rec	1	9/10/2022 6:19:40 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	ND	60	mg/Kg	20	9/13/2022 5:47:48 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 10 of 0

### **Analytical Report**

Lab Order **2209226** 

### Hall Environmental Analysis Laboratory, Inc.

Date Reported:

CLIENT: Marathon Oil Company

Client Sample ID: BG01-1'

 Project:
 Parkway 1918 Federal Com 001H 08162
 Collection Date: 9/2/2022 12:00:00 PM

 Lab ID:
 2209226-011
 Matrix: SOIL
 Received Date: 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/10/2022 2:02:17 AM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/10/2022 2:02:17 AM
Surr: DNOP	89.1	21-129	%Rec	1	9/10/2022 2:02:17 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 6:43:15 AM
Surr: BFB	97.9	37.7-212	%Rec	1	9/10/2022 6:43:15 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 6:43:15 AM
Toluene	ND	0.049	mg/Kg	1	9/10/2022 6:43:15 AM
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 6:43:15 AM
Xylenes, Total	ND	0.098	mg/Kg	1	9/10/2022 6:43:15 AM
Surr: 4-Bromofluorobenzene	93.2	70-130	%Rec	1	9/10/2022 6:43:15 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	ND	60	mg/Kg	20	9/13/2022 6:49:52 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 11 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

**CLIENT:** Marathon Oil Company

**Project:** Parkway 1918 Federal Com 001H 08162

**Lab ID:** 2209226-012

Client Sample ID: BG01-2'

**Collection Date:** 9/2/2022 12:05:00 PM **Received Date:** 9/7/2022 7:30:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	Analyst: <b>DGH</b>				
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/10/2022 2:13:22 AM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/10/2022 2:13:22 AM
Surr: DNOP	81.8	21-129	%Rec	1	9/10/2022 2:13:22 AM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/10/2022 7:53:35 AM
Surr: BFB	99.1	37.7-212	%Rec	1	9/10/2022 7:53:35 AM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.025	mg/Kg	1	9/10/2022 7:53:35 AM
Toluene	ND	0.049	mg/Kg	1	9/10/2022 7:53:35 AM
Ethylbenzene	ND	0.049	mg/Kg	1	9/10/2022 7:53:35 AM
Xylenes, Total	ND	0.099	mg/Kg	1	9/10/2022 7:53:35 AM
Surr: 4-Bromofluorobenzene	94.3	70-130	%Rec	1	9/10/2022 7:53:35 AM
EPA METHOD 300.0: ANIONS					Analyst: <b>JMT</b>
Chloride	ND	60	mg/Kg	20	9/13/2022 7:02:17 PM

Matrix: SOIL

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 12 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF01-3'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/23/2022 11:00:00 AM

 Lab ID:
 2209E95-001
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	SANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/29/2022 9:01:30 PM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/29/2022 9:01:30 PM
Surr: DNOP	80.3	21-129	%Rec	1	9/29/2022 9:01:30 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.6	mg/Kg	1	9/29/2022 5:45:13 PM
Surr: BFB	92.7	37.7-212	%Rec	1	9/29/2022 5:45:13 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.023	mg/Kg	1	9/29/2022 5:45:13 PM
Toluene	ND	0.046	mg/Kg	1	9/29/2022 5:45:13 PM
Ethylbenzene	ND	0.046	mg/Kg	1	9/29/2022 5:45:13 PM
Xylenes, Total	ND	0.093	mg/Kg	1	9/29/2022 5:45:13 PM
Surr: 4-Bromofluorobenzene	98.2	70-130	%Rec	1	9/29/2022 5:45:13 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	150	60	mg/Kg	20	10/3/2022 9:28:59 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 1 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF02-3'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/23/2022 11:04:00 AM

 Lab ID:
 2209E95-002
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OR	Analyst: <b>mb</b>				
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/29/2022 9:16:14 PM
Motor Oil Range Organics (MRO)	ND	46	mg/Kg	1	9/29/2022 9:16:14 PM
Surr: DNOP	89.7	21-129	%Rec	1	9/29/2022 9:16:14 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	9/29/2022 6:08:37 PM
Surr: BFB	92.4	37.7-212	%Rec	1	9/29/2022 6:08:37 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.025	mg/Kg	1	9/29/2022 6:08:37 PM
Toluene	ND	0.050	mg/Kg	1	9/29/2022 6:08:37 PM
Ethylbenzene	ND	0.050	mg/Kg	1	9/29/2022 6:08:37 PM
Xylenes, Total	ND	0.099	mg/Kg	1	9/29/2022 6:08:37 PM
Surr: 4-Bromofluorobenzene	98.1	70-130	%Rec	1	9/29/2022 6:08:37 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	170	60	mg/Kg	20	10/3/2022 9:41:24 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 2 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF03-3'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/23/2022 11:42:00 AM

 Lab ID:
 2209E95-003
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE O	RGANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/29/2022 9:30:55 PM
Motor Oil Range Organics (MRO)	ND	50	mg/Kg	1	9/29/2022 9:30:55 PM
Surr: DNOP	67.7	21-129	%Rec	1	9/29/2022 9:30:55 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.8	mg/Kg	1	9/29/2022 6:31:55 PM
Surr: BFB	93.7	37.7-212	%Rec	1	9/29/2022 6:31:55 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.024	mg/Kg	1	9/29/2022 6:31:55 PM
Toluene	ND	0.048	mg/Kg	1	9/29/2022 6:31:55 PM
Ethylbenzene	ND	0.048	mg/Kg	1	9/29/2022 6:31:55 PM
Xylenes, Total	ND	0.095	mg/Kg	1	9/29/2022 6:31:55 PM
Surr: 4-Bromofluorobenzene	98.5	70-130	%Rec	1	9/29/2022 6:31:55 PM
EPA METHOD 300.0: ANIONS					Analyst: <b>JTT</b>
Chloride	ND	60	mg/Kg	20	10/3/2022 10:18:39 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 3 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF04-3'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/23/2022 11:57:00 AM

 Lab ID:
 2209E95-004
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	ANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/29/2022 9:45:43 PM
Motor Oil Range Organics (MRO)	ND	50	mg/Kg	1	9/29/2022 9:45:43 PM
Surr: DNOP	87.6	21-129	%Rec	1	9/29/2022 9:45:43 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/29/2022 8:05:30 PM
Surr: BFB	92.8	37.7-212	%Rec	1	9/29/2022 8:05:30 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.025	mg/Kg	1	9/29/2022 8:05:30 PM
Toluene	ND	0.049	mg/Kg	1	9/29/2022 8:05:30 PM
Ethylbenzene	ND	0.049	mg/Kg	1	9/29/2022 8:05:30 PM
Xylenes, Total	ND	0.098	mg/Kg	1	9/29/2022 8:05:30 PM
Surr: 4-Bromofluorobenzene	98.7	70-130	%Rec	1	9/29/2022 8:05:30 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	62	60	mg/Kg	20	10/3/2022 10:31:04 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 4 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

**CLIENT:** Marathon Oil Company Client Sample ID: CONF05-1.5'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/23/2022 11:45:00 AM

 Lab ID:
 2209E95-005
 Matrix:
 SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OF	RGANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/29/2022 10:00:30 PM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/29/2022 10:00:30 PM
Surr: DNOP	103	21-129	%Rec	1	9/29/2022 10:00:30 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.7	mg/Kg	1	9/29/2022 8:28:55 PM
Surr: BFB	95.9	37.7-212	%Rec	1	9/29/2022 8:28:55 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.024	mg/Kg	1	9/29/2022 8:28:55 PM
Toluene	ND	0.047	mg/Kg	1	9/29/2022 8:28:55 PM
Ethylbenzene	ND	0.047	mg/Kg	1	9/29/2022 8:28:55 PM
Xylenes, Total	ND	0.095	mg/Kg	1	9/29/2022 8:28:55 PM
Surr: 4-Bromofluorobenzene	101	70-130	%Rec	1	9/29/2022 8:28:55 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	200	60	mg/Kg	20	10/3/2022 10:43:28 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 5 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF06-2'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/26/2022 8:46:00 AM

 Lab ID:
 2209E95-006
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OR	GANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/29/2022 10:15:25 PM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/29/2022 10:15:25 PM
Surr: DNOP	83.5	21-129	%Rec	1	9/29/2022 10:15:25 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/29/2022 8:52:21 PM
Surr: BFB	93.3	37.7-212	%Rec	1	9/29/2022 8:52:21 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.025	mg/Kg	1	9/29/2022 8:52:21 PM
Toluene	ND	0.049	mg/Kg	1	9/29/2022 8:52:21 PM
Ethylbenzene	ND	0.049	mg/Kg	1	9/29/2022 8:52:21 PM
Xylenes, Total	ND	0.098	mg/Kg	1	9/29/2022 8:52:21 PM
Surr: 4-Bromofluorobenzene	98.7	70-130	%Rec	1	9/29/2022 8:52:21 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	110	60	mg/Kg	20	10/3/2022 10:55:53 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 6 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF07-2'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/26/2022 8:48:00 AM

 Lab ID:
 2209E95-007
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	ANICS				Analyst: mb
Diesel Range Organics (DRO)	ND	13	mg/Kg	1	9/29/2022 10:30:17 PM
Motor Oil Range Organics (MRO)	ND	44	mg/Kg	1	9/29/2022 10:30:17 PM
Surr: DNOP	104	21-129	%Rec	1	9/29/2022 10:30:17 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.7	mg/Kg	1	9/29/2022 9:16:02 PM
Surr: BFB	93.0	37.7-212	%Rec	1	9/29/2022 9:16:02 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.023	mg/Kg	1	9/29/2022 9:16:02 PM
Toluene	ND	0.047	mg/Kg	1	9/29/2022 9:16:02 PM
Ethylbenzene	ND	0.047	mg/Kg	1	9/29/2022 9:16:02 PM
Xylenes, Total	ND	0.093	mg/Kg	1	9/29/2022 9:16:02 PM
Surr: 4-Bromofluorobenzene	98.5	70-130	%Rec	1	9/29/2022 9:16:02 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	230	60	mg/Kg	20	10/3/2022 11:08:17 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 7 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company Client Sample ID: CONF08-3'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/26/2022 10:52:00 AM

 Lab ID:
 2209E95-008
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	ANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	14	mg/Kg	1	9/29/2022 10:45:03 PM
Motor Oil Range Organics (MRO)	ND	47	mg/Kg	1	9/29/2022 10:45:03 PM
Surr: DNOP	100	21-129	%Rec	1	9/29/2022 10:45:03 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.6	mg/Kg	1	9/29/2022 9:39:43 PM
Surr: BFB	92.1	37.7-212	%Rec	1	9/29/2022 9:39:43 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.023	mg/Kg	1	9/29/2022 9:39:43 PM
Toluene	ND	0.046	mg/Kg	1	9/29/2022 9:39:43 PM
Ethylbenzene	ND	0.046	mg/Kg	1	9/29/2022 9:39:43 PM
Xylenes, Total	ND	0.092	mg/Kg	1	9/29/2022 9:39:43 PM
Surr: 4-Bromofluorobenzene	97.9	70-130	%Rec	1	9/29/2022 9:39:43 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	140	60	mg/Kg	20	10/3/2022 11:20:42 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 8 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

**CLIENT:** Marathon Oil Company Client Sample ID: CONF09-1.5'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/26/2022 8:59:00 AM

 Lab ID:
 2209E95-009
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE OI	RGANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	21	14	mg/Kg	1	9/29/2022 10:59:59 PM
Motor Oil Range Organics (MRO)	ND	46	mg/Kg	1	9/29/2022 10:59:59 PM
Surr: DNOP	95.1	21-129	%Rec	1	9/29/2022 10:59:59 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.9	mg/Kg	1	9/29/2022 10:03:16 PM
Surr: BFB	90.1	37.7-212	%Rec	1	9/29/2022 10:03:16 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.024	mg/Kg	1	9/29/2022 10:03:16 PM
Toluene	ND	0.049	mg/Kg	1	9/29/2022 10:03:16 PM
Ethylbenzene	ND	0.049	mg/Kg	1	9/29/2022 10:03:16 PM
Xylenes, Total	ND	0.097	mg/Kg	1	9/29/2022 10:03:16 PM
Surr: 4-Bromofluorobenzene	95.3	70-130	%Rec	1	9/29/2022 10:03:16 PM
EPA METHOD 300.0: ANIONS					Analyst: <b>JTT</b>
Chloride	430	60	mg/Kg	20	10/4/2022 9:14:39 AM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 9 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

**CLIENT:** Marathon Oil Company Client Sample ID: CONF10-1.5'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/26/2022 8:56:00 AM

 Lab ID:
 2209E95-010
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	ANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	21	14	mg/Kg	1	9/29/2022 11:14:49 PM
Motor Oil Range Organics (MRO)	ND	47	mg/Kg	1	9/29/2022 11:14:49 PM
Surr: DNOP	112	21-129	%Rec	1	9/29/2022 11:14:49 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	4.7	mg/Kg	1	9/29/2022 10:26:38 PM
Surr: BFB	91.7	37.7-212	%Rec	1	9/29/2022 10:26:38 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.023	mg/Kg	1	9/29/2022 10:26:38 PM
Toluene	ND	0.047	mg/Kg	1	9/29/2022 10:26:38 PM
Ethylbenzene	ND	0.047	mg/Kg	1	9/29/2022 10:26:38 PM
Xylenes, Total	ND	0.094	mg/Kg	1	9/29/2022 10:26:38 PM
Surr: 4-Bromofluorobenzene	97.2	70-130	%Rec	1	9/29/2022 10:26:38 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	380	60	mg/Kg	20	10/4/2022 9:27:03 AM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 10 of 0

2209E95-011

Lab ID:

**Analytical Report**Lab Order **2209E95** 

Date Reported:

Received Date: 9/28/2022 7:25:00 AM

#### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company

Client Sample ID: CONF11 Wall-1'

Project: Parkway 1918 Federal Com 001H 8 16 2

Collection Date: 9/26/2022 9:11:00 AM

Matrix: SOIL

Result **RL Qual Units** DF **Date Analyzed** Analyses **EPA METHOD 8015M/D: DIESEL RANGE ORGANICS** Analyst: mb Diesel Range Organics (DRO) ND 15 mg/Kg 1 9/29/2022 11:29:34 PM Motor Oil Range Organics (MRO) ND 50 mg/Kg 1 9/29/2022 11:29:34 PM Surr: DNOP 77.4 21-129 %Rec 1 9/29/2022 11:29:34 PM **EPA METHOD 8015D: GASOLINE RANGE** Analyst: RAA Gasoline Range Organics (GRO) ND 9/29/2022 10:49:59 PM 5.0 mg/Kg 1 Surr: BFB 92.8 37.7-212 %Rec 1 9/29/2022 10:49:59 PM **EPA METHOD 8021B: VOLATILES** Analyst: RAA Benzene ND 0.025 mg/Kg 9/29/2022 10:49:59 PM 1 Toluene ND 0.050 mg/Kg 1 9/29/2022 10:49:59 PM Ethylbenzene ND 0.050 mg/Kg 1 9/29/2022 10:49:59 PM Xylenes, Total ND 0.099 mg/Kg 1 9/29/2022 10:49:59 PM Surr: 4-Bromofluorobenzene 98.4 70-130 %Rec 1 9/29/2022 10:49:59 PM **EPA METHOD 300.0: ANIONS** Analyst: JTT Chloride 59 10/4/2022 9:39:28 AM 160 ma/Ka 20

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

QL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix interference

B Analyte detected in the associated Method Blank

E Estimated value

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Limit

Page 11 of 0

Date Reported:

### Hall Environmental Analysis Laboratory, Inc.

CLIENT: Marathon Oil Company

Client Sample ID: CONF12 Wall-1'

 Project:
 Parkway 1918 Federal Com 001H 8 16 2
 Collection Date: 9/26/2022 12:04:00 PM

 Lab ID:
 2209E95-012
 Matrix: SOIL
 Received Date: 9/28/2022 7:25:00 AM

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORG	ANICS				Analyst: <b>mb</b>
Diesel Range Organics (DRO)	ND	15	mg/Kg	1	9/29/2022 11:44:26 PM
Motor Oil Range Organics (MRO)	ND	48	mg/Kg	1	9/29/2022 11:44:26 PM
Surr: DNOP	93.8	21-129	%Rec	1	9/29/2022 11:44:26 PM
EPA METHOD 8015D: GASOLINE RANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	9/29/2022 11:13:25 PM
Surr: BFB	91.8	37.7-212	%Rec	1	9/29/2022 11:13:25 PM
EPA METHOD 8021B: VOLATILES					Analyst: RAA
Benzene	ND	0.025	mg/Kg	1	9/29/2022 11:13:25 PM
Toluene	ND	0.050	mg/Kg	1	9/29/2022 11:13:25 PM
Ethylbenzene	ND	0.050	mg/Kg	1	9/29/2022 11:13:25 PM
Xylenes, Total	ND	0.10	mg/Kg	1	9/29/2022 11:13:25 PM
Surr: 4-Bromofluorobenzene	96.5	70-130	%Rec	1	9/29/2022 11:13:25 PM
EPA METHOD 300.0: ANIONS					Analyst: JTT
Chloride	110	60	mg/Kg	20	10/4/2022 9:51:52 AM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix interference
- B Analyte detected in the associated Method Blank
- E Estimated value
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Limit

Page 12 of 0

# ATTACHMENT F

48-Hour Confirmation Sampling Notification Emails

#### Melodie Sanjari

Environmental Professional Permian & Oklahoma 575-988-8753



From: Sanjari, Melodie (MRO)

Sent: Monday, September 19, 2022 11:04 AM

**To:** Enviro, OCD, EMNRD < OCD.Enviro@state.nm.us > **Cc:** Ashley Giovengo < ashley.giovengo@wescominc.com >

Subject: Marathon Oil Company - 48 Hour Notice for Sampling - nAPP2222844442

Good Morning,

Please let this email serve as the required 48 hour notice for final confirmation sampling to close out incident nAPP2222844442 at the Parkway facility. Excavation activities will begin Wednesday morning (9/21/22) and confirmation samples are expected to be collected on the Wednesday and/or potentially Thursday.

Thanks and have a wonderful day.

#### **Melodie Sanjari**

Environmental Professional Permian & Oklahoma 575-988-8753



# ATTACHMENT G

48-Hour Liner Inspection Notification Emails

From: Ashley Giovengo
To: Cole Burton

Subject: FW: Marathon Oil Company - 48 Hour Notice for Sampling - nAPP2222844442

Date: Wednesday, October 5, 2022 2:12:15 PM

**Ashley Giovengo**, Environmental Manager - Permian

O (218) 724-1322 | C (505) 382-1211

WescomInc.com | ashley.giovengo@WescomInc.com

"I am in charge of my own safety."

From: Sanjari, Melodie (MRO) <msanjari@marathonoil.com>

Sent: Thursday, September 22, 2022 7:51 AM

**To:** Enviro, OCD, EMNRD < OCD.Enviro@state.nm.us> **Cc:** Ashley Giovengo < ashley.giovengo@wescominc.com>

Subject: RE: Marathon Oil Company - 48 Hour Notice for Sampling - nAPP2222844442

Good Morning,

Apologies as it was left off of the original notification but a liner integrity inspection will also take place during the excavation and confirmation sampling event.

Thank you

#### Melodie Sanjari

Environmental Professional Permian & Oklahoma 575-988-8753



From: Sanjari, Melodie (MRO)

Sent: Monday, September 19, 2022 11:47 AM

To: Enviro, OCD, EMNRD < OCD. Enviro@state.nm.us>

Subject: RE: Marathon Oil Company - 48 Hour Notice for Sampling - nAPP2222844442

Good Morning,

The remediation has been pushed to a start date of Thursday the 22<sup>nd</sup> with potential for samples to be collected on the 22<sup>nd</sup> and/or the 23<sup>rd</sup>.

Thanks

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 154899

#### **CONDITIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	154899
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created I	By Condition	Condition Date
rhamle	t We have received your closure report and final C-141 for Incident #NAPP2222844442 PARKWAY 1H, thank you. This closure is approved.	1/4/2023