

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NPAC0604048727
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Dale Woodall Title: Env. Professional

Signature: Dale Woodall Date: 1/12/2023

email: dale.woodall@dvn.com Telephone: 575-748-1838

**APPROVED**

*By Ashley Maxwell at 1:26 pm, Jan 17, 2023*



Devon Energy Production Company, LP

## Request for Incident Closure

August 4<sup>th</sup>, 2020

Townsend State #9

API – 30-025-34829

nPAC0604048727

NO-RP

### Description of Original Incident:

On May 4<sup>th</sup>, of 2004, an unknown event happened that caused an unknown fluid to be released. The release was approximately 50 gallons in volume. No fluid was recovered. The location of this site is, J-2-16S-35E; 32.9557686, -103.4260483.

### Immediate Actions Taken:

My apologies, but we could not find any other information regarding this incident. This well was plugged and abandoned on 1/11/2007 and was released on 10/7/2010. As you can see in the following pictures, there appears to be no environmental impact on this location from this release.

Our current assessment of this incident was performed on November 11<sup>th</sup>, 2019. **With the information and pictures provided, we would like to respectfully request that the incident be closed out.**

Thank you so much for your time. If there is anything more that you would like us to do with this incident in order to close it out, please let us know and we'll be happy to make the necessary arrangements.

Have a wonderful day,

Tom Bynum

***Tom Bynum***

EHS Consultant/Contractor

[tom.bynum@dvn.com](mailto:tom.bynum@dvn.com)

580-748-1613




Devon Energy Production Company, LP







Devon Energy Production Company, LP





Devon Energy Production Company, LP

OCD Permitting

Home > Searches > Incidents > Incident Details

NPAC0604048727 2004 A OTH @ 30-025-34829

General Incident Information

Site Name:

Well:

Facility:

Operator:

Status:

Type:

District:

[30-025-34829] TOWNSEND STATE #009

[6137] DEVON ENERGY PRODUCTION COMPANY, LP

Closure Not Approved

Other

Hobbs

Severity:

Surface Owner:

County:

Lea (25)

Incident Location:

Lat/Long:

Directions:

J-02-169-35E Lot: 10 3927 FNL 1940 FEL

32.9557686,-103.4260483 NAD83

Notes

Source of Referral: Industry Rep

Action / Escalation:

Resulted In Fire: ☐

Will or Has Reached Watercourse: ☐

Endangered Public Health: ☐

Property Or Environmental Damage: ☐

Contact Details

Contact Name:

Contact Title:

Event Dates

Date of Discovery: 05/04/2004

OCD Notified of Major Release: 05/04/2004

Extension Date: 11/15/2018

Cancelled Date:

Initial C-141 Received:

Characterization Report Received:

Remediation Plan Received:

Closure Report Received:

Characterization Report Approved:

Remediation Plan Approved:

Remediation Due:

Closure Report Approved:

Incidents Materials

Cause	Source	Material	Volume				Units
			Unk.	Spilled	Recovered	Lost	
Other	Other (Specify)	Other (Specify)	<input type="checkbox"/>	50	0	50	GAL

Incident Events

No events Found

Orders

No Orders Found

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NPAC0604048727
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Tom Bynum Title: EHS Consultant

Signature: Tom Bynum Date: 8/4/2020

email: tom.bynum@dvn.com Telephone: 575-748-0176

Incident ID	NPAC0604048727
District RP	
Facility ID	
Application ID	

**OCD Only**

Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: \_\_\_\_\_ Date: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 175435

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 175435
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
amaxwell	None	1/17/2023