District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2303040186
District RP	
Facility ID	
Application ID	

## **Release Notification**

## **Responsible Party**

Dagmangilala I	Dowley TAD 1	DOCK ODED AT	TING LLC		OGRID 372	20.43	
Responsible Party TAP ROCK OPERATING, LLC							
Contact Name CHRISTIAN COMBS			Contact Telephone (720)360-4028				
Contact email ccombs@taprk.com			Incident # (assigned by OCD)				
Contact mail:	ing address	523 Park Point I	)r. #200		Golden CC	), 80401	
			Location	of F	Release So	ource	
atitude 32.1	99247		(NAD 83 in dec	cimal de	Longitude <u>-1</u> egrees to 5 decime		
Site Name PF		US CTB PAD A	(CLOSEST WEI	L:	Site Type P	PRODUCTION	
Date Release		1/29/2023			API# (if applicable) 30-025-48727		
Unit Letter	Section	Township	Range		Count	ty	
M	22	248	33E	LEA COUNTY			
	Materia	il(s) Released (Select :	Nature and			Release justification for the volumes provided below)	
Crude Oil		Volume Release		curcure	atoms of appearing	Volume Recovered (bbls)	
Noduced Produced	Water	Volume Releas	ed (bbls) 31.77BB	LS		Volume Recovered (bbls) 0BBLS	
Is the concentration of dissolved chloric produced water >10,000 mg/l?			hlorid	le in the	⊠ Yes □ No		
Condensate Volume Released (bbls)					Volume Recovered (bbls)		
☐ Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide unit		s)	Volume/Weight Recovered (provide units)				
Cause of Rel	ease						
BURIED W. BEING REF		ANSFER LINE I	LEAKED CAUSIN	NG FI	LUID TO SUI	RFACE. WELLS WERE SHUT IN AND LINE IS	

Page 2

State of New Mexico
Oil Conservation Division

	0 0
Incident ID	NAPP2303040186
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?  VOLUME OF RELEASE
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?  THE OCD, BRATCHER, HAMLET, NOBUI, HARIMON AT 10:57AM, BY NATALIE GLADDEN /30/23
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
The impacted area ha	as been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and r	ecoverable materials have been removed and managed appropriately.
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred nt area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environ failed to adequately investig	ormation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have gate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name: Natalie G Signature:	lu Gladden Date: 1/30/23
OCD Only  Jocely Received by:	yn Harimon 01/30/2023 Date:

Soil Type	Porosity	Length	Width	<b>Depth</b> (.083 per inch)	Cubic Feet	Estimated Barrels	Soil Type
Clay	0.15	10	10	0.083	8.3	0.22	Clay
Peat	0.40	10	10	0.083	8.3	0.59	Peat
Glacial Sediments	0.13	10	10	0.083	8.3	0.19	Glacial Sediments
Sandy Clay	0.12	10	10	0.083	8.3	0.18	Sandy Clay
Silt	0.16	10	10	0.083	8.3	0.24	Silt
Loess	0.25	10	10	0.083	8.3	0.37	Loess
Fine Sand	0.16	10	10	0.083	8.3	0.24	Fine Sand
Medium Sand	0.25	10	10	0.083	8.3	0.37	Medium Sand
Coarse Sand	0.26	10	10	0.083	8.3	0.38	Coarse Sand
Gravely Sand	0.26	10	10	0.083	8.3	0.38	Gravely Sand
Fine Gravel	0.26	10	10	0.083	8.3	0.38	Fine Gravel
Medium Gravel	0.20	48.95	43.87	0.415	891.18615	31.77	Medium Gravel
Coarse Gravel	0.18	10	10	0.083	8.3	0.27	Coarse Gravel
Sandstone	0.25	10	10	0.083	8.3	0.37	Sandstone
Siltstone	0.18	10	10	0.083	8.3	0.27	Siltstone
Shale	0.05	10	10	0.083	8.3	0.07	Shale
Limestone	0.13	10	10	0.083	8.3	0.19	Limestone
Basalt	0.19	10	10	0.083	8.3	0.28	Basalt
Volcanic Tuff	0.20	10	10	0.083	8.3	0.30	Volcanic Tuff
Standing Liquids	Х	10	10	0.083	8.3	1.48	Standing Liquids

1	2	3	4	5	6
0.083	0.166	0.250	0.332	0.415	0.500
7	8	9	10	11	12
0.581	0.664	0.750	0.830	0.913	1.000

NOTE: This is an **estimate** tool designed for quick field estimates of whether a C-141 should be required (*I.e. a release is estimated to be greater than or less than 5 barrel volumes*)

Choose the one prevailing ground type for estimating spill volumes at a single location.

Note that the depth should be measured in feet and tenths of feet (1 inch = .083)

Cubic Feet = L x W x D

Estimated Barrels = ((Cubic Feet x Porosity) / 5.61)

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 180640

## **CONDITIONS**

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	180640
	Action Type:
	[C-141] Release Corrective Action (C-141)

## CONDITIONS

Created By		Condition Date
jharimon	None	1/31/2023