

Released to Inquiries: 4/3/2023 3:00:08 PM

RECEIVED

Form C-141
Revised October 10, 2003

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 14 2008
Copies to appropriate District Office in accordance with Rule 116 on back side of form

HOBBS OCD

I French Dr., Hobbs, NM 88240
II Grand Avenue, Artesia, NM 88210
III Brazos Road, Aztec, NM 87410
IV St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Company Name: Targa Midstream Services L P	Contact: James Lingnau 505.394.2534
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Middle Plant	Facility Type: Natural Gas Processing Facility
Lease Owner: Versado Gas Processors, L.P.	Mineral Owner:
	Lease No.

LOCATION OF RELEASE

Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	3	21S	37E					Lea

Latitude 32.25.16.9 N Longitude 103.08.47.8W

NATURE OF RELEASE

Type of Release: Diglycolamine (DGA) and water	Volume of Release: Approximately 1000 gallons	Volume Recovered: Approximately 500 gallons
Type of Release: Acid Gas Flare	Date and Hour of Occurrence: 5/24/07 Approx. 9:20AM	Date and Hour of Discovery: Same
Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Rebecca Woodell Attempted to notify OCD on 5/25/07 and phone lines were out. Don Embrey Sent E-mail on 5-29-07	
To Whom? Rebecca Woodell and Don Embrey	Date and Hour 5/25/07 and 5/29/07	
Watercourse Reached? No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
 Damage in the Amine Regenerator caused a high differential pressure in the vessel causing a plant upset that resulted in the liquid amine carrying into the flare system. The plant was shutdown, the vessel entered and the trays repaired.

Describe Area Affected and Cleanup Action Taken.*
 DGA-water mix sprayed over the plant yard. Targa recovered approximately 500 gallons of the DGA-water mix by drip truck. The remaining of the spill was spread with fresh soil to soak up the mix. The area affected was then scraped to remove 88,940 pounds of contaminated soil and sent to the Lea Land Landfill.

Operator hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of responsibility should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, air, or human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District Supervisor: <i>[Signature]</i>	
Advisor:	Approval Date: 2-14-08	Expiration Date: —
Email Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/29/07 Phone: (432) 688-0546		1 RP-1469

Attach Additional Sheets If Necessary

Received by: OCD: 4/3/2023 2:58:44 PM

Page 1 of 2

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 203547

CONDITIONS

Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002	OGRID: 24650
	Action Number: 203547
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	None	4/3/2023