District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party EOG Resources

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2310047413
District RP	
Facility ID	
Application ID	

# **Release Notification**

### **Responsible Party**

**OGRID** 7377

Contact Name James Kennedy		Contact Te	elephone 432-8	848-9146			
Contact ema	il james_ker	nedy@eogresour	ces.com		Incident #	(assigned by OCI	D) nAPP2310047413
Contact mail 79706	ing address	5509 Champions l	Drive Midland, T	Ϋ́X	1		
			Logotion	, of D	delease So	N11400	
			Location	1 01 K	keiease Sc	ource	
Latitude 32.1	00813		011D 02 : 1		Longitude -		-
<b>-</b>			(NAD 83 in a	есітаі ає			
Site Name Almost Eddy Lay Flat Release			Site Type T	Transfer line			
Date Release	Discovered	03/24/2023			API# (if app	licable)	
Unit Letter	Section	Township	Range		Coun		
I	30	25S	32E	Lea			
Surface Owne	r: State	☐ Federal ☐ Ti	ribal 🛛 Private (	(Name:			)
			Nature an	d Va	luma af I	Dalaasa	
			Mature an	u vo	iuille of r	Neiease	
Crude Oi				h calcula	tions or specific		he volumes provided below)
	, ,					covered (bbls)	
	Water	Volume Release	` ′				covered (bbls) 0
		Is the concentrate produced water	tion of dissolved >10 000 mg/l?	chlorid	e in the	Yes T	No
Condensa	ite	Volume Release				Volume Rec	covered (bbls) 0
Natural G	ias	Volume Release	ed (Mcf)			Volume Rec	covered (Mcf)
Other (de	scribe)	Volume/Weight	Released (provid	de units	)	Volume/We	ight Recovered (provide units)
A leak on a la	ay flat line v	vas found.					

Received by OCD: 4/10/2023 1:22:51 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

w Mexico Page 2 of 7

Incident ID	NAPP2310047413
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release? Greater than 25 bbls
⊠ Yes □ No	
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? D.enviro@emnrd.nm.gov, 03/24/23, email.
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
☐ The impacted area ha	s been secured to protect human health and the environment.
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and managed appropriately.
	AC the responsible party may commence remediation immediately after discovery of a release. If remediation
within a lined containmen	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name: _James F.	Kennedy Title:Env Specialist
Signature:	Date: _03/24/2023
email:james_kennedy	#@eogresouirces.com         Telephone:        432-258-4346
OCD Only  Received by:	celyn Harimon Date: 04/10/2023

Received by OCD: 4/10/2023 1:22:51 PM Form C-141 State of New Mexico Page 3 Oil Conservation Division

	Page 3 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

# Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.  Field data  Data table of soil contaminant concentration data  Depth to water determination  Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release  Boring or excavation logs  Photographs including date and GIS information  Topographic/Aerial maps  Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 4/10/2023 1:22:51 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thruaddition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	ifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name:	
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Received by OCD: 4/10/2023 1:22:51 PM Form C-141 State of New Mexico Page 5 Oil Conservation Division

	I uge 5 of
Incident ID	
District RP	
Facility ID	
Application ID	

# **Remediation Plan**

Remediation Plan Checklist: Each of the following items must b	e included in the plan.
<ul> <li>□ Detailed description of proposed remediation technique</li> <li>□ Scaled sitemap with GPS coordinates showing delineation poin</li> <li>□ Estimated volume of material to be remediated</li> <li>□ Closure criteria is to Table 1 specifications subject to 19.15.29.</li> <li>□ Proposed schedule for remediation (note if remediation plan tin</li> </ul>	12(C)(4) NMAC
Deferral Requests Only: Each of the following items must be con-	nfirmed as part of any request for deferral of remediation.
Contamination must be in areas immediately under or around p deconstruction.	roduction equipment where remediation could cause a major facility
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human healt	n, the environment, or groundwater.
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
☐ Approved	Approval
Signature:	Date:

Received by OCD: 4/10/2023 1:22:51 PM Form C-141 State of New Mexico Page 6 Oil Conservation Division

	Page 6 of
Incident ID	
District RP	
Facility ID	
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODG	C District office must be notified 2 days prior to final sampling)
☐ Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	nations. The responsible party acknowledges they must substantially notitions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.
Signature:	Date:
email:	Telephone:
OCD Only	
OCD Only Received by:	Date:
Received by:  Closure approval by the OCD does not relieve the responsible party	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible
Received by:  Closure approval by the OCD does not relieve the responsible party remediate contamination that poses a threat to groundwater, surface	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 205737

### **CONDITIONS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	205737
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By	Condition	Condition Date
jharimon	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-	4/10/2023