

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Flat Head Federal Com #027H	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-43147
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 14	Township 17S	Range 32E	Feet from the 1170	North/South Line North	Feet from the 990	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.83859469 Longitude -103.7317216

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100 bbls	Volume Recovered: 99 bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: April 4, 2017 12:00 am	Date and Hour of Discovery: April 4, 2017 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD & Ms. Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour: April 4, 2017 11:27 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 1:01 pm, Apr 17, 2017

Describe Cause of Problem and Remedial Action Taken.*

This release was due to a POC Malfunction causing the water pump not to turn on.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>Dyf</i>	
Title: Senior HSE Coordinator	Approval Date: 4/17/2017	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 7, 2017 Phone: 432-683-7443		

Attach Additional Sheets If Necessary

nOY1709756862

From: Rebecca Haskell
To: [Yu, Olivia, EMNRD](#); [Price, Henryetta](#)
Cc: [Oberding, Tomas, EMNRD](#); [Jim Amos \(jamos@blm.gov\)](mailto:jamos@blm.gov); stucker@blm.gov
Subject: FW: (C-141 Initial) Flat Head Federal Com #27H 4/4/17 (30-025-43147)
Date: Monday, April 17, 2017 11:44:58 AM
Attachments: [Flat Head Federal Com #27H Battery Final C-141 4-4-17 \(30-025-43147\).pdf](#)

Ms. Yu / Ms. Price,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]

Sent: Friday, April 07, 2017 5:00 PM
To: Rebecca Haskell; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD; Jim Amos (jamos@blm.gov)
Subject: [External] RE: (C-141 Initial) Flat Head Federal Com #27H 4/4/17 (30-025-43147)

**** External email. Use caution. ****

Dear Ms. Haskell:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Rebecca Haskell [<mailto:RHaskell@concho.com>]
Sent: Friday, April 7, 2017 10:35 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD <Tomas.Oberding@state.nm.us>; Jim Amos (jamos@blm.gov)
<jamos@blm.gov>
Subject: (C-141 Initial) Flat Head Federal Com #27H 4/4/17 (30-025-43147)

Ms. Yu, / Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rebecca Haskell
Sent: Tuesday, April 04, 2017 12:27 PM
To: Olivia Yu (olivia.yu@state.nm.us); stucker@blm.gov
Cc: Jim Amos (jamos@blm.gov); Oberding, Tomas, EMNRD (Tomas.Oberding@state.nm.us)
Subject: (Notification) Flat Head Federal Com #27H 4/4/17 (30-025-43147)

Ms. Yu / Ms. Tucker,

COG Operating LLC is reporting a release at the Flat Head Com #27H Tank Battery.

Section 14 Township 17S Range 32E

The release occurred on April 4, 2017 at approximately 12:00 AM.

Estimated Released: Approx. 100 bbls of Produced Water.

Estimated Recovered: Approx. 99 bbls of Produced Water.

This release was due to a POC malfunction causing the water pump not to turn on. This release occurred within a lined facility. A vacuum truck was dispatched to recover the standing fluid. The initial C-141 will follow. If you have any additional questions please feel free to contact me.

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If

you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Flat Head Federal Com #027H	Facility Type: Tank Battery	
Surface Owner: Federal	Mineral Owner:	API No. 30-025-43147

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	17S	32E	1170	North	990	East	Lea

Latitude 32.83859469 Longitude -103.7317216

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100 bbls	Volume Recovered: 99 bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: April 4, 2017 12:00 am	Date and Hour of Discovery: April 4, 2017 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD & Ms. Tucker BLM	
By Whom? Rebecca Haskell	Date and Hour: April 4, 2017 11:27 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 3:44 pm, Apr 07, 2017

Describe Cause of Problem and Remedial Action Taken.*

This release was due to a POC Malfunction causing the water pump not to turn on.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>oy</i>	
Title: Senior HSE Coordinator	Approval Date: 4/7/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 7, 2017 Phone: 432-683-7443	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	nOY1709756862
Attach Additional Sheets If Necessary		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 206018

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 206018
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	historic document upload	4/11/2023