

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2307447383
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Chevron U.S.A., Inc.	OGRID 4323
Contact Name Aaron Rotto	Contact Telephone 281-543-3205
Contact email aaron.ritto@chevron.com	Incident # (assigned by OCD) nAPP2307447383
Contact mailing address 6301 Deauville Blvd Midland, TX 79706	

Location of Release Source

Latitude 32.2404213 Longitude -103.6210556
(NAD 83 in decimal degrees to 5 decimal places)

Site Name J KEATS 1 24 32 #040H	Site Type Oil
Date Release Discovered 3/14/2023	API# (if applicable) 30-025-41582

Unit Letter	Section	Township	Range	County
P	01	24S	32E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 2.065	Volume Recovered (bbls) 0.5
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 6.196	Volume Recovered (bbls) 0
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Packing on the stuffing box of well failed.

Incident ID	nAPP2307447383
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? 	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Aaron Rotto</u>	Title: <u>Environmental Specialist</u>
Signature: <u>Aaron C. Rotto</u>	Date: <u>6/21/2023</u>
email: <u>aaron.ritto@chevron.com</u>	Telephone: <u>281-543-3205</u>
<u>OCD Only</u> Received by: <u>Shelly Wells</u> Date: <u>6/22/2023</u>	

State of New Mexico
Oil Conservation Division

Incident ID	nAPP2307447383
District RP	
Facility ID	
Application ID	

Total Spill



Oil Recovered (bbl)	Oil Released (bbl)	Water Recovered (bbl)	Water Released (bbl)
---------------------	--------------------	-----------------------	----------------------

Spill Calculations

Area 1_Shape	Area 1_StandingLiquidDimensions	Area 1_PenetrationDepth	Area 1_Water to Soil	Area 1_Standing Liquid Volume	Area 1_Oil Volume	Area 1_Water Volume
Rectangle	22 ft x 44 ft x .5 in	.5 in	1.078 bbl	8.261 bbl	2.065 bbl	6.196 bbl
Area 2_Shape	Area 2_StandingLiquidDimensions	Area 2_PenetrationDepth	Area 2_Water to Soil	Area 2_Standing Liquid Volume	Area 2_Oil Volume	Area 2_Water Volume

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 231017

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 231017
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	6/22/2023