District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Page 1 of 5

Incident ID	nAPP2317752059
District RP	
Facility ID	fKJ1518128159
Application ID	

Release Notification

Responsible Party

Responsible Party OXY USA	OGRID 16696	
Contact Name Shaina Rojas	Contact Telephone 432-448-6693	
Contact email Shaina_rojas@oxy.com	Incident	
Contact mailing address 1600 Gehrig Dr. Midland TX 79706		

Location of Release Source

Latitude 32.7065

Longitude -103.1159_ (NAD 83 in decimal degrees to 5 decimal places)

Site Name North Hobbs NIB		Site Type Central Tank Battery
Date Release Discovered	06/9/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
Е	33	18S	38E	Lea

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Carbon Dioxide	272MCF	0MCF

Compressor went down on fan motor vibration; restart unit ASAP

orm C-141	3 2:36:32 PM State of New Mexico	Incident ID	nAPP2317752059
ge 2	Oil Conservation Division	mendent 1D	114112317732033
		District RP	
		Facility ID	fKJ1518128159
		Application ID	
Was this a major release as defined by 19.15.29.7(A) NMAC? □ Yes⊠ No	If YES, for what reason(s) does the responsible part	y consider this a major release	?
	otice given to the OCD? By whom? To whom? Whe	en and by what means (phone,	email, etc)?
The responsible	Initial Response party must undertake the following actions immediately unless they		uld result in injury
\square The source of the rele	ease has been stopped.		
The impacted area ha	s been secured to protect human health and the enviro	onment.	
Released materials ha	ave been contained via the use of berms or dikes, absor	rbent pads, or other containme	ent devices.
All free liquids and re	ecoverable materials have been removed and managed	l appropriately.	
	d above have <u>not</u> been undertaken, explain why:	·· · · ·	
	a accre nave <u>nev</u> ocen anderaken, explain why.		
has begun, please attach	IAC the responsible party may commence remediation a narrative of actions to date. If remedial efforts hav at area (see $19.15.29.11(A)(5)(a)$ NMAC), please attac	ve been successfully complete	d or if the release occurred
regulations all operators are	rmation given above is true and complete to the best of my large required to report and/or file certain release notifications and ment. The acceptance of a C-141 report by the OCD does not file the true of the	d perform corrective actions for r	eleases which may endanger

regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

rinted Name:Shaina Rojas Title: Environmentalist Specialist	
Signature: <i>Shaina Rojas</i>	Date: 6/26/2023
email:Shaina_rojas@oxy.com	Telephone432-448-6693
OCD Only	
Received by: <u>Shelly Wells</u>	Date: <u>6/26/2023</u>

Received by OCD: 6/26/2023 2:36:32 PMForm C-141State of New MexicoPage 6Oil Conservation Division

Page 3 of 5Incident IDnAPP2317752059District RPFacility IDfKJ1518128159Application ID

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following	ng items must be included in the closure report.	
A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
Description of remediation activities		
and regulations all operators are required to report and/or file ce may endanger public health or the environment. The acceptance should their operations have failed to adequately investigate and human health or the environment. In addition, OCD acceptance compliance with any other federal, state, or local laws and/or reg restore, reclaim, and re-vegetate the impacted surface area to the accordance with 19.15.29.13 NMAC including notification to th Printed Name:Shaina Rojas		
OCD Only		
Received by:	Date:	
	arty of liability should their operations have failed to adequately investigate and ace water, human health, or the environment nor does not relieve the responsible ind/or regulations.	
Closure Approved by:	Date:	
Printed Name:	Title:	

nAPP2317752059 compressor went down on fan motor vibration ;restarted unit



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	232944
	Action Type:
	[C-141] Release Corrective Action (C-141)
	• · · · ·

CONDITIONS

Created By Condition scwells None

CONDITIONS

Action 232944

Condition Date

6/26/2023