District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Page 1 of 5

Incident ID	nAPP2317834814
District RP	
Facility ID	fJXK1520829861
Application ID	

Release Notification

Responsible Party

Responsible Party OXY USA	OGRID 16696	
Contact Name Shaina Rojas	Contact Telephone 432-448-6693	
Contact email Shaina_rojas@oxy.com	Incident	
Contact mailing address 1600 Gehrig Dr. Midland TX 79706		

Location of Release Source

Latitude 32.680192

Longitude -103.115965 (NAD 83 in decimal degrees to 5 decimal places)

Site Name South Hobbs Unit CTB		Site Type Central Tank Battery
Date Release Discovered	06/10/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
А	09	19S	38E	Lea

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe) Carbon Dioxide	Volume/Weight Released (provide units) 149MCF	Volume/Weight Recovered (provide units) 0MCF
Carbon Dioxide		

Compressor went down on high discharge temperature

<i>ceived by OCD: 6/27/202</i> . orm C-141	3 6:44:03 PM State of New Mexico	Incident ID	Pag nAPP2317834814
ge 2	Oil Conservation Division	Incident ID	HAFF2517654614
-		District RP	
		Facility ID	fJXK1520829861
		Application ID	
Was this a major release as defined by 19.15.29.7(A) NMAC? Yes No If YES, was immediate no No , we did not notify the	If YES, for what reason(s) does the responsible par otice given to the OCD? By whom? To whom? Wh e OCD .		
The responsible	Initial Respons party must undertake the following actions immediately unless the		uld result in injury
The source of the rele	ease has been stopped.		
The impacted area ha	s been secured to protect human health and the envir	onment.	
Released materials ha	ave been contained via the use of berms or dikes, abs	orbent pads, or other containm	ent devices.
	ecoverable materials have been removed and manage		
•	d above have <u>not</u> been undertaken, explain why:	······································	
If all the actions described	a above have <u>not</u> been undertaken, explain why.		

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name:Shaina Rojas	Title: Environmentalist Specialist
Signature: <i>Signature:S</i>	Date: 6/27/2023
email:Shaina_rojas@oxy.com	Telephone432-448-6693
OCD Only	

5

Received by OCD: 6/27/2023 6:44:03 PM Form C-141 State of New Mexico

Page 6

Oil Conservation Division

	Page 3 of 5
Incident ID	nAPP2317834814
District RP	
Facility ID	fJXK1520829861
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.		
A scaled site and sampling diagram as described in 19	.15.29.11 NMAC	
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
Laboratory analyses of final sampling (Note: appropria	ate ODC District office must be notified 2 days prior to final sampling)	
Description of remediation activities		
and regulations all operators are required to report and/or fil may endanger public health or the environment. The accept should their operations have failed to adequately investigate human health or the environment. In addition, OCD accepta compliance with any other federal, state, or local laws and/o restore, reclaim, and re-vegetate the impacted surface area to	complete to the best of my knowledge and understand that pursuant to OCD rules e certain release notifications and perform corrective actions for releases which rance of a C-141 report by the OCD does not relieve the operator of liability e and remediate contamination that pose a threat to groundwater, surface water, ance of a C-141 report does not relieve the operator of responsibility for or regulations. The responsible party acknowledges they must substantially to the conditions that existed prior to the release or their final land use in to the OCD when reclamation and re-vegetation are complete.	
Signature: <i>Shaina Rojas</i>	Date:6/27/2023	
email: Shaina_rojas@oxy.com Telephone:	432-448-6693	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by:	Date:	
Printed Name:	Title:	

Compressor went down on high discharge temperature nAPP2317834814



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	233590
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By Condition scwells None

CONDITIONS

Action 233590

Condition Date

6/28/2023

Released to Imaging: 6/28/2023 10:30:44 AM