e of New Mexico

Incident ID nAPP2300446864

Incident ID	nAPP2300446864
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following iter	ms must be included in the closure report.
A scaled site and sampling diagram as described in 19.15.29.11	NMAC
Photographs of the remediated site prior to backfill or photos of must be notified 2 days prior to liner inspection)	f the liner integrity if applicable (Note: appropriate OCD District office
Laboratory analyses of final sampling (Note: appropriate ODC I	District office must be notified 2 days prior to final sampling)
☐ Description of remediation activities	
and regulations all operators are required to report and/or file certain remay endanger public health or the environment. The acceptance of a should their operations have failed to adequately investigate and reme human health or the environment. In addition, OCD acceptance of a compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the conductor accordance with 19.15.29.13 NMAC including notification to the OCI. Printed Name: Melodie Sanjari Signature: Melodie Sanjari	C-141 report by the OCD does not relieve the operator of liability diate contamination that pose a threat to groundwater, surface water, C-141 report does not relieve the operator of responsibility for ons. The responsible party acknowledges they must substantially itions that existed prior to the release or their final land use in D when reclamation and re-vegetation are complete. Title: Environmental Professional Date: 3/6/2023
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
OCD Only	
Received by: Robert Hamlet	Date: 7/6/2023
	Cliability should their operations have failed to adequately investigate and ster, human health, or the environment nor does not relieve the responsible regulations.
Closure Approved by: Robert Hamlet	Date:7/6/2023
Printed Name: Robert Hamlet	Title: Environmental Specialist - Advanced

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2300446864
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

(NAD 83 in decimal degrees to 5 decimal places)

Site Name BI	LACK RIVE	ER 15 10 STATE 3	ЗН7Н ТВ		Site Type Oil & Gas Facili	ty	
Date Release Discovered: 1/4/2023		fAPP2125247203					
Unit Letter	Section	Township	Range		County]	
О	15	24S	27E	Edd	y		
Surface Owner: State Federal Tribal Private (Name:)							

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)			
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)	
Produced Water	Volume Released (bbls) 15.1	Volume Recovered (bbls) 15.1	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	⊠ Yes □ No	
Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)	
Cause of Release			

A pinhole in the 4" 90 upstream of the tank inlet line resulted in the release of just over 15 bbl. of produced water within the lined secondary containment. Because the depth of the fluid was too shallow to recover, it's being removed during the pressure washing process. A notice will be sent out prior to a liner integrity inspection.

023 8:19:08 AM, Page 3 of 11

Incident ID	nAPP2300446864
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the respons	sible party consider this a major release?
release as defined by	, , , , , , , , , , , , , , , , , , , ,	ı J
19.15.29.7(A) NMAC?		
☐ Yes ⊠ No		
If YES, was immediate no	otice given to the OCD? By whom? To who	m? When and by what means (phone, email, etc)?
	Initial Re	sponse
The responsible j	party must undertake the following actions immediately	unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.	
The impacted area ha	s been secured to protect human health and t	he environment.
Released materials ha	ave been contained via the use of berms or di	kes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and	managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain w	hy:
		mediation immediately after discovery of a release. If remediation fforts have been successfully completed or if the release occurred
		ease attach all information needed for closure evaluation.
		est of my knowledge and understand that pursuant to OCD rules and
		cations and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have
failed to adequately investig	ate and remediate contamination that pose a threa	to groundwater, surface water, human health or the environment. In
and/or regulations.	f a C-141 report does not refleve the operator of re	esponsibility for compliance with any other federal, state, or local laws
Printed Name: Mel	odie Sanjari	Title: Environmental Professional
		Title
Signature: Melod	<u>lie Sanjari</u>	Date: 1/4/2023
email: <u>msanjari@mara</u>	thonoil.com_	Telephone: <u>575-988-8753</u>
OCD Only		
-		Deter
Received by:		Date:

e of New Mexico

Incident ID nAPP2300446864

Incident ID	nAPP2300446864
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following item	s must be included in the closure report.		
✓ A scaled site and sampling diagram as described in 19.15.29.11 NMAC			
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)			
☐ Description of remediation activities			
and regulations all operators are required to report and/or file certain remay endanger public health or the environment. The acceptance of a C should their operations have failed to adequately investigate and remediuman health or the environment. In addition, OCD acceptance of a C compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the conditaccordance with 19.15.29.13 NMAC including notification to the OCD	C-141 report by the OCD does not relieve the operator of liability liate contamination that pose a threat to groundwater, surface water, -141 report does not relieve the operator of responsibility for ns. The responsible party acknowledges they must substantially tions that existed prior to the release or their final land use in 0 when reclamation and re-vegetation are complete.		
Printed Name: Melodie Sanjari	Title: Environmental Professional		
Signature: <u>Melodie Sanjari</u>	Date: 3/6/2023		
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>		
OCD Only			
Received by:	Date:		
	liability should their operations have failed to adequately investigate and er, human health, or the environment nor does not relieve the responsible regulations.		
Closure Approved by:	Date:		
Printed Name:	Title:		

Sanjari, Melodie (MRO)

From: Sanjari, Melodie (MRO)

Sent: Thursday, February 23, 2023 1:19 PM **To:** OCDOnline@state.nm.us; Mann, Ryan

Subject: Liner Inspection - Marathon Oil - nAPP2234045568 & nAPP2300446864

Good Afternoon,

Please let this email serve as notice for a liner integrity inspection to take place at the Black River 15 10 State Com 3H 7H CTB to close out incidents nAPP2234045568 & nAPP2300446864. The inspection will take place the morning of Monday, February 27th, please reach out if you plan on attending.

Thank you.

Melodie Sanjari

Environmental Professional Permian & Oklahoma 575-988-8753



Liner Integrity Inspection (Photos Attached)	
Date: 2/27/2023	
Facility: Black River 34 7H CTB	
48 Hour Notification Given On: $2/23/2023$	
Responsible party has visually inspected the liner	(V)N
Liner remains intact	Ø⁄N
Liner had the ability to contain the leak in question:	(y/N
Notes:	
pressure washed	
no rips or tears existing patches in good shafe.	


Company Representative(s)


Melodie Sanjari

Received by OCD: 3/6/2023 8:19:08 AM













District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 193342

CONDITIONS

Operator:	OGRID:	
MARATHON OIL PERMIAN LLC	372098	
990 Town & Country Blvd.	Action Number:	
Houston, TX 77024	193342	
	Action Type:	
	[C-141] Release Corrective Action (C-141)	

CONDITIONS

rhamlet	We have received your closure report and final C-141 for Incident #NAPP2300446864 BLACK RIVER 15 10 STATE 3H7H TB, thank you. This closure is approved.	7/6/2023
Created By	Condition	Condition Date