State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	nAPP2319230011
District RP	
Facility ID	fJXK1521644806
Application ID	

Release Notification

Responsible Party

Responsible Party OXY USA	OGRID 16696
Contact Name Shaina Rojas	Contact Telephone 432-448-6693
Contact email Shaina_rojas@oxy.com	Incident
Contact mailing address 1600 Gehrig Dr. Midland TX 79706	

Location of Release Source

Latitude 32.7065

Longitude -103.162

(NAD 83 in decimal degrees to 5 decimal places)

Site Name North Hobbs Unit CTB		Site Type Central Tank Battery
Date Release Discovered	06/27/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
L	33	18S	38E	Lea

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe) Carbon Dioxide	Volume/Weight Released (provide units) 120MCF	Volume/Weight Recovered (provide units) 0MCF

Gas plant pressured up caused compressor to go down on hi discharge

e 2		ico	Incident ID	nAPP2319230011
	Oil Conservation Div	vision		
			District RP	
			Facility ID	fJXK1521644806
			Application ID	
Vas this a major elease as defined by 9.15.29.7(A) NMAC?	If YES, for what reason(s) does	he responsible party consider	r this a major releas	e?
Yes⊠ No				
f YES, was immediate not not if yes in the not in the no	otice given to the OCD? By whon OCD .	n? To whom? When and by	what means (phone	, email, etc)?
	Ini	tial Response		
The responsible	party must undertake the following actions	immediately unless they could creat	te a safety hazard that wo	ould result in injury
\boxtimes The source of the rele	ease has been stopped.			
	is been secured to protect human h	ealth and the environment		
-	•			
	ave been contained via the use of b	erms or dikes, absorbent pad	s, or other containm	lent devices.
All free liquids and r				
	ecoverable materials have been rer	noved and managed appropri-	ately.	
	ecoverable materials have been rer d above have <u>not</u> been undertaken,		ately.	
			ately.	
			ately.	
			ately.	
•			ately.	
			ately.	
•			ately.	
If all the actions described Per 19.15.29.8 B. (4) NM has begun, please attach		explain why: numence remediation immedia remedial efforts have been su	ately after discovery	ed or if the release occurred
Fer 19.15.29.8 B. (4) NM has begun, please attach within a lined containmer I hereby certify that the info regulations all operators are public health or the environ failed to adequately investig	d above have <u>not</u> been undertaken, IAC the responsible party may con a narrative of actions to date. If n	explain why: mmence remediation immedia remedial efforts have been su (MAC), please attach all info ete to the best of my knowledge elease notifications and perform rt by the OCD does not relieve th pose a threat to groundwater, sur	ately after discovery accessfully complet rmation needed for and understand that p corrective actions for he operator of liability face water, human hea	ed or if the release occurred closure evaluation. pursuant to OCD rules and releases which may endanger y should their operations have alth or the environment. In
If all the actions described Per 19.15.29.8 B. (4) NM has begun, please attach within a lined containmer I hereby certify that the info regulations all operators are public health or the environn failed to adequately investig addition, OCD acceptance o and/or regulations.	d above have <u>not</u> been undertaken, IAC the responsible party may con a narrative of actions to date. If n nt area (see 19.15.29.11(A)(5)(a) N rmation given above is true and compl required to report and/or file certain ro nent. The acceptance of a C-141 repo ate and remediate contamination that p	explain why: mmence remediation immedia remedial efforts have been su (MAC), please attach all info ete to the best of my knowledge elease notifications and perform rt by the OCD does not relieve th pose a threat to groundwater, sur perator of responsibility for com	ately after discovery accessfully complet rmation needed for and understand that p corrective actions for he operator of liability face water, human hea pliance with any other	ed or if the release occurred closure evaluation. pursuant to OCD rules and releases which may endanger y should their operations have alth or the environment. In
If all the actions described Per 19.15.29.8 B. (4) NM has begun, please attach within a lined containmer I hereby certify that the info regulations all operators are public health or the environn failed to adequately investig addition, OCD acceptance o and/or regulations. Printed Name:Shaina	d above have <u>not</u> been undertaken, IAC the responsible party may con a narrative of actions to date. If n at area (see 19.15.29.11(A)(5)(a) N rmation given above is true and compl required to report and/or file certain ro nent. The acceptance of a C-141 repo ate and remediate contamination that p f a C-141 report does not relieve the o	explain why: mence remediation immedia remedial efforts have been su (MAC), please attach all info ete to the best of my knowledge clease notifications and perform rt by the OCD does not relieve th sose a threat to groundwater, sur perator of responsibility for com Title: Environmentalist Sp	ately after discovery accessfully complet rmation needed for and understand that p corrective actions for he operator of liability face water, human hea pliance with any other	ed or if the release occurred closure evaluation. pursuant to OCD rules and releases which may endanger y should their operations have alth or the environment. In

Received by: <u>Shelly Wells</u>

Received by OCD: 7/11/2023 12:09:37 PM Form C-141 State of New Mexico

Page 6

Oil Conservation Division

	Page 3 of 5
Incident ID	nAPP2319230011
District RP	
Facility ID	fJXK1521644806
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

<u>Closure Report Attachment Checklist</u>: Each of the following item	s must be included in the closure report.	
A scaled site and sampling diagram as described in 19.15.29.11 N	IMAC	
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
Description of remediation activities		
I hereby certify that the information given above is true and complete to and regulations all operators are required to report and/or file certain re may endanger public health or the environment. The acceptance of a C should their operations have failed to adequately investigate and remed human health or the environment. In addition, OCD acceptance of a C compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the condit accordance with 19.15.29.13 NMAC including notification to the OCD Printed Name:Shaina Rojas	lease notifications and perform corrective actions for releases which -141 report by the OCD does not relieve the operator of liability iate contamination that pose a threat to groundwater, surface water, -141 report does not relieve the operator of responsibility for ns. The responsible party acknowledges they must substantially ions that existed prior to the release or their final land use in when reclamation and re-vegetation are complete.	
Signature: <i>Shaina Rojas</i>	Date:7/11/2023	
email: Shaina_rojas@oxy.com Telephone: 432-448-66	593	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by: Shelly Wells	Date:7/11/2023	
Printed Name:Shelly Wells		



Gas plant pressured up caused compressor to go down on hi discharge

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	238510
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By Condition

CO2 release. Closure approved. scwells

CONDITIONS

Action 238510

Condition Date

7/11/2023