<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2319849332
District RP	
Facility ID	fJXK1520829861
Application ID	

# **Release Notification**

## **Responsible Party**

Responsible Party OXY USA	OGRID 16696
Contact Name Shaina Rojas	Contact Telephone 432-448-6693
Contact email Shaina_rojas@oxy.com	Incident
Contact mailing address 1600 Gehrig Dr. Midland TX 79706	

## **Location of Release Source**

Latitude	32.680192	Longitude-103.115965
		(NAD 83 in decimal degrees to 5 decimal places)

Site Name South Hobbs CTB		Site Type Central Tank F	Battery			
Date Release Discovered 06/26/2023				API# (if applicable)		
Unit Letter	Section	Township	Range		County	
A	11	19S	38E	Lea		

Surface Owner	·· I   State	Federal Tr	ihal IXI Private (/	Vame:	`
Surface Owner	. Dianc		Ivai Tiraic (1	vanie.	

Nature and Volume of Release					
Mater	ial(s) Released (Select all that apply and attach calculations or specif	ic justification for the volumes provided below)			
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)			
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)			
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No			
Condensate	Volume Released (bbls)	Volume Recovered (bbls)			
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)			
Other (describe)	Volume/Weight Released (provide units) 128MCF	Volume/Weight Recovered (provide units) 0MCF			
Carbon Dioxide					
Compressor went down	n cooler fan vibration due to hailstorm and rain storn	1			

Page 2 of 5

Incident ID	nAPP2319849332
District RP	
Facility ID	fJXK1520829861
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?
19.15.29.7(A) NMAC?	
☐ Yes⊠ No	
If VES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
No, we did not notify the	
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
l <u> </u>	s been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NM	AC the responsible party may commence remediation immediately after discovery of a release. If remediation
has begun, please attach	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger
public health or the environr	nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have
addition, OCD acceptance of	ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	
Printed Name:Shaina	Rojas Title: Environmentalist Specialist
Signature: Shair	na Rojas Date: 7/15/2023
email:Shaina_rojas@	oxy.com Telephone432-448-6693
OCD Only	
Received by: Shelly Well	S Date: 7/17/2023

ate of New Mexico

Incident ID NAPP2319849332

Incident ID	nAPP2319849332
District RP	
Facility ID	fJXK1520829861
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must	be included in the closure report.		
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC			
Photographs of the remediated site prior to backfill or photos of the lines must be notified 2 days prior to liner inspection)	r integrity if applicable (Note: appropriate OCD District office		
☐ Laboratory analyses of final sampling (Note: appropriate ODC District o	ffice must be notified 2 days prior to final sampling)		
☐ Description of remediation activities			
I hereby certify that the information given above is true and complete to the be and regulations all operators are required to report and/or file certain release no may endanger public health or the environment. The acceptance of a C-141 reshould their operations have failed to adequately investigate and remediate corn human health or the environment. In addition, OCD acceptance of a C-141 reprompliance with any other federal, state, or local laws and/or regulations. The restore, reclaim, and re-vegetate the impacted surface area to the conditions that accordance with 19.15.29.13 NMAC including notification to the OCD when the Printed Name: Shaina Rojas	otifications and perform corrective actions for releases which port by the OCD does not relieve the operator of liability atamination that pose a threat to groundwater, surface water, port does not relieve the operator of responsibility for responsible party acknowledges they must substantially at existed prior to the release or their final land use in reclamation and re-vegetation are complete.		
Signature: Shaina Rojas	Date:7/15/2023		
email: Shaina_rojas@oxy.com Telephone: 432-448-6693			
OCD Only			
Received by: Shelly Wells Da	ate: 7/17/2023		
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.			
Closure Approved by:	Date:		
Printed Name:	Title:		



Compressor went down cooler fan vibration due to hailstorm and rain storm

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 241075

### **CONDITIONS**

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	241075
	Action Type:
	[C-141] Release Corrective Action (C-141)

### CONDITIONS

Created By		Condition Date
scwells	None	7/17/2023