District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2320629829
District RP	
Facility ID	fJXK1521644806
Application ID	

Release Notification

Responsible Party

Responsible Party	OXY USA		OGRID	16696	
Contact Name Sha	aina Rojas		Contact Teleph	none 432-448-6693	
Contact email	Shaina_rojas@oxy.	com	Incident		
Contact mailing add	ress 1600 Gehrig Dr	. Midland TX 79706			
Location of Release Source					
Latitude 32.7176	Longitude	-103.1775 (NAD 83 in decimal de	grees to 5 decimal pla	aces)	

Site Name North Hobbs Unit CTB		Site Type Central Tank Battery				
Date Release Discovered 7/9/2023		API# (if applicable)				
Unit Letter	Section	Township	Range		County	

L	29	18S	38E	Lea	
Surface Owner	r: State	☐ Federal ☐ Tr	ribal 🛛 Private (1	Name:)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil Volume Released (bbls) Volume Recovered (bbls) Produced Water Volume Released (bbls) Volume Recovered (bbls) Is the concentration of dissolved chloride in the ☐ Yes ☐ No produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) ■ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Volume/Weight Released (provide units) Other (describe) Volume/Weight Recovered (provide units) 101MCF 0MCF Carbon Dioxide

Calculation:

Total Flared Volume 126MCF; Co2 80.49% total Co2 Volume is MCF101

HC Volume 19.51%=24mcf

this was just a gas release to the emergency flare and NO liquids spilled .

After repairs on the seal and belt were completed last night they started compressor and it went down on hi lube oil differential Pressure. They then went to the warehouse and were able to get new filters to replace used ones. Wells were already down but we were bumping flare

73	-		
Paga		0	r 1
Page	- 44	v_{I}	U

Incident ID	nAPP2320629829
District RP	
Facility ID	fJXK1521644806
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
☐ Yes⊠ No	
If YES, was immediate no No , we did not notify the	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? OCD.
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
☐ The impacted area ha	s been secured to protect human health and the environment.
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions described	d above have not been undertaken, explain why:
Per 19.15.29.8 B. (4) NM	AC the responsible party may commence remediation immediately after discovery of a release. If remediation
within a lined containmen	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environmental failed to adequately investigations.	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name:Shaina	Rojas Title: Environmentalist Specialist
Signature: Shair	na Rojas Date: 7/25/2023
email:Shaina_rojas@	
OCD Only	
Received by: Shelly We	Date: <u>7/25/2023</u>

Page 3 of 5

Incident ID	nAPP2320629829
District RP	
Facility ID	fJXK1521644806
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items mu	st be included in the closure report.				
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC					
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)					
☐ Laboratory analyses of final sampling (Note: appropriate ODC Distric	t office must be notified 2 days prior to final sampling)				
☐ Description of remediation activities					
I hereby certify that the information given above is true and complete to the and regulations all operators are required to report and/or file certain release may endanger public health or the environment. The acceptance of a C-141 should their operations have failed to adequately investigate and remediate a human health or the environment. In addition, OCD acceptance of a C-141 compliance with any other federal, state, or local laws and/or regulations. Trestore, reclaim, and re-vegetate the impacted surface area to the conditions accordance with 19.15.29.13 NMAC including notification to the OCD when the Printed Name:Shaina Rojas	e notifications and perform corrective actions for releases which report by the OCD does not relieve the operator of liability contamination that pose a threat to groundwater, surface water, report does not relieve the operator of responsibility for the responsible party acknowledges they must substantially that existed prior to the release or their final land use in en reclamation and re-vegetation are complete. Title: Environmentalist Specialist				
email: Shaina_rojas@oxy.com Telephone: 432-448-6693					
OCD Only					
Received by: Shelly Wells	Date: <u>7/25/2023</u>				
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.					
Closure Approved by: Shelly Wells	Date: 7/25/2023				
Printed Name: Shelly Wells	Title: Environmental Specialist-Advanced				

After repairs on the seal and belt were completed last night they started compressor and it went down on hi lube oil dp. They then went to the warehouse and were able to get new filters to replace used ones. Wells were already down but we were bumping flare



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 243941

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	243941
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
scwells	CO2 release. Closure approved.	7/25/2023