## **Closure Report**

#### ID #nJMW1402934481

Site Description		
Site Name:	MCKRITTRICK 24 FEDERAL #001H	
Company:	Oxy USA, Inc.	
Legal Description:	U/L O ,S13, 22S ,24E,	
County:	EDDY	
GPS Coordinates:	N 32.385934,W-104.448783	

Release Data		
Date of Release:	12/25/2013	
Type of Release:	OIL, PRODUCED WATER	
Source of Release:	TRANSFER PUMP	
Volume of Release:	35 BBLS OIL , 30BBLS WATER	
Volume Recovered:	30 BBLS OIL , 30 BBLS WATER	

Remediation Specifications				
Remediation Parameters:	This site is listed on the Agreed Compliance Order of 4/5/19. This site had previously been remediated but apparently no paperwork exists on the NMOCD website for closure verification. Therefore, OXY is submitting documentation that verifies remediation was conducted, the liner was inspected and verified for integrity and completed per OCD regulations.			
Plan Sent to OCD:				
OCD Approval of Plan:				
Plan Sent to BLM:				
BLM Approval of Plan:				

Supporting Documentation			
C-141, page 6	signed and included		
Site Diagram	Google Earth map		
Pictures	Closure photos		
Liner Inspection	Liner inspection form		
Notifications	7/14/2023		

### **Request for Closure**

Based on the completion of the remediation, OXY requests closure approval from the NMOCD.

Cliff P. Brunson President, BBC International, Inc.

7/28/2023

Form C-141	State of New Mexico	Incident ID	nJMW1402934481
D (	Oil Commention District	Incident ID	11310100 1402934461
Page 6	Oil Conservation Division	District RP	1
		Facility ID	1
		Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must	be included in the closure report.
A scaled site and sampling diagram as described in 19.15.29.11 NMAC	
Photographs of the remediated site prior to backfill or photos of the line must be notified 2 days prior to liner inspection)	er integrity if applicable (Note: appropriate OCD District office
Laboratory analyses of final sampling (Note: appropriate ODC District of	office must be notified 2 days prior to final sampling)
Description of remediation activities	
I hereby certify that the information given above is true and complete to the be and regulations all operators are required to report and/or file certain release in may endanger public health or the environment. The acceptance of a C-141 re should their operations have failed to adequately investigate and remediate co- human health or the environment. In addition, OCD acceptance of a C-141 re compliance with any other federal, state, or local laws and/or regulations. The restore, reclaim, and re-vegetate the impacted surface area to the conditions the accordance with 19.15.29.13 NMAC including notification to the OCD when Printed Name: Wade Dittrich Signature: Wade Dittrich email: wade_dittrich@oxy.com Telephon	otifications and perform corrective actions for releases which eport by the OCD does not relieve the operator of liability ntamination that pose a threat to groundwater, surface water, port does not relieve the operator of responsibility for e responsible party acknowledges they must substantially at existed prior to the release or their final land use in
OCD Only Received by: D	
	ate:
Closure approval by the OCD does not relieve the responsible party of liability remediate contamination that poses a threat to groundwater, surface water, hum party of compliance with any other federal, state, or local laws and/or regulation $\frac{1}{2}$	an health, or the environment nor does not relieve the responsible
Closure Approved by: Buttan Hall	Date: 7/31/2023
Printed Name: Brittany Hall	Title: Environmental Specialist

Cliff P. Brunson
<u>"OCD.Enviro@emnrd.nm.gov"</u>
Wade Dittrich; Tyson Pierce; Jennifer Gilkey; Kathy Sweeney
OXY - McKittrick 24 Federal #001H (12/25/13) ACO - Liner Inspection Notification
Friday, July 14, 2023 11:31:00 AM

This is a notification that the liner at the McKittrick 24 Federal #001H (12/25/13) ACO (**Incident #nJMW1402934481**) is ready for inspection on Tuesday, July 18 at 12:00 p.m. The liner has been inspected for integrity.

Cliff P. Brunson, CEI, CRS President BBC International, Inc. World-Wide Environmental Specialists Mailing Address: P. O. Box 805 Hobbs, NM 88241-0805 USA Shipping Address: 1324 W. Marland St. Hobbs, NM 88240 USA Phone: (575) 397-6388 Fax: (575) 397-0397 E-Mail: correspondence.



Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

From:	Wells, Shelly, EMNRD
To:	Cliff P. Brunson
Cc:	Bratcher, Michael, EMNRD; Hamlet, Robert, EMNRD
Subject:	RE: [EXTERNAL] OXY - McKittrick 24 Federal #001H (12/25/13) ACO - Liner Inspection Notification
Date:	Friday, July 14, 2023 1:25:27 PM

Good afternoon Cliff,

Please be aware that notification requirements are **two business days**, per rule. You may proceed on your schedule. This, and all correspondence, should be included in the closure report to insure inclusion in the project file.

Sincerely,

Shelly

Shelly Wells \* Environmental Specialist-Advanced Administrative Permitting Program EMNRD-Oil Conservation Division 1220 S. St. Francis Drive|Santa Fe, NM 87505 (505)469-7520<u>|Shelly.Wells@emnrd.nm.gov</u> http://www.emnrd.state.nm.us/OCD/

From: Cliff P. Brunson <cbrunson@bbcinternational.com>
Sent: Friday, July 14, 2023 11:31 AM
To: Enviro, OCD, EMNRD <OCD.Enviro@emnrd.nm.gov>
Cc: Wade Dittrich <Wade\_Dittrich@oxy.com>; Tyson Pierce <tyson\_pierce@oxy.com>; Jennifer
Gilkey <jgilkey@bbcinternational.com>; Kathy Sweeney <kathys@bbcinternational.com>
Subject: [EXTERNAL] OXY - McKittrick 24 Federal #001H (12/25/13) ACO - Liner Inspection
Notification

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

This is a notification that the liner at the McKittrick 24 Federal #001H (12/25/13) ACO (**Incident #nJMW1402934481**) is ready for inspection on Tuesday, July 18 at 12:00 p.m. The liner has been inspected for integrity.

Cliff P. Brunson, CEI, CRS President BBC International, Inc. World-Wide Environmental Specialists Mailing Address: P. O. Box 805



BBC International, Inc. PO Box 805 Hobbs, NM 88241

575-397-6388

# **Liner Inspection Report**

Operator:	OXY			
Site Name:	McKittrick 24 Fed	eral #001H		
Leak Date:	12/25/2013			
Inspection Date:	7/18/2023			
Inspection Results:	7/18/2023			
	Liner Intergity:	Good X	Bad	
	Debris Removal:	Yes x	No	
Remediation Activi	ties:			
	Gravel Removal:	Yes X	No	
	Power Wash:	Yes	No	
Closure Photos:	X			
Inspected By:	Beto Martinez		Date:	7/18/2023











































District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	245498
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By		Condition Date
bhall	None	7/31/2023

Page 14 of 14

Action 245498