District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2322956610
District RP	
Facility ID	FAPP2301259449
Application ID	

Release Notification

Responsible Party

Dagmangilala	Doutre				OGRID		-	-
Responsible Party Matador Resources				228937				
Contact Name Clinton Talley			Contact Te	elephone 337-	-319-8398			
Contact email clinton.talley@matadorresources.com			Incident #	(assigned by OCD)	NAPP2322956610			
Contact mailing address 5347 N. 26th Street 2nd Floor, Ar			tesia, NM 8	8210				
			Location	of R	Release So	ource		
Latitude 32.	57778		(NAD 83 in de	cimal de	Longitude _ egrees to 5 decim	-103.67142 nal places)		
Site Name Pony Express Fed West Facility Tank Battery			Site Type					
Date Release Discovered 8/16/2023			API# (if app	licable)				
Unit Letter	G 4:	Tr 1'	D		C	4		
	Section	Township	Range	1.	Coun	ity	-	
L	16	20S	33E	Lea				
Surface Owner	Surface Owner: ☐ State ☐ Federal ☐ Tribal ☐ Private (Name:) Nature and Volume of Release							
Crude Oil		Volume Released	***	i calculat	tions or specific	Volume Recov	volumes provided below) vered (bbls)	
☐ Produced	Water	Volume Released (bbls) 10			Volume Recov	. ,		
		Is the concentration of dissolved chlorid produced water >10,000 mg/l?		e in the	Yes No	·		
Condensa Condensa	te	Volume Release	ed (bbls)			Volume Recov	vered (bbls)	
Natural G	as	Volume Release	ed (Mcf)			Volume Recov	vered (Mcf)	
Other (de	scribe)	Volume/Weight	Released (provid	e units))	Volume/Weig	ght Recovered (provide	e units)
Cause of Rel	ease	1						
	Lir	ne failure						

Page 2 of 7

Incident ID	NAPP2322956610
District RP	
Facility ID	FAPP2301259449
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respon	sible party consider this a major release?
☐ Yes ☑ No		
If YES, was immediate no	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial Ro	esponse
The responsible	party must undertake the following actions immediatel	vunless they could create a safety hazard that would result in injury
✓ The source of the rele	ease has been stopped.	
☑ The impacted area ha	s been secured to protect human health and	the environment.
✓ Released materials has	ave been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.
☑ All free liquids and re	ecoverable materials have been removed and	l managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain	vhy:
Per 10 15 20 8 R (A) NIM	AC the responsible party may commence r	emediation immediately after discovery of a release. If remediation
has begun, please attach	a narrative of actions to date. If remedial	efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
		pest of my knowledge and understand that pursuant to OCD rules and
public health or the environr	nent. The acceptance of a C-141 report by the C	Scations and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have
		at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name: Clinton	Talley	Title: EHS
Signature: Clint	Talley	Date:8/21/2023
email: clinton.talley@	matadorresources.com	Telephone: 337-319-8398
OCD Only		
Received by: Shelly We	ells	Date: 8/21/2023

f New Mexico Incident ID NAPP2322956610

Incident ID	NAPP2322956610
District RP	
Facility ID	FAPP2301259449
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring well Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody	ls.	

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 8/21/2023 9:10:59 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 o	f 7
Incident ID	NAPP2322956610	
District RP		
Facility ID	FAPP2301259449	
Application ID		

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thr addition, OCD acceptance of a C-141 report does not relieve the operator o and/or regulations.	tifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have reat to groundwater, surface water, human health or the environment. In
Printed Name:	
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Received by OCD: 8/21/2023 9:10:59 AM Form C-141 State of New Mexico Page 5 Oil Conservation Division

	Page 5 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must b	e included in the plan.
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation poin □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29. □ Proposed schedule for remediation (note if remediation plan times) 	12(C)(4) NMAC
<u>Deferral Requests Only</u> : Each of the following items must be con	nfirmed as part of any request for deferral of remediation.
Contamination must be in areas immediately under or around predeconstruction.	roduction equipment where remediation could cause a major facility
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
☐ Approved ☐ Approved with Attached Conditions of	Approval
Signature:	Date:

by OCD: 8/21/2023 9:10:59 AM Page 6 of 7

Incident ID	NAPP2322956610
District RP	
Facility ID	FAPP2301259449
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

NMAC
f the liner integrity if applicable (Note: appropriate OCD District office
District office must be notified 2 days prior to final sampling)
to the best of my knowledge and understand that pursuant to OCD rules release notifications and perform corrective actions for releases which C-141 report by the OCD does not relieve the operator of liability ediate contamination that pose a threat to groundwater, surface water, C-141 report does not relieve the operator of responsibility for ons. The responsible party acknowledges they must substantially ditions that existed prior to the release or their final land use in D when reclamation and re-vegetation are complete.
Title:
Date:
Telephone:
Date:
f liability should their operations have failed to adequately investigate and ater, human health, or the environment nor does not relieve the responsible regulations.
ater, human health, or the environment nor does not relieve the responsible

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 254675

CONDITIONS

Operator:	OGRID:
MATADOR PRODUCTION COMPANY	228937
One Lincoln Centre	Action Number:
Dallas, TX 75240	254675
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created by		Condition Date
scwells	None	8/21/2023