

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party TAP ROCK OPERATING, LLC	OGRID 372043
Contact Name CHRISTIAN COMBS	Contact Telephone (720)360-4028
Contact email ccombs@taprk.com	Incident # <i>(assigned by OCD)</i>
Contact mailing address 523 Park Point Dr. #200	Golden CO, 80401

Location of Release Source

Latitude **32.109260** Longitude **-103.305429**
(NAD 83 in decimal degrees to 5 decimal places)

Site Name BLUE MARLIN FEDERAL COM #212H	Site Type PRODUCTION
Date Release Discovered 09/21/2023	API# <i>(if applicable)</i> 30-025-49196

Unit Letter	Section	Township	Range	County
N	19	25S	36E	LEA COUNTY

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☒ Produced Water	Volume Released (bbls) 86.91BBLS	Volume Recovered (bbls) 75BBLS
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☒ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

HOSE ON THE H-PUMP SPLIT AFTER AN ELECTRICAL POWER SURGE OCCURRED ON LOCATION. WELL WAS SHUT IN AND A VACUUM TRUCK WAS DISPATCHED AND STANDING FLUID WAS RECOVERED.

Form C-141

State of New Mexico

Oil Conservation Division

Page 2

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?

☒ Yes ☐ No

If YES, for what reason(s) does the responsible party consider this a major release?
VOLUME OF RELEASE

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

EMAIL WAS SENT TO THE OCD, BRATCHER, HAMLET, HARIMON, BLM AT 10:53AM, BY NATALIE GLADDEN (ESS) BY EMAIL

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Natalie Gladden Title: Director of Environmental and Regulatory

Signature:  Date: 9/27/23

email: natalie@energystaffingllc.com Telephone: 575-390-6397

OCD Only

Received by: _____ Date: _____

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party TAP ROCK OPERATING, LLC	OGRID 372043
Contact Name CHRISTIAN COMBS	Contact Telephone (720)360-4028
Contact email ccombs@taprk.com	Incident # <i>(assigned by OCD)</i>
Contact mailing address 523 Park Point Dr. #200	Golden CO, 80401

Location of Release Source

Latitude **32.109260** Longitude **-103.305429**
(NAD 83 in decimal degrees to 5 decimal places)

Site Name BLUE MARLIN FEDERAL COM #212H	Site Type PRODUCTION
Date Release Discovered 09/21/2023	API# <i>(if applicable)</i> 30-025-49196

Unit Letter	Section	Township	Range	County
N	19	25S	36E	LEA COUNTY

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☒ Produced Water	Volume Released (bbls) 86.91BBLS	Volume Recovered (bbls) 75BBLS
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☒ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

HOSE ON THE H-PUMP SPLIT AFTER AN ELECTRICAL POWER SURGE OCCURRED ON LOCATION. WELL WAS SHUT IN AND A VACUUM TRUCK WAS DISPATCHED AND STANDING FLUID WAS RECOVERED.

Form C-141

State of New Mexico

Oil Conservation Division

Page 2

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?

☒ Yes ☐ No

If YES, for what reason(s) does the responsible party consider this a major release?
VOLUME OF RELEASE

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

EMAIL WAS SENT TO THE OCD, BRATCHER, HAMLET, HARIMON, BLM AT 10:53AM, BY NATALIE GLADDEN (ESS) BY EMAIL

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury


- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Natalie Gladden Title: Director of Environmental and Regulatory

Signature:  Date: 9/27/23

email: natalie@energystaffingllc.com Telephone: 575-390-6397

OCD Only

Received by: Scott Rodgers Date: 09/27/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 269738

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 269738
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scott.rodgers	None	9/27/2023