District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Page 1 of 5

Incident ID	nAPP2326965347
District RP	
Facility ID	fAPP2125238645
Application ID	

# **Release Notification**

### **Responsible Party**

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

#### **Location of Release Source**

Latitude 32.2106117

Longitude-104.1807023

(NAD 83 in decimal degrees to 5 decimal places)

Site Name BLACK RIVER 374 STATE TB	Site Type Oil & Gas Facility
Date Release Discovered: 9/25/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
Ν	15	24S	27E	Eddy

Surface Owner: State Federal Tribal Private (Name: \_

## Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 505	Volume Recovered (bbls) 505
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Failure on a collar on water tank resulted in the release of approx. 505 bbl. of produced water within the lined, secondary containment. Source was isolated. Fluid recovered. Notice will be sent out prior to liner integrity inspection.

ceived by OCD: 9/28/202	3 8:50:01 AM State of New Mexico		Page 2
1111 (-141		Incident ID	nAPP2326965347
ge 2	Oil Conservation Division	District RP	
		Facility ID	
		Application ID	
Was this a major release as defined by 19.15.29.7(A) NMAC? Yes No	If YES, for what reason(s) does the responsible par Volume	ty consider this a major release	?
If YES, was immediate n Yes, NOR was submitted	otice given to the OCD? By whom? To whom? Wh 19/26/23. Initial Respons	- u	email, etc)?

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\boxtimes$  The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: <u>Melodie Sanjari</u>	Title: <u>Environmental Professional</u>
Signature: <u>Melodie Sanjari</u>	Date: 9/28/2023
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
OCD Only Scott Rodgers Received by:	Date:09/28/2023

<b>Received by OCD:</b>	9120	12023	0:30:01 AM
-------------------------	------	-------	------------

MARATHON	11.00 <sup>17</sup> 0.000.0	29-26-23
	a, Mar	ESTERM
Black Marg 574 Blace No. 00 534 5895 125		11.00 ···
DRIVER TO 1	6.00 TICA 000 0000	0 00000 0 00000
5895 125	6.00 TICA 000 0000	- 11.00

AGAVE

Manoraen	NUMER -		09-	26-28
	44 10.000000		EG	race
Elect Diver 374 Star	1166 A	CPAR 1	Ø/spc	
5895 mil 125 11.00	0.10		3:30	0.4.6
5895 125 11.00	0	10 100 C	3:30	0.44 #10
DRIVER TO LOUDINGA TRING WATER FROM	2	100 Tall (0)	3:30	0.44 
DRIVER TO LOISTICA	2	- 0 10	3:30	0

AGAVE 523780 MARATHON 09-26-23 ESTERAN Mel ALANA DISPOSE " Black Khok WXY 3H 5895 60 Belo 3,30 ..... O compress O consent 0 m 41 ORIVER TO LOCATION TARING WATER FROM TO DEPESAL 100 310 MLS JOB SAFETY ANALYSIS 15.15 HAS

NOEL Y HERIBERTO 15.15- HES 12. HRS

310 8845 195 8845

TOTAL 5 27 tos 15 min

505 NOLS

ALPHA NGC - TICKOT # 22571

ink activity (Stani Toe Bosta) to work safety and severe weather rd, Cold days - sufficient codring.

Harre(N)				
		-		-
	 _			-
	 			-
	 -			
1				
(c)arear	 land in			
		_	_	-

Released to Imaging: 9/28/2023 9:27:23 AM

AGAVE 100 W Durick Rd. Cardinator No.			
C 1000 W Destrict Rd Control of the		- 51	8409
A CARDON NO. CARDON NO	220		
Marce thom		9-2	6-23
Inara mom	a service	ONDERAGE BY	
PROM Brack River 10 A	11pha s.	w.D	NGI
une State 2427-15 3H 0m	O AATTENY O C		FLOW BACK
1400 00 4705 MOLANT 120 DIANT THE 8:50 00	U PHO TIME	2:10	OAM TH
Work in the location	5,20-		AMOUNT
	Fille		
Container arter 125 bbls			
to Disposal	Prev.		
	CR		
		BUB TOTAL	
- AN.			
Marathon reader	22572	9-2	6/2:
U MAMER		DADENED BY	
DOLIVERO Black River TO Al	phas.	w. 5 1	VAL
LEASE 5,8,10 0.00	O BATTERY O CO	MPLETON O	FLOWBACK
UNTINO: 4705 MILLED 70 STANT THE 2:10 000	DOTME	8:52	O AM
work in the location	7,40	RATE	AMOUNT
addin in the total for	FW		-
Cleining Container and	BW		
Se Die State	PW-		
70 bb/s OF Water to	CRE		
70 bb/s OF Water to	Market States		
Disposal Water to			
To pois of water to Disposal B:40		BLB TOTAL	1
JOB SAFETY ANALYSIS 5:20	125	BLØ TOTAL SXX TOTAL	
JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS HAZARDS AND CONTROLS (Check Those That Apply:)	125	105AL	
JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS HAZARDS AND CONTROLS (Check Those That Apply:)	70	105AL	001
JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS TA HRJ HAZARDS AND CONTROLS (Check Those That Apply:) Falling Hazards: Head Protection (Hard Hat) Feet (Steel Toe Boots). Airborne Particulates: Safety Glasses.	70	105AL	BC J
JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS TALKS HAZARDS AND CONTROLS (Check Those That Apply:) Falling Hazards: Head Protection (Hard Hat) Feet (Steel Toe Boots). Airborne Particulates: Safety Glasses. Hand Protection: Work Gloves.	125 70 1957	105AL	3BLJ
FO bbl's F Water to   Disposal 5:20   JOB SAFETY ANALYSIS 5:20   HAZARDS AND CONTROLS (Check Those That Apply:)   Falling Hazards: Head Protection (Hard Hat) Feet (Steel Toe Boots).   Falling Hazards: Head Protection (Hard Hat) Feet (Steel Toe Boots).   Falling Hazards: Safety Glasses.   Hand Protection: Work Gloves.   H2S / Gases LEL: H2S Monitor	-70 1957	105AL	BC J
JOB SAFETY ANALYSIS JOB SAFETY ANALYSIS HAZARDS AND CONTROLS (Check Those That Apply:)	-70 1957	105AL	BBC J
How point Filling   HAZARDS AND CONTROLS (Check Those That Apply:)   HAZARDS AND CONTROLS (Check Those That Apply:)   Hailing Hazards: Head Protection (Hard Hat) Feet (Steel Toe Boots).   Hand Protection: Work Gloves.   HAZARDS LEL: H2S Monitor   Fire Hazard: Clothing (FR), Fire Extinguisher on Truck/Trailer and Locat   Hearing Protection: Ear Plugs (if Posted on Location or Noisy Area).   Slip or Trip Hazards: Maintain a clean work area before and during work	70 1957 ion. x activity. (Steel Too	TOOL D	BC J
How point How point   Hearing Protection: Ear Plugs (if Posted on Location or Noisy Area).	70 1957 son. k activity (Steel Tor p work safety.	TOOL D	3BLJ

Rec

New or Other Hazards	reamine(s) or
eleased to Imaging: 9/28/2023 9:27:23 AM	
Working on the location	

.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	269915
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By		Condition Date
scott.rodgers	None	9/28/2023

Page 5 of 5

Action 269915