

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	nAPP2328345879
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party	Earthstone Operating, LLC	OGRID	331165
Contact Name	Chris Martin	Contact Telephone	432-253-9998 Ext. 2653
Contact email	cmartin@earthstoneenergy.com	Incident # (assigned by OCD)	
Contact mailing address	600 N. Marienfeld, Suite 1000, Midland, TX 79701		

### Location of Release Source

Latitude 32.486196 Longitude -103.445067  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Outland 14-23 State 2BS #2H	Site Type	Well Pad
Date Release Discovered	9/25/2023	API# (if applicable)	30-025-44157

Unit Letter	Section	Township	Range	County
D	14	21S	34E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) <u>1</u>	Volume Recovered (bbls) <u>0</u>
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) <u>9</u>	Volume Recovered (bbls) <u>2</u>
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release The release occurred when a suction hose detached from a pump due to the hose not being rated for the vessel which was rated for 250 PSI. The valve was shut for the vessel and pump and the hose was replaced with steel pipe. A vacuum truck was called, and free liquids were recovered.

## Oil Conservation Division

Incident ID	nAPP2328345879
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?          
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?          	

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:          	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Rebecca Haskell</u>	Title: <u>Senior Project Manager</u>
Signature: <u>Rebecca Haskell</u>	Date: <u>10/10/2023</u>
email: <u>bhaskell@ntglobal.com</u>	Telephone: <u>432-766-1918</u>
<b><u>OCD Only</u></b>	
Received by: <u>Shelly Wells</u>	Date: <u>10/11/2023</u>

## \*\*\*\*\* LIQUID SPILLS - VOLUME CALCULATIONS \*\*\*\*\*

Location of spill: Outland 14-23 State 2BS #2H

Date of Spill: 25-Sep-2023

If the leak/spill is associated with production equipment, i.e. - wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here: ☒

## Input Data:

If spill volumes from measurement, i.e. metering, tank volumes, etc. are known enter the volumes here: OIL: BBL WATER: BBL

If "known" spill volumes are given, input data for the following "Area Calculations" is optional. The above will override the calculated volumes.

## Total Area Calculations

Total Surface Area	width	length	wet soil depth	oil (%)
Rectangle Area #1	230 ft	104 ft	X 0.2 in	13%
Rectangle Area #2	0 ft	0 ft	X 0.0 in	0%
Rectangle Area #3	0 ft	0 ft	X 0 in	0%
Rectangle Area #4	0 ft	0 ft	X 0 in	0%
Rectangle Area #5	0 ft	0 ft	X 0 in	0%
Rectangle Area #6	0 ft	0 ft	X 0 in	0%
Rectangle Area #7	0 ft	0 ft	X 0 in	0%
Rectangle Area #8	0 ft	0 ft	X 0 in	0%

## Standing Liquid Calculations

Standing Liquid Area	width	length	liquid depth	oil (%)
Rectangle Area #1	0 ft	0 ft	X 0 in	0%
Rectangle Area #2	0 ft	0 ft	X 0 in	0%
Rectangle Area #3	0 ft	0 ft	X 0 in	0%
Rectangle Area #4	0 ft	0 ft	X 0 in	0%
Rectangle Area #5	0 ft	0 ft	X 0 in	0%
Rectangle Area #6	0 ft	0 ft	X 0 in	0%
Rectangle Area #7	0 ft	0 ft	X 0 in	0%
Rectangle Area #8	0 ft	0 ft	X 0 in	0%

okay

## production system leak - DAILY PRODUCTION DATA REQUIRED

Average Daily Production: Oil 0 BBL Water 0 BBL 0 Gas (MCFD)

Total Hydrocarbon Content in gas: 0% (percentage)

Did leak occur before the separator?: ☒ YES ☒ N/A (place an "X")

H2S Content in Produced Gas: 0 PPM

H2S Content in Tank Vapors: 0 PPM

Amount of Free Liquid Recovered: 0 BBL okay

Percentage of Oil in Free Liquid Recovered: 0% (percentage)

Liquid holding factor \*: 0.14 gal per gal

Use the following when the spill wets the grains of the soil.

Use the following when the liquid completely fills the pore space of the soil:

\* Sand = 0.08 gallon (gal.) liquid per gal. volume of soil.

Occurs when the spill soaked soil is contained by barriers, natural (or not).

\* Gravelly (caliche) loam = 0.14 gal. liquid per gal. volume of soil.

\* Clay loam = 0.20 gal. liquid per gal. volume of soil.

\* Sandy clay loam soil = 0.14 gal liquid per gal. volume of soil.

\* Gravelly (caliche) loam = 0.25 gal. liquid per gal. volume of soil.

\* Clay loam = 0.16 gal. liquid per gal. volume of soil.

\* Sandy loam = 0.5 gal. liquid per gal. volume of soil.

Total Solid/Liquid Volume: 23,805 sq. ft. 278 cu. ft. 40 cu. ft.

Total Free Liquid Volume: sq. ft. cu. ft. cu. ft.

## Estimated Volumes Spilled

	H2O	OIL
Liquid in Soil:	7 BBL	1 BBL
Free Liquid:	0 BBL	0.0 BBL
Totals:	7 BBL	1 BBL

Total Liquid Spill Liquid: 7 BBL 1 BBL

## Recovered Volumes

Estimated oil recovered: BBL check - okay  
Estimated water recovered: BBL check - okay

## Estimated Production Volumes Lost

	H2O	OIL
Estimated Production Spilled:	0.0 BBL	0.0 BBL

## Estimated Surface Damage

Surface Area: 23,805 sq. ft.

Surface Area: .5465 acre

## Estimated Weights, and Volumes

Saturated Soil = 35,549 lbs 317 cu. ft. 12 cu. yds.  
Total Liquid = 8 BBL 332 gallon 2,765 lbs

## Air Emission from flowline leaks:

Volume of oil spill: - BBL  
Separator gas calculated: - MCF  
Separator gas released: - MCF  
Gas released from oil: - lb  
H2S released: - lb  
Total HC gas released: - lb  
Total HC gas released: - MCF

## Air Emission of Reporting Requirements:

New Mexico  
HC gas release reportable? NO  
H2S release reportable? NO  
Texas  
NO  
NO

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 274235

CONDITIONS

Operator: Earthstone Operating, LLC 1400 Woodloch Forest; Ste 300 The Woodlands, TX 77380	OGRID: 331165
	Action Number: 274235
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	10/11/2023