

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	nAPP2328531507
District RP	
Facility ID	fAPP2202645940
Application ID	

Release Notification

Responsible Party

Responsible Party: Cimarex Energy Co. of Colorado	OGRID: 162683
Contact Name: Laci Luig	Contact Telephone: (432) 571-7800
Contact email: laci.luig@coterra.com	Incident # (assigned by OCD) nAPP2328531507
Contact mailing address: 6001 Deauville Blvd., Suite 300N Midland, TX 79706	

Location of Release Source

Latitude 32.10872 _____ Longitude -104.26883 _____
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Pintail 23 Federal Com 8H	Site Type: Battery
Date Release Discovered: 10/10/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
M	23	25S	26E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 128	Volume Recovered (bbls) 105
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Equipment Failure

A ½" nipple downstream of the water transfer meter broke, releasing a total of 128 barrels produced water into the gravel lined containment. All fluids remained inside the containment and were recovered. A liner inspection will be scheduled.

Released: 128 barrels produced water (gravel lined containment)

Recovered: 105 barrels produced water

Incident ID	nAPP2328531507
District RP	
Facility ID	fAPP2202645940
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Total amount of release greater than 25 barrels
---	---

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
 By: Laci Luig
 To: OCD Enviro, BLM
 By: Email

Initial Response


The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
--

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Laci Luig _____ Title: ESH Specialist _____
 Signature:  _____ Date: 10/12/2023 _____
 email: laci.luig@coterra.com _____ Telephone: (432) 208-3035 _____

OCD Only
 Received by: Shelly Wells _____ Date: 10/12/2023 _____

***** LIQUID SPILLS - VOLUME CALCULATIONS *****

Location of spill: Pintail 23 Federal Com 8H

Date of Spill: 10/10/2023

If the leak/spill is associated with production equipment, i.e. - wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here:

Input Data:

If spill volumes from measurement, i.e. metering, tank volumes, etc. are known enter the volumes here: **OIL:** 0.0000 BBL **WATER:** 0.0000 BBL

If "known" spill volumes are given, input data for the following "Area Calculations" is optional. The above will override the calculated volumes.

Total Area Calculations					Standing Liquid Calculations				
Total Surface Area	width	length	wet soil depth	oil (%)	Standing Liquid Area	width	length	liquid depth	oil (%)
Rectangle Area #1	0 ft X	0 ft X	0 in	0%	Rectangle Area #1	8 ft X	35 ft X	8 in	0%
Rectangle Area #2	0 ft X	0 ft X	0 in	0%	Rectangle Area #2	8 ft X	34 ft X	8 in	0%
Rectangle Area #3	0 ft X	0 ft X	0 in	0%	Rectangle Area #3	8 ft X	75 ft X	7 in	0%
Rectangle Area #4	0 ft X	0 ft X	0 in	0%	Rectangle Area #4	0 ft X	0 ft X	0 in	0%
Rectangle Area #5	0 ft X	0 ft X	0 in	0%	Rectangle Area #5	0 ft X	0 ft X	0 in	0%
Rectangle Area #6	0 ft X	0 ft X	0 in	0%	Rectangle Area #6	0 ft X	0 ft X	0 in	0%
Rectangle Area #7	0 ft X	0 ft X	0 in	0%	Rectangle Area #7	0 ft X	0 ft X	0 in	0%
Rectangle Area #8	0 ft X	0 ft X	0 in	0%	Rectangle Area #8	0 ft X	0 ft X	0 in	0%

Saturated Soil Volume Calculations:				Free Liquid Volume Calculations:			
Total Solid/Liquid Volume:	sq. ft.	H2O cu. ft.	OIL cu. ft.	Total Free Liquid Volume:	1,152 sq. ft.	H2O 718.000 cu. ft.	OIL .000 cu. ft.
Estimated Volumes Spilled				Estimated Production Volumes Lost			
Liquid in Soil:		H2O 0.0 BBL	OIL 0.0 BBL	Estimated Production Spilled:		H2O 0.000000 BBL	OIL 0.000000 BBL
Free Liquid:		127.9 BBL	0.0 BBL	Estimated Surface Damage			
Totals:		127.872 BBL	0.000 BBL	Surface Area:	1,152 sq. ft.		
Total Liquid Spill Liquid:		127.872 BBL	0.000 BBL	Surface Area:	.0264 acre		
Recovered Volumes				Estimated Weights, and Volumes			
Estimated oil recovered:	0.0 BBL	check - okay		Saturated Soil =	lbs	cu.ft.	cu.yds.
Estimated water recovered:	0.0 BBL	check - okay		Total Liquid =	128 BBL	5,370.64 gallon	44,684 lbs



CIMAREX ENERGY
PINTAIL 23 FEDERAL COM 8H
EDDY, NM





CIMAREX ENERGY
PINTAIL 23 FEDERAL COM 8H
EDDY, NM





CIMAREX ENERGY
PINTAIL 23 FEDERAL COM 8H
EDDY, NM



District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 275060

CONDITIONS

Operator: CIMAREX ENERGY CO. OF COLORADO 6001 Deauville Blvd, Ste 300N Midland, TX 79706	OGRID: 162683
	Action Number: 275060
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	10/12/2023