District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Latitude 32.7176 Longitude

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2329042809
District RP	
Facility ID	fJXK1521644806
Application ID	

Release Notification

Responsible Party

Responsible Party OXY USA	OGRID 16696	
Contact Name Shaina Rojas	Contact Telephone 432-448-6693	
Contact email Shaina_rojas@oxy.com	Incident	
Contact mailing address 1600 Gehrig Dr. Midland TX 79706		
Location of Release Source		

			(NAD 83 in de	ecimal de	grees to 5 decimal places)	
Site Name	North Hobbs	Unit NIB			Site Type Central Tank E	Battery
Date Release	Discovered	9/2	6/2023		API# (if applicable)	
Unit Letter	Section	Township	Range		County	
L	29	18S	38E	Lea		

Surface Owner: State Federal Tribal Private (Name:

-103.1775

Nature and Volume of Release

	l(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)			
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)			
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)			
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No			
Condensate	Volume Released (bbls)	Volume Recovered (bbls)			
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)			
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)			
Carbon Dioxide	66MCF	0MCF			
Calculation :		 -			
	MCF; Co2 80.49% total Co2 Volume is MCF66				
HC Volume 19.51%=15.9					
this was just a gas releas	se to the emergency flare and NO liquids spilled.				
We had a power blink at	We had a power blink at the battery that knocked the compressor down				

- 73			-		•
\boldsymbol{P}	$\alpha \alpha$	a	٠,	0.1	
	42	C	4	\boldsymbol{v}	٠.

Incident ID	nAPP2329042809
District RP	
Facility ID	fJXK1521644806
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
☐ Yes⊠ No	
If YES, was immediate no No , we did not notify the	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? OCD.
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
☐ The source of the rele	ase has been stopped.
☐ The impacted area has	s been secured to protect human health and the environment.
Released materials ha	ve been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and re	coverable materials have been removed and managed appropriately.
If all the actions described	l above have <u>not</u> been undertaken, explain why:
has begun, please attach a	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred t area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environn failed to adequately investigated to adequate the state of the	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have atte and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name:Shaina	Rojas Title: Environmentalist Specialist
Signature: Shain	va Rojas Date 10/17/2023
email:Shaina_rojas@	oxy.com Telephone432-448-6693
OCD Only	
Received by: Shelly Well	S Date: 10/18/2023

Page 3 of 5

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items mus	st be included in the closure report.	
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of the lin must be notified 2 days prior to liner inspection)	ner integrity if applicable (Note: appropriate OCD District office	
Laboratory analyses of final sampling (Note: appropriate ODC District	office must be notified 2 days prior to final sampling)	
Description of remediation activities		
I hereby certify that the information given above is true and complete to the and regulations all operators are required to report and/or file certain release may endanger public health or the environment. The acceptance of a C-141 should their operations have failed to adequately investigate and remediate chuman health or the environment. In addition, OCD acceptance of a C-141 compliance with any other federal, state, or local laws and/or regulations. Trestore, reclaim, and re-vegetate the impacted surface area to the conditions accordance with 19.15.29.13 NMAC including notification to the OCD when Printed Name:Shaina Rojas	notifications and perform corrective actions for releases which report by the OCD does not relieve the operator of liability ontamination that pose a threat to groundwater, surface water, report does not relieve the operator of responsibility for the responsible party acknowledges they must substantially that existed prior to the release or their final land use in a reclamation and re-vegetation are complete. Title: Environmentalist Specialist Date: 10/17/2023	
och o I		
OCD Only		
Received by: Shelly Wells	Date: <u>10/18/2023</u>	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by: Shelly Wells	Date: 10/18/2023	
Printed Name: _Shelly Wells	Title: _Environmental Specialist-Advanced	

We had a power blink at the battery that knocked the compressor down



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 276475

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294 Houston, TX 772104294	Action Number: 276475
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	CO2 release. Closure approved.	10/18/2023