District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2330654483
District RP	
Facility ID	fKJ1518128159
Application ID	

Release Notification

Responsible Party

Responsible Party OXY USA	OGRID 16696
Contact Name Shaina Rojas	Contact Telephone 432-448-6693
Contact email Shaina_rojas@oxy.com	Incident
Contact mailing address 1600 Gehrig Dr. Midland TX 79706	

Location of Release Source

Latitude 32.7065	Longitude -103.162
------------------	--------------------

(NAD 83 in decimal degrees to 5 decimal places)

			(NAD 03 in at	cimui ue	grees to 5 decimal places)		
Site Name	North Hobbs	s Unit NIB			Site Type Central Tank I	Battery	
Date Release	Discovered	09	/26/2023		API# (if applicable)		
Unit Letter	Section	Township	Range		County		
e	33	18S	38E	Lea	<u> </u>	1	
Surface Owner: State Federal Tribal Private (Name:)					.)		
Nature and Volume of Release							

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)				
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)		
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)		
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No		
Condensate	Volume Released (bbls)	Volume Recovered (bbls)		
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)		
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)		
Carbon Dioxide	274MCF	0MCF		

Calculation:

Total Flared Volume 291MCF; Co2 90.46% total Co2 Volume is MCF274

HC Volume 5.54%=16mcf

this was just a gas release to the emergency flare and NO liquids spilled .

We had a power blink at the battery knocking the compressor down. The power came back up shortly, however the compressor would not start. Had to have compressor mechanics and automation troubleshoot. Hey had to make adjustments to the lube oil dp. We had a small flare during this time

Page 2 of	٠,
	4

Incident ID	nAPP2330654483
District RP	
Facility ID	fKJ1518128159
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	NO
☐ Yes⊠ No	
If YES, was immediate no No , we did not notify the	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? OCD.
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
☐ The impacted area ha	s been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain why:
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the info	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name:Shaina	Rojas Title: Environmentalist Specialist
Signature: Shair	na Rojas Date 11/2/2023
email:Shaina_rojas@	oxy.com Telephone432-448-6693
OCD Only	
Received by: Shelly We	Date: <u>11/2/2023</u>

nAPP2330654483

Incident ID District RP Facility ID fKJ1518128159 Application ID

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.			
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMA	С		
Photographs of the remediated site prior to backfill or photos of the limust be notified 2 days prior to liner inspection)	ner integrity if applicable (Note: appropriate OCD District office		
Laboratory analyses of final sampling (Note: appropriate ODC Distric	t office must be notified 2 days prior to final sampling)		
Description of remediation activities			
I hereby certify that the information given above is true and complete to the and regulations all operators are required to report and/or file certain release may endanger public health or the environment. The acceptance of a C-141 should their operations have failed to adequately investigate and remediate human health or the environment. In addition, OCD acceptance of a C-141 compliance with any other federal, state, or local laws and/or regulations. Trestore, reclaim, and re-vegetate the impacted surface area to the conditions accordance with 19.15.29.13 NMAC including notification to the OCD who Printed Name:Shaina Rojas	e notifications and perform corrective actions for releases which report by the OCD does not relieve the operator of liability contamination that pose a threat to groundwater, surface water, report does not relieve the operator of responsibility for The responsible party acknowledges they must substantially that existed prior to the release or their final land use in the reclamation and re-vegetation are complete. Title: Environmentalist Specialist Date: 11/2/2023		
email: Shaina_rojas@oxy.com Telephone: 432-448-6693			
OCD Only			
Received by: Shelly Wells	Date: 11/2/2023		
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.			
Closure Approved by: Shelly Wells	Date: 11/2/2023		
Printed Name: _Shelly Wells	Title: Environmental Specialist-Advanced		

We had a power blink at the battery knocking the compressor down. The power came back up shortly, however the compressor would not start. Had to have compressor mechanics and automation troubleshoot. Hey had to make adjustments to the lube oil dp. We had a small flare during this time



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 282291

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	282291
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	/ Condition	Condition Date
scwells	CO2 release. Closure approved.	11/2/2023