

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

Location of Release Source

Latitude _____ Longitude _____
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input type="checkbox"/> The source of the release has been stopped.	
<input type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: Dale Woodall	Title: Env. Professional
Signature: <u>Dale Woodall</u>	Date: _____
email: dale.woodall@dvn.com	Telephone: 575-748-1838
<u>OCD Only</u>	
Received by: Shelly Wells	Date: 11/7/2023

SUPERVISOR'S REPORT OF EQUIPMENT, ENVIRONMENT, PROPERTY OR AUTO DAMAGE

INCIDENT DATE 10/27/23	INCIDENT TIME 2:10 p.m.	AREA/COUNTRY Lea County, NM	SITE NAME RIG 129	CUSTOMER DEVON	COMPANY REP CHRIS NORTHCUTT
<input type="checkbox"/> EQUIPMENT 12" LAY FLAT HOSE	<input type="checkbox"/> ENVIRONMENT SPILL	<input type="checkbox"/> PROPERTY DEVON	AUTOMOTIVE: N/A		
WERE ANY PERSON(S) INJURED? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> X IF YES, OR POTENTIAL FOR INJURY EXISTS, COMPLETE SUPERVISOR'S ACCIDENT REPORT FOR PERSONAL INJURY OR ILLNESS.			PROPERTY, EQUIPMENT OR ASSET ID NO KRT BACKHOE		
INCIDENT DESCRIPTION (IF ENVIRONMENTAL DAMAGE, GIVE TYPE, EXTENT AND REVIEW OF SPILL RESPONSE AND STATUS)					
Events leading up to and thorough description of the incident (What, When, Where, Who, How): ON 10/27/23 at 2:10 p.m. KRT employee (Edgar Vazquez) was crossing NexGen's 12" lay flat hose without the proper crossing protection (Half-moon). He was crossing caliche with his backhoe because they had started to fill in a hole. In the process of crossing the backhoe created a slash on NexGen's 12" hose causing a spill.					
DID POLICE, PUBLIC AUTHORITY OR OTHER AUTHORITY INVESTIGATE? <input type="checkbox"/> YES <input checked="" type="checkbox"/> X NO			IF YES, PROVIDE DETAILS OR INFORMATION TO SECURE A COPY OF OFFICIAL REPORT BY ATTACHING A COPY TO THIS REPORT.		
Describe an executive summary to explain actions taken by the Area Management team to report to local authorities (What, When, Where, Who, How): The vacuum truck was called to location and recovered 30 BBL. KRT					
NABORS PROPERTY, EQUIPMENT, OR AUTOMOBILE DAMAGE INFORMATION					
IF COMPANY DRIVER WAS INVOLVED, GIVE COMPLETE NAME AND ADDRESS EDGAR VAZQUEZ			IS DAMAGED PROPERTY, EQUIPMENT, OR AUTOMOBILE A TOTAL LOSS? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
1324 BAKER AVENUE			ESTIMATE OF DAMAGE <input type="checkbox"/> \$ 10,000 OR LESS		
BRYAN TX 77803			<input type="checkbox"/> \$ 10,000 - \$50,000		
PHONE NUMBER: 979-229-5686 <input type="checkbox"/>			<input type="checkbox"/> \$ 50,000 OR MORE		
DRIVERS LICENSE & STATE: 27666766 TEXAS			HOW LONG WILL IT TAKE TO REPAIR THE DAMAGES? UNKNOWN		
HAS A SURVEY OF DAMAGE BEEN PERFORMED? <input type="checkbox"/> YES (PROVIDE DETAILS AND/OR REPORT)			230 BBL. Produce water spilled		
<input checked="" type="checkbox"/> NO (WHERE CAN DAMAGES BE SURVEYED?)			30 BBL. Produce water recovered		
CONTACT PERSON AND PHONE No.					
THIRD PARTY PROPERTY, EQUIPMENT, OR AUTOMOBILE DAMAGE INFORMATION					
THIRD PARTY OWNER NAME AND ADDRESS NOEY VAZQUEZ (Noey561@gmail.com)			DESCRIPTION OF PROPERTY, EQUIPMENT OR AUTOMOBILE		
			A. TYPE OF PROPERTY: N/A		
			B. YEAR, MAKE, MODEL: N/A		
			C. VEHICLE I.D. NO.: N/A		
CONTACT PERSON & PHONE No. 979-229-5686					
THIRD PARTY INSURANCE INFORMATION					
THIRD PARTY INSURANCE CO.: N/A				POLICY No.	
CONTACT NAME & PHONE No.					
IF THIRD PARTY DRIVER WAS INVOLVED, GIVE COMPLETE NAME AND ADDRESS.			IS DAMAGED PROPERTY, EQUIPMENT, OR AUTOMOBILE A TOTAL LOSS? <input type="checkbox"/> YES <input type="checkbox"/> NO		
			<input type="checkbox"/> \$ 10,000 OR LESS		
			DAMAGE ESTIMATE <input type="checkbox"/> \$ 10,000 - \$50,000		
PHONE No. DOB			<input type="checkbox"/> \$50,000 OR MORE		
DRIVERS LICENSE & STATE			HOW LONG WILL IT TAKE TO REPAIR DAMAGES?		
HAS A SURVEY OF DAMAGE BEEN PERFORMED? <input type="checkbox"/> YES (PROVIDE DETAILS AND/OR REPORT)					
<input type="checkbox"/> NO (WHERE CAN DAMAGES BE SURVEYED?)					
CONTACT PERSON AND PHONE No.					


WITNESS INFORMATION (COMPLETE HSE-F0053, INTERVIEWER'S NOTES)

WITNESS NAME	ADDRESS	PHONE
JESUS ENRIQUE PIEDRA		940-463-2276
CHRIS NORTHCUTT		575-513-0014

ACKNOWLEDGEMENT	NAME	SIGNATURE	DATE
Reported By:	JESUS ENRIQUE PIEDRA	_____	10/28/2023
Immediate Supervisor	JESUS AVILA	_____	10/28/2023
Site Supervisor	DANIEL AGUAYO	_____	10/28/2023
Superintendent	THEODORE CABRERA	_____	10/28/2023
Area HSE Manager	LUIS ASTRAIN	_____	10/28/2023







-

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 283394

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 283394
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	11/7/2023