District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	nAPP2331245084
District RP	
Facility ID	fJXK1521644806
Application ID	

Release Notification

Responsible Party

Responsible Party OXY USA	OGRID 16696
Contact Name Shaina Rojas	Contact Telephone 432-448-6693
Contact email Shaina_rojas@oxy.com	Incident
Contact mailing address 1600 Gehrig Dr. Midland TX 79706	

Location of Release Source

Latitude 32.7065 Longitude -103.162

(NAD 83 in decimal degrees to 5 decimal places)

Site Name North Hobbs Unit NIB		Site Type Central Tank Battery
Date Release Discovered	09/29/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
Е	33	18S	38E	Lea

Surface Owner: State Federal Tribal Private (Name: _____

Nature and Volume of Release

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe) Carbon Dioxide	Volume/Weight Released (provide units) 296MCF	Volume/Weight Recovered (provide units) 0MCF
HC Volume 19.51%=17 this was just a gas rele Mechanics had to shu	ease to the emergency flare and NO liquids spilled .	ve to lube oil system to make a higher viscosity of lube

<i>eived by OCD: 11/8/202</i> . m C-141	3 12:47:24 PM State of New Mexico		Page
		Incident ID	nAPP2331245084
e 2	Oil Conservation Division	District RP	
	Facility ID	fJXK1521644806	
		Application ID	
Was this a major	If YES, for what reason(s) does the responsible part	ty consider this a major release?	
release as defined by			
19.15.29.7(A) NMAC?	NO		
☐ Yes⊠ No			
If YES, was immediate no	otice given to the OCD? By whom? To whom? Wh	en and by what means (phone.)	email. etc)?
No, we did not notify the			,) :
· · ·			
	Initial Respons	e	

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The impacted area has been secured to protect human health and the environment.

 \boxtimes The source of the release has been stopped.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name:Shaina Rojas	Title: Environmentalist Specialist
Signature: <i>Signature:</i>	Date 11/8/2023
email:Shaina_rojas@oxy.com	Telephone432-448-6693
OCD Only	
Received by: Shelly Wells	Date: 11/8/2023

Page 6

Oil Conservation Division

	Page 3 of
Incident ID	nAPP2331245084
District RP	
Facility ID	fJXK1521644806
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.		
A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
Laboratory analyses of final sampling (Note: appropriate ODC Distr	ict office must be notified 2 days prior to final sampling)	
Description of remediation activities		
I hereby certify that the information given above is true and complete to the and regulations all operators are required to report and/or file certain relear may endanger public health or the environment. The acceptance of a C-14 should their operations have failed to adequately investigate and remediate human health or the environment. In addition, OCD acceptance of a C-14 compliance with any other federal, state, or local laws and/or regulations. restore, reclaim, and re-vegetate the impacted surface area to the condition accordance with 19.15.29.13 NMAC including notification to the OCD we Printed Name:Shaina Rojas	ase notifications and perform corrective actions for releases which 41 report by the OCD does not relieve the operator of liability e contamination that pose a threat to groundwater, surface water, e1 report does not relieve the operator of responsibility for The responsible party acknowledges they must substantially as that existed prior to the release or their final land use in hen reclamation and re-vegetation are complete Title: Environmentalist Specialist	
email: Shaina_rojas@oxy.com Telephone: 432-448-6693		
OCD Only		
Received by: <u>Shelly Wells</u>	Date: <u>11/8/2023</u>	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by: <u>Shelly Wells</u>	Date: <u>11/8/2023</u>	
Printed Name: <u>Shelly Wells</u>	Title: Environmental Specialist-Advanced	

Mechanics had to shutdown lp 4500 compressor to add anti foaming additive to lube oil system to make a higher viscosity of lube oil to prevent mechanical damage to compressor



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	283944
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By Condition

scwells CO2 release. Closure approved.

CONDITIONS

Action 283944

Condition Date

11/8/2023