



November 28, 2023

RE: Release Notification Report for Incident Number nAPP2332538575

Dear Sir or Madam,

As previously communicated, approximately 14.2 barrels of produced water were released within the Pearl Valley area when a road grader contacted a 4" poly produced water line. Twelve barrels of produced water were recovered from the ditch area by vacuum truck. Approximately 66 cubic yards of impacted soil were removed from the ditch area, and an additional 12 cubic yards were removed from the area adjacent to the roadway. Clean soil was used in the backfilling process.

Should there be questions concerning this submittal or if additional information is required, please advise.

Sincerely,



Rachael Overbey

Director - Operations Planning & Regulatory

Franklin Mountain Energy LLC

44 Cook Street, Suite 1000

Denver, CO 80206

Main: 720.414.7868

Mobile: 303.570.4057

roverbey@fme LLC.com

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2332538575
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Franklin Mountain Energy 3, LLC	OGRID: 331595
Contact Name: Rachael Overbey	Contact Telephone: 720-414-7868
Contact email: roverbey@fmccl.com	Incident # nAPP2332538575
Contact mailing address: 44 Cook Street, Suite 1000; Denver, CO 80206	

Location of Release Source

Latitude 32.6829411° Longitude -103.4675554°
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: CABLE 19 35 9 STATE COM #001H Well Site	Site Type: Produced Water Line
Date Release Discovered: 11/21/2023	API# (if applicable): 30-025-46140

Unit Letter	Section	Township	Range	County
M	4	19S	35E	Lea

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)


<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 14.2	Volume Recovered (bbls) 12
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units):	Volume/Weight Recovered (provide units):

Cause of Release: During road grading operations, a 4" poly produced water line, residing on the surface, was hit, causing the release of an estimated 14.2 barrels of produced water. Approximately 12 barrels of produced water were recovered from the ditch by vacuum truck. Approximately 66 cubic yards of impacted soil were removed from the ditch, and another 12 cubic yards were removed from the area adjacent to the roadway. Clean soil was used to backfill the impacted areas.

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Rachael Overbey</u> Title: <u>Director – Operations Planning and Regulatory</u> Signature:  Date: <u>11/28/2023</u> email: <u>roverbey@fmcflc.com</u> Telephone: <u>720-414-7868</u>
<u>OCD Only</u> Received by: <u>Shelly Wells</u> Date: <u>11/29/2023</u>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 289324

CONDITIONS

Operator: Franklin Mountain Energy 3, LLC 44 Cook Street Denver, CO 80206	OGRID: 331595
	Action Number: 289324
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	12/1/2023