

Meter: Cadillac Discharge

Meter Data	
Flow Rate:	54,661.3 mcf/d
Static Pressure:	1,150.5 psia
Diff Pressure:	172.7 inH2O
Temperature:	120.9 F
Tdy Volume:	6,829.6 mcf
Ydy Volume:	63,148.7 mcf
Accum Volume:	994,978.7 mcf
Uncorrected Flow Rate:	
Tdy Uncorrected Volume:	
Ydy Uncorrected Volume:	
Accum Uncorrected Vol:	
Energy Flow Rate:	71,318.6 mmbtuh
Tdy Energy:	8,910.8 mmbtu
Ydy Energy:	82,392.4 mmbtu
Accumulated Energy:	1,298,185.0 mmbtu
Mass Flow Rate:	3,154,104.0 lbm/h
Tdy Mass:	394,083.8 lbm
Ydy Mass:	3,643,849.0 lbm
Accumulated Mass:	57,412,940.0 lbm
Absolute Press Dwnstrm:	
Pulse Count:	
Orifice Diameter:	4.25 in
Pipe Diameter:	6.063 in

Gas Quality	
Methane:	76.947 %
CO2:	0.133 %
Ethane:	11.828 %
Hexane:	0.916 %
Iso-Butane:	0.770 %
Iso-pentane:	0.440 %
Nitrogen:	1.039 %
N-Butane:	1.823 %
N-Pentane:	0.505 %
Propane:	5.600 %
BTU Content:	1304.736 MBTU/MCF
Specific Gravity:	0.754 %

Device Data	
Battery Voltage:	14.4 vdc
Contract Hour:	8
Device Address:	56095767
Device Comm ID:	C_COYOTDSCHRG3
Device Enabled:	Y
Device Type:	TotalFlow-G4
Device Time:	11-26-2023 02:10:05

Meter Attributes	
Meter Number:	56095767
Area:	South Carlsbad
System:	Palo Duro
Operator:	Targa Resources

	Lo Limit	Hi Limit
Static Press:	13.0 psia	1,500.0 psia
Temp:	0.3 F	400.0 F
Flow Rate:	0.0 MCFD	420.0 MCFD
Uncorr Vol:	0.0 macf/d	60,000.0 macf/d



Please submit this form by the 5th business day of the month following the month the vent/blowdown occurred. Please submit a separate form for each site. All sections should be filled out by field personnel. **All red fields per event must be entered to calculate volumes correctly!** **All yellow fields should be entered if known for increased accuracy.**

Month Blowdown Occurred	November	Year	2023
Site	AP-Field Pipeline Ops	Employee Name	Jordan Pando

Known (Station) Volumes

All red fields per event must be entered to calculate volumes correctly! All yellow fields should be entered if known for increased accuracy.

Type of Blowdown	Number of Occurrences	Known Volume (MCF) Blowdown	Volume (MCF)
Other (Explain in "Comments")		Multiplied by	Equals
		Multiplied by	Equals
		Multiplied by	Equals

Calculated (Pipeline) Volumes

Blowdown(s)				Purge/Vent			
Reference Meter Number		Blowdown (MCF)		Reference Meter Number		Volume Lost (MCF)	480.28
Pipe ID (in)		Length (Feet)		Beginning Date & Time	11/17/2023 12:30	Vent Duration (Hours)	71.00
Begin Press. (PSIG)		End Press. (PSIG)	0.00	Ending Date & Time	11/20/2023 11:30	Gas Temp	
Gas Temp.		Specific Gravity		Pipe ID (in)	8in Sch. 80	Specific Gravity	
Elevation (ft)				Orifice Size (in)	0.5	Elevation (ft)	
				Avg Pressure	17.00		
Reference Meter Number		Blowdown (MCF)		Reference Meter Number		Volume Lost (MCF)	
Pipe ID (in)		Length (Feet)		Beginning Date & Time		Vent Duration (Hours)	
Begin Press. (PSIG)		End Press. (PSIG)		Ending Date & Time		Gas Temp	
Gas Temp.		Specific Gravity		Pipe ID (in)		Specific Gravity	
Elevation (ft)				Orifice Size (in)		Elevation (ft)	
				Avg Pressure			
Reference Meter Number		Blowdown (MCF)		Reference Meter Number		Volume Lost (MCF)	
Pipe ID (in)		Length (Feet)		Beginning Date & Time		Vent Duration (Hours)	
Begin Press. (PSIG)		End Press. (PSIG)	0.00	Ending Date & Time		Gas Temp	
Gas Temp.		Specific Gravity		Pipe ID (in)		Specific Gravity	
Elevation (ft)				Orifice Size (in)		Elevation (ft)	
				Avg Pressure			

Total Volume (MCF): 480.28

Comments:

11/20/2023 Reporting a vent event at the Cadillac compressor station. Leak has been repaired.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 290225

DEFINITIONS

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 290225
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.
--

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 290225

QUESTIONS

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 290225
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.	
Incident Well	Unavailable.
Incident Facility	[fAPP2123031392] TARGA NORTHERN DELAWARE, LLC.

Determination of Reporting Requirements Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas Please provide the mole percent for the percentage questions in this group.	
Methane (CH4) percentage	77
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 290225

QUESTIONS (continued)

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 290225
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	11/17/2023
Time vent or flare was discovered or commenced	12:30 PM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	11

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Cause: Equipment Failure Gas Compressor Station Natural Gas Vented Released: 74 Mcf Recovered: 0 Mcf Lost: 74 Mcf.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	A poly supply line feeding a PRV on a compressor failed. This caused a compromise of pressure to the valve, and without enough pressure, the valve was unable to seal.
Steps taken to limit the duration and magnitude of vent or flare	Operations responded to troubleshoot the issue once notified of the emissions event. The supply line was replaced as expeditiously as possible.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	The poly supply line was replaced, the PRV was verified to be sealing properly and the emission event ended.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 290225

ACKNOWLEDGMENTS

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 290225
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 290225

CONDITIONS

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 290225
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
amberg	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/1/2023