

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

|                |                |
|----------------|----------------|
| Incident ID    | nAPP2400948698 |
| District RP    |                |
| Facility ID    | fKJ1518128159  |
| Application ID |                |

Release Notification

Responsible Party

|                         |                                  |                   |              |
|-------------------------|----------------------------------|-------------------|--------------|
| Responsible Party       | OXY USA                          | OGRID             | 16696        |
| Contact Name            | Shaina Rojas                     | Contact Telephone | 432-448-6693 |
| Contact email           | Shaina_rojas@oxy.com             | Incident          |              |
| Contact mailing address | 1600 Gehrig Dr. Midland TX 79706 |                   |              |

Location of Release Source

Latitude 32.7065                      Longitude -103.162  
(NAD 83 in decimal degrees to 5 decimal places)

|                         |                 |           |                      |
|-------------------------|-----------------|-----------|----------------------|
| Site Name               | North Hobbs NIB | Site Type | Central Tank Battery |
| Date Release Discovered | 12/16//2023     | API#      | (if applicable)      |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|--------|
| E           | 33      | 18S      | 38E   | Lea    |

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: \_\_\_\_\_)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

|                                                                        |                                                                                |                                                          |
|------------------------------------------------------------------------|--------------------------------------------------------------------------------|----------------------------------------------------------|
| <input type="checkbox"/> Crude Oil                                     | Volume Released (bbls)                                                         | Volume Recovered (bbls)                                  |
| <input type="checkbox"/> Produced Water                                | Volume Released (bbls)                                                         | Volume Recovered (bbls)                                  |
|                                                                        | Is the concentration of dissolved chloride in the produced water >10,000 mg/l? | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| <input type="checkbox"/> Condensate                                    | Volume Released (bbls)                                                         | Volume Recovered (bbls)                                  |
| <input type="checkbox"/> Natural Gas                                   | Volume Released (Mcf)                                                          | Volume Recovered (Mcf)                                   |
| <input checked="" type="checkbox"/> Other (describe)<br>Carbon Dioxide | Volume/Weight Released (provide units)<br>88MCF                                | Volume/Weight Recovered (provide units)<br>0MCF          |

Calculation :

Total Flared Volume 94MCF ; Co2 94.46% total Co2 Volume is MCF88

HC Volume 5.54%=5mcf

this was just a gas release to the emergency flare and NO liquids spilled .

The south plant lost c-train. They had to close their loop line sending all gas to the north. This caused the north plant to pressure up which resulted in our north facilities to pressure up as well. The south lp compressor went down on high high discharge pressure.

This caused us to bump flare intermittently at low volumes

|                |                |
|----------------|----------------|
| Incident ID    | nAPP2400948698 |
| District RP    |                |
| Facility ID    | fKJ1518128159  |
| Application ID |                |

|                                                                                                                                                |                                                                                      |
|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Was this a major release as defined by 19.15.29.7(A) NMAC?<br><br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No          | If YES, for what reason(s) does the responsible party consider this a major release? |
| If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?<br>No, we did not notify the OCD. |                                                                                      |

## Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> The source of the release has been stopped.<br><input type="checkbox"/> The impacted area has been secured to protect human health and the environment.<br><input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.<br><input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| If all the actions described above have <u>not</u> been undertaken, explain why:                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.<br><br>Printed Name: <u>Shaina Rojas</u> Title: <u>Environmental Specialist</u><br><br>Signature: <u>Shaina Rojas</u> Date <u>01/09/2024</u><br><br>email: <u>Shaina_rojas@oxy.com</u> Telephone <u>432-448-6693</u> |
| <b><u>OCD Only</u></b><br><br>Received by: _____ Date: _____                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |

|                |                |
|----------------|----------------|
| Incident ID    | nAPP2400948698 |
| District RP    |                |
| Facility ID    | fKJ1518128159  |
| Application ID |                |

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist: Each of the following items must be included in the closure report.**

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Shaina Rojas Title: Environmental Specialist

Signature: Shaina Rojas Date: 01/09/2024

email: Shaina\_rojas@oxy.com Telephone: 432-448-6693

**OCD Only**


Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: \_\_\_\_\_ Date: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

The south plant lost c-train. They had to close their loop line sending all gas to the north. This caused the north plant to pressure up which resulted in our north facilities to pressure up as well. The south lp compressor went down on high high discharge pressure. This caused us to bump flare intermittently at low volumes



**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS  
  
Action 301742

QUESTIONS

|                                                                               |                |                                                             |
|-------------------------------------------------------------------------------|----------------|-------------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:         | 157984                                                      |
|                                                                               | Action Number: | 301742                                                      |
|                                                                               | Action Type:   | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |
|                                                                               |                |                                                             |

QUESTIONS

|                   |                                                       |
|-------------------|-------------------------------------------------------|
| Prerequisites     |                                                       |
| Incident ID (n#)  | nAPP2400948698                                        |
| Incident Name     | NAPP2400948698 NORTH HOBBS UNIT INJECTION BATTERY @ 0 |
| Incident Type     | Flare                                                 |
| Incident Status   | Remediation Closure Report Received                   |
| Incident Facility | [fKJ1518128159] North Hobbs Unit NIB                  |

|                                                |                                    |
|------------------------------------------------|------------------------------------|
| Location of Release Source                     |                                    |
| Please answer all the questions in this group. |                                    |
| Site Name                                      | North Hobbs Unit Injection Battery |
| Date Release Discovered                        | 12/16/2023                         |
| Surface Owner                                  | Private                            |

|                                                                                                      |       |
|------------------------------------------------------------------------------------------------------|-------|
| Incident Details                                                                                     |       |
| Please answer all the questions in this group.                                                       |       |
| Incident Type                                                                                        | Flare |
| Did this release result in a fire or is the result of a fire                                         | No    |
| Did this release result in any injuries                                                              | No    |
| Has this release reached or does it have a reasonable probability of reaching a watercourse          | No    |
| Has this release endangered or does it have a reasonable probability of endangering public health    | No    |
| Has this release substantially damaged or will it substantially damage property or the environment   | No    |
| Is this release of a volume that is or may with reasonable probability be detrimental to fresh water | No    |

|                                                                                                                                                                                      |                                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| Nature and Volume of Release                                                                                                                                                         |                                                                                                                  |
| Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission. |                                                                                                                  |
| Crude Oil Released (bbls) Details                                                                                                                                                    | Not answered.                                                                                                    |
| Produced Water Released (bbls) Details                                                                                                                                               | Not answered.                                                                                                    |
| Is the concentration of chloride in the produced water >10,000 mg/l                                                                                                                  | No                                                                                                               |
| Condensate Released (bbls) Details                                                                                                                                                   | Not answered.                                                                                                    |
| Natural Gas Vented (Mcf) Details                                                                                                                                                     | Not answered.                                                                                                    |
| Natural Gas Flared (Mcf) Details                                                                                                                                                     | Not answered.                                                                                                    |
| Other Released Details                                                                                                                                                               | Cause: Equipment Failure   Producing Well   Carbon Dioxide   Released: 88 MCF   Recovered: 0 MCF   Lost: 88 MCF. |
| Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)                                 | Not answered.                                                                                                    |

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 301742

**QUESTIONS (continued)**

|                                                                               |                                                                             |
|-------------------------------------------------------------------------------|-----------------------------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                                            |
|                                                                               | Action Number:<br>301742                                                    |
|                                                                               | Action Type:<br>[C-141] Remediation Closure Request C-141 (C-141-v-Closure) |
|                                                                               |                                                                             |

**QUESTIONS**

|                                                                                                                                                                |                                                                                   |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| <b>Nature and Volume of Release (continued)</b>                                                                                                                |                                                                                   |
| Is this a gas only submission (i.e. only significant Mcf values reported)                                                                                      | <b>Yes, according to supplied volumes this appears to be a "gas only" report.</b> |
| Was this a major release as defined by Subsection A of 19.15.29.7 NMAC                                                                                         | <b>No</b>                                                                         |
| Reasons why this would be considered a submission for a notification of a major release                                                                        | <i>Unavailable.</i>                                                               |
| <i>With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.</i> |                                                                                   |

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.*

|                                                                                                                    |                                                                  |
|--------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| The source of the release has been stopped                                                                         | <b>True</b>                                                      |
| The impacted area has been secured to protect human health and the environment                                     | <b>True</b>                                                      |
| Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices | <b>True</b>                                                      |
| All free liquids and recoverable materials have been removed and managed appropriately                             | <b>True</b>                                                      |
| If all the actions described above have not been undertaken, explain why                                           | <b>This was a gas release of CO2 only no liquid was spilled.</b> |

*Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

|                                                    |                                                                                                          |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|
| I hereby agree and sign off to the above statement | Name: Shaina Rojas<br>Title: Specialist Environmental<br>Email: Shaina_rojas@oxy.com<br>Date: 01/09/2024 |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|

**District I**1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720**District II**811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720**District III**1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170**District IV**1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 301742

**QUESTIONS (continued)**

|                                                                               |                |
|-------------------------------------------------------------------------------|----------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:         |
|                                                                               | 157984         |
|                                                                               | Action Number: |
|                                                                               | 301742         |
| Action Type:                                                                  |                |
| [C-141] Remediation Closure Request C-141 (C-141-v-Closure)                   |                |

**QUESTIONS****Site Characterization**

Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

|                                                                                                                            |                                |
|----------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs) | Between 51 and 75 (ft.)        |
| What method was used to determine the depth to ground water                                                                | NM OSE iWaters Database Search |
| Did this release impact groundwater or surface water                                                                       | No                             |
| <b>What is the minimum distance, between the closest lateral extents of the release and the following surface areas:</b>   |                                |
| A continuously flowing watercourse or any other significant watercourse                                                    | Between 1000 (ft.) and ½ (mi.) |
| Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)                                          | Greater than 5 (mi.)           |
| An occupied permanent residence, school, hospital, institution, or church                                                  | Between ½ and 1 (mi.)          |
| A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes  | Between 1000 (ft.) and ½ (mi.) |
| Any other fresh water well or spring                                                                                       | Between ½ and 1 (mi.)          |
| Incorporated municipal boundaries or a defined municipal fresh water well field                                            | Between 1 and 5 (mi.)          |
| A wetland                                                                                                                  | Between 1000 (ft.) and ½ (mi.) |
| A subsurface mine                                                                                                          | Greater than 5 (mi.)           |
| An (non-karst) unstable area                                                                                               | Greater than 5 (mi.)           |
| Categorize the risk of this well / site being in a karst geology                                                           | Low                            |
| A 100-year floodplain                                                                                                      | Between 1 and 5 (mi.)          |
| Did the release impact areas not on an exploration, development, production, or storage site                               | No                             |

**Remediation Plan**

Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

|                                                                                                                                                                                                         |     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| Requesting a remediation plan approval with this submission                                                                                                                                             | Yes |
| Attach a comprehensive report demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC. |     |
| Have the lateral and vertical extents of contamination been fully delineated                                                                                                                            | Yes |
| Was this release entirely contained within a lined containment area                                                                                                                                     | No  |

**Soil Contamination Sampling:** (Provide the highest observable value for each, in milligrams per kilograms.)

|                   |                                    |   |
|-------------------|------------------------------------|---|
| Chloride          | (EPA 300.0 or SM4500 Cl B)         | 0 |
| TPH (GRO+DRO+MRO) | (EPA SW-846 Method 8015M)          | 0 |
| GRO+DRO           | (EPA SW-846 Method 8015M)          | 0 |
| BTEX              | (EPA SW-846 Method 8021B or 8260B) | 0 |
| Benzene           | (EPA SW-846 Method 8021B or 8260B) | 0 |

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, which includes the anticipated timelines for beginning and completing the remediation.

|                                                                             |            |
|-----------------------------------------------------------------------------|------------|
| On what estimated date will the remediation commence                        | 01/09/2024 |
| On what date will (or did) the final sampling or liner inspection occur     | 01/09/2024 |
| On what date will (or was) the remediation complete(d)                      | 01/09/2024 |
| What is the estimated surface area (in square feet) that will be reclaimed  | 0          |
| What is the estimated volume (in cubic yards) that will be reclaimed        | 0          |
| What is the estimated surface area (in square feet) that will be remediated | 0          |
| What is the estimated volume (in cubic yards) that will be remediated       | 0          |

These estimated dates and measurements are recognized to be the best guess or calculation at the time of submission and may (be) change(d) over time as more remediation efforts are completed.

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 4

Action 301742

**QUESTIONS (continued)**

|                                                                               |                |                                                             |
|-------------------------------------------------------------------------------|----------------|-------------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:         | 157984                                                      |
|                                                                               | Action Number: | 301742                                                      |
|                                                                               | Action Type:   | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |
|                                                                               |                |                                                             |

**QUESTIONS****Remediation Plan (continued)**

Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

**This remediation will (or is expected to) utilize the following processes to remediate / reduce contaminants:**

(Select all answers below that apply.)

|                                                                                       |                                                         |
|---------------------------------------------------------------------------------------|---------------------------------------------------------|
| (Ex Situ) Excavation and <b>off-site</b> disposal (i.e. dig and haul, hydrovac, etc.) | Not answered.                                           |
| (Ex Situ) Excavation and <b>on-site</b> remediation (i.e. On-Site Land Farms)         | Not answered.                                           |
| (In Situ) Soil Vapor Extraction                                                       | Not answered.                                           |
| (In Situ) Chemical processing (i.e. Soil Shredding, Potassium Permanganate, etc.)     | Not answered.                                           |
| (In Situ) Biological processing (i.e. Microbes / Fertilizer, etc.)                    | Not answered.                                           |
| (In Situ) Physical processing (i.e. Soil Washing, Gypsum, Disking, etc.)              | Not answered.                                           |
| Ground Water Abatement pursuant to 19.15.30 NMAC                                      | Not answered.                                           |
| OTHER (Non-listed remedial process)                                                   | Yes                                                     |
| Other Non-listed Remedial Process. Please specify                                     | This was a CO2 gas release only NO liquids were spilled |

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, which includes the anticipated timelines for beginning and completing the remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

|                                                    |                                                                                                          |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|
| I hereby agree and sign off to the above statement | Name: Shaina Rojas<br>Title: Specialist Environmental<br>Email: Shaina_rojas@oxy.com<br>Date: 01/09/2024 |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 5  
  
Action 301742

**QUESTIONS (continued)**

|                                                                               |                |
|-------------------------------------------------------------------------------|----------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:         |
|                                                                               | 157984         |
|                                                                               | Action Number: |
|                                                                               | 301742         |
| Action Type:                                                                  |                |
| [C-141] Remediation Closure Request C-141 (C-141-v-Closure)                   |                |

**QUESTIONS**

|                                                                                                                                                                                                |    |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| <b>Deferral Requests Only</b>                                                                                                                                                                  |    |
| Only answer the questions in this group if seeking a deferral upon approval this submission. Each of the following items must be confirmed as part of any request for deferral of remediation. |    |
| Requesting a deferral of the remediation closure due date with the approval of this submission                                                                                                 | No |

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 6

Action 301742

**QUESTIONS (continued)**

|                                                                               |                                                                             |
|-------------------------------------------------------------------------------|-----------------------------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                                            |
|                                                                               | Action Number:<br>301742                                                    |
|                                                                               | Action Type:<br>[C-141] Remediation Closure Request C-141 (C-141-v-Closure) |
|                                                                               |                                                                             |

**QUESTIONS**

| Sampling Event Information                                                                      |            |
|-------------------------------------------------------------------------------------------------|------------|
| Last sampling notification (C-141N) recorded                                                    | 301735     |
| Sampling date pursuant to Subparagraph (a) of Paragraph (1) of Subsection D of 19.15.29.12 NMAC | 12/16/2023 |
| What was the (estimated) number of samples that were to be gathered                             | 0          |
| What was the sampling surface area in square feet                                               | 0          |

**Remediation Closure Request**

Only answer the questions in this group if seeking remediation closure for this release because all remediation steps have been completed.

|                                                                                                                                                                                                                                                                                    |                                                         |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| Requesting a remediation closure approval with this submission                                                                                                                                                                                                                     | Yes                                                     |
| Have the lateral and vertical extents of contamination been fully delineated                                                                                                                                                                                                       | Yes                                                     |
| Was this release entirely contained within a lined containment area                                                                                                                                                                                                                | No                                                      |
| All areas reasonably needed for production or subsequent drilling operations have been stabilized, returned to the sites existing grade, and have a soil cover that prevents ponding of water, minimizing dust and erosion                                                         | Yes                                                     |
| What was the total surface area (in square feet) remediated                                                                                                                                                                                                                        | 0                                                       |
| What was the total volume (cubic yards) remediated                                                                                                                                                                                                                                 | 0                                                       |
| All areas not reasonably needed for production or subsequent drilling operations have been reclaimed to contain a minimum of four feet of non-waste contain earthen material with concentrations less than 600 mg/kg chlorides, 100 mg/kg TPH, 50 mg/kg BTEX, and 10 mg/kg Benzene | Yes                                                     |
| What was the total surface area (in square feet) reclaimed                                                                                                                                                                                                                         | 0                                                       |
| What was the total volume (in cubic yards) reclaimed                                                                                                                                                                                                                               | 0                                                       |
| Summarize any additional remediation activities not included by answers (above)                                                                                                                                                                                                    | N/A this was a CO2 gas release only NO liquids spilled. |

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (in .pdf format) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

|                                                    |                                                                                                          |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|
| I hereby agree and sign off to the above statement | Name: Shaina Rojas<br>Title: Specialist Environmental<br>Email: Shaina_rojas@oxy.com<br>Date: 01/09/2024 |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 7  
  
Action 301742

QUESTIONS (continued)

|                                                                                   |                                                                                 |
|-----------------------------------------------------------------------------------|---------------------------------------------------------------------------------|
| Operator:<br><br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br><br>157984                                                            |
|                                                                                   | Action Number:<br><br>301742                                                    |
|                                                                                   | Action Type:<br><br>[C-141] Remediation Closure Request C-141 (C-141-v-Closure) |
|                                                                                   |                                                                                 |

QUESTIONS

|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| Reclamation Report                                                                    |    |
| Only answer the questions in this group if all reclamation steps have been completed. |    |
| Requesting a reclamation approval with this submission                                | No |

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 301742

CONDITIONS

|                                                                               |                |
|-------------------------------------------------------------------------------|----------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:         |
|                                                                               | 157984         |
|                                                                               | Action Number: |
|                                                                               | 301742         |
| Action Type:<br>[C-141] Remediation Closure Request C-141 (C-141-v-Closure)   |                |

CONDITIONS

| Created By | Condition                      | Condition Date |
|------------|--------------------------------|----------------|
| scwells    | CO2 release. Closure approved. | 1/9/2024       |