

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

PI# 30-015-26407
nLLB0631140464

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Co., LP	6137	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211		Telephone No. 505-748-0160
Facility Name Laguna Salado Fed 1		Facility Type Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	22	23S	29E	2030	North	1980	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 62 bbls	Volume Recovered: 50 bbls
Source of Release: Seal broke	Date and Hour of Occurrence: 3-10-06: 10:30 AM	Date and Hour of Discovery: 3-10-06: 10:30 AM
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Mike Bratcher--OCD	
By Whom? Merle Lewis: Lease Operator	Date and Hour: 3-10-06: 1:36 PM	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Seal on SWD transfer pump ruptured, spilling 62 bbls of produced water into dike. We recovered 50 bbls of produced water. Truck. Replaced seal on pump and discussed incident at safety meeting. Will continue to monitor seals at all transfer pumps.

Describe Area Affected and Cleanup Action Taken.*

Isolated pump and called mechanic & vac. 25' X 100' area affected.

RECEIVED

APR 19 2006

000-ARTESIA

000-ARTESIA

APR 19 2006

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>		OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen		Approved by District Supervisor: TIM GUM by MB <i>Mike Bratcher</i>	
Title: Production Field Tech		Approval Date: <i>4/9/06</i>	Expiration Date:
E-mail Address: jennifer.vancuren@dvn.com		Conditions of Approval:	
Date: 3/20/06	Phone: 748-0160	Attached ☒	

* Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Devon Energy Production Co., LP
P.O. Box 250
Artesia, NM 88211
ATTN: Environmental Department

April 9, 2007

Reference: **Laguna Salado Federal #1 22-23S-29E API # 30-015-26407 Eddy County, New Mexico**

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 reporting a release of produced fluids that occurred on or about March 10, 2006 at the above referenced well site. Please submit a work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD Rules and Guidelines.

A publication outlining OCD guidelines and requirements for site ranking and spill remediation can be found on the OCD website as follows: <http://www.emnrd.state.nm.us/ocd> Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 office no later than May 9, 2007. Please include any remedial or clean up actions that have already been performed.

Remediation requirements may be subject to other federal, state, local laws and/or regulations.

If I can be of assistance in this matter, my contact information is listed below.

Sincerely,

Mike Bratcher

NMOCD District 2

1301 W. Grand Ave.

Artesia, NM 88210

(505) 748-1283 Ext. 108

(505) 626-0857

mike.bratcher@state.nm.us

Tracking number: nLLB0631140464

Oil Conservation Division * 1301 W Grand * Artesia, NM 88210
Phone: (505) 748-1283 * Fax (505) 748-9720 * <http://www.emnrd.state.nm.us>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 374667

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 374667
	Action Type: [REPORT] Alternative Remediation Report (C-141AR)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	8/16/2024