From: Patterson, Heather, EMNRD

To: "taylortaylor16@aol.com"

Cc: <u>Bratcher, Mike, EMNRD; Cordero, Gilbert, EMNRD</u>

Subject: FW: Smith & Marrs

Date: Thursday, November 12, 2015 12:36:00 PM

Ms. Taylor,

Please review the attached pictures. Our field inspector discovered a release on Monday at the Signal State #2. As he stated, the oil may be coming from below ground at this site. The OCD will require a C-141 be turned in for this release as soon as possible. This is to be followed by a remediation plan submitted for OCD approval. Please contact me if you have any questions.

Thank you,

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Cordero, Gilbert, EMNRD


Sent: Monday, November 09, 2015 1:26 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD


Subject: Smith & Marrs

Pics of standing oil around the well head. Appears to be coming from below ground level. Signal State #002 30-015-01901-00-00

Sent from my Verizon Wireless 4G LTE DROID







District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 382982

CONDITIONS

Operator:	OGRID:
SMITH & MARRS INC	20989
P.O. Box 863	Action Number:
Kermit, TX 79745	382982
	Action Type:
	[IM-SD] Incident File Support Doc (ENG) (IM-ANF)

CONDITIONS

Created By	Condition	Condition Date
amaxwe	Historical document upload.	9/12/2024