

From: Patterson, Heather, EMNRD
To: ["Denis Schoenhofer"](#)
Cc: [Bratcher, Mike, EMNRD](#); [Cordero, Gilbert, EMNRD](#); ["Tucker, Shelly"](#); [Bayliss, Randolph, EMNRD](#)
Subject: FW: Agua Sucia
Date: Friday, August 19, 2016 7:58:00 AM
Attachments: ESU 27(1).JPG
ESU 27(2).JPG
ESU 27(3).JPG
ESU 27(4).JPG
ESU 39(1).JPG
ESU 39(2).JPG
ESU 39(3).JPG
ESU 39(4).JPG
ESU 46(1).JPG
ESU 46(2).JPG
ESU 46(3).JPG
ESU 46(4).JPG
ESU 46(5).JPG
ESU 46(6).JPG
ESU 46(7).JPG

Denis,

Please see the attached photos from the East Shugart Unit Wells number 27, 39, and 46. All three of these releases will require a Form C-141 and a work plan, based on analytic data, detailing how Agua Sucia intends to clean them up. Your C-141 is due 15 days from the date of discovery of the release. The BLM is copied in this email since this involves federal lands.

If you have any questions, please contact me.
Thanks,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Cordero, Gilbert, EMNRD
Sent: Thursday, August 18, 2016 3:24 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Agua Sucia

Attached are some pictures of the ESU 27 – Had a release with oil in the cellar.
ESU 39 had a release with staining around location and the well head.
ESU 46 is a starting point. The release is west of location.

Thanks,

Gilbert Cordero
Compliance Officer
NMOCD District II
Office 575.748.1283 ext.114
Cell 575.626.0830









From: [Tucker, Shelly](#)
To: [Patterson, Heather, EMNRD](#)
Cc: [Denis Schoenhofer](#); [Bratcher, Mike, EMNRD](#); [Cordero, Gilbert, EMNRD](#); [Bayliss, Randolph, EMNRD](#)
Subject: Re: FW: Agua Sucia
Date: Friday, August 19, 2016 1:16:57 PM

I recently did an inspection too and I think I have a couple more to add to this list...I was working on sending out the INC's on the ones I found.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

stucker@blm.gov



The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Fri, Aug 19, 2016 at 7:58 AM, Patterson, Heather, EMNRD
<Heather.Patterson@state.nm.us> wrote:

Denis,

Please see the attached photos from the East Shugart Unit Wells number 27, 39, and 46. All three of these releases will require a Form C-141 and a work plan, based on analytic data, detailing how Agua Sucia intends to clean them up. Your C-141 is due 15 days from the date of discovery of the release. The BLM is copied in this email since this involves federal lands.

If you have any questions, please contact me.

Thanks,

Heather Patterson

Environmental Specialist

NMOCD District II

Office (575)748-1283 ext.101

Cell (575)703-0228

From: Cordero, Gilbert, EMNRD

Sent: Thursday, August 18, 2016 3:24 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Subject: Agua Sucia

Attached are some pictures of the ESU 27 – Had a release with oil in the cellar.

ESU 39 had a release with staining around location and the well head.

ESU 46 is a starting point. The release is west of location.

Thanks,

Gilbert Cordero

Compliance Officer

NMOCD District II

Office 575.748.1283 ext.114

Cell 575.626.0830

From: [Cordero, Gilbert, EMNRD](#)
To: [Tucker, Shelly](#); [Patterson, Heather, EMNRD](#)
Cc: [Denis Schoenhofer](#); [Bratcher, Mike, EMNRD](#); [Bayliss, Randolph, EMNRD](#)
Subject: RE: FW: Agua Sucia
Date: Friday, August 19, 2016 3:27:49 PM
Attachments: ESU 27(5).JPG
ESU 27(6).JPG
ESU 27(7).JPG
ESU 39(5).JPG
ESU 39(6).JPG
ESU 39(7).JPG
ESU 39(8).JPG

Attached are some pictures of the ESU 27 and ESU 39 that I took today. The ESU 27 had a truck on location that pulled about 20 BBLS of fluid. And the ESU 39 had a backhoe and dump truck picking up some of the contaminated material.

Thanks,

Gilbert Cordero
Compliance Officer
NMOCD District II
Office 575.748.1283 ext.114
Cell 575.626.0830

From: Tucker, Shelly [mailto:stucker@blm.gov]
Sent: Friday, August 19, 2016 1:17 PM
To: Patterson, Heather, EMNRD
Cc: Denis Schoenhofer; Bratcher, Mike, EMNRD; Cordero, Gilbert, EMNRD; Bayliss, Randolph, EMNRD
Subject: Re: FW: Agua Sucia

I recently did an inspection too and I think I have a couple more to add to this list...I was working on sending out the INC's on the ones I found.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker
Environmental Protection Specialist
Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

stucker@blm.gov



The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Fri, Aug 19, 2016 at 7:58 AM, Patterson, Heather, EMNRD

<Heather.Patterson@state.nm.us> wrote:

Denis,

Please see the attached photos from the East Shugart Unit Wells number 27, 39, and 46. All three of these releases will require a Form C-141 and a work plan, based on analytic data, detailing how Agua Sucia intends to clean them up. Your C-141 is due 15 days from the date of discovery of the release. The BLM is copied in this email since this involves federal lands.

If you have any questions, please contact me.

Thanks,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Cordero, Gilbert, EMNRD
Sent: Thursday, August 18, 2016 3:24 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Agua Sucia

Attached are some pictures of the ESU 27 – Had a release with oil in the cellar.
ESU 39 had a release with staining around location and the well head.
ESU 46 is a starting point. The release is west of location.

Thanks,

Gilbert Cordero
Compliance Officer
NMOCD District II
Office 575.748.1283 ext.114
Cell 575.626.0830

AmeriCo Energy Resources **co,ly**
UCIA LLC
EAST SHUGAR UNIT NO.27
SW $\frac{1}{4}$ OF SE $\frac{1}{4}$ SEC. 34
T.18 S-R 31 E NMNM10193
EDDY COUNTY, NEW MEXICO





From: [Denis Schoenhofer](#)
To: [Patterson, Heather, EMNRD](#)
Subject: Re: Agua Sucia
Date: Wednesday, August 24, 2016 1:25:44 AM

Heather,

I am just confirming that you received all the C141s relating to the East Shugart lease that you requested. Wells 27, 39 and 46. I assure you this is being addressed and will be resolved to your satisfaction.

Please let me know if there is anything else you need and I will devote time and effort to cure the problems. In addition, I will do my best to make sure this does not happen again. Changes will be made!

Denis Schoenhofer

Agua Sucia

918-984-8176

Sent from my iPhone

On Aug 19, 2016, at 7:58 AM, Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us> wrote:

Denis,

Please see the attached photos from the East Shugart Unit Wells number 27, 39, and 46. All three of these releases will require a Form C-141 and a work plan, based on analytic data, detailing how Agua Sucia intends to clean them up. Your C-141 is due 15 days from the date of discovery of the release. The BLM is copied in this email since this involves federal lands.

If you have any questions, please contact me.
Thanks,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Cordero, Gilbert, EMNRD
Sent: Thursday, August 18, 2016 3:24 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Agua Sucia

Attached are some pictures of the ESU 27 – Had a release with oil in the cellar.
ESU 39 had a release with staining around location and the well head.
ESU 46 is a starting point. The release is west of location.

Thanks,

Gilbert Cordero
Compliance Officer
NMOCD District II
Office 575.748.1283 ext.114
Cell 575.626.0830

<ESU 27(1).JPG>

<ESU 27(2).JPG>

<ESU 27(3).JPG>

<ESU 27(4).JPG>

<ESU 39(1).JPG>

<ESU 39(2).JPG>

<ESU 39(3).JPG>

<ESU 39(4).JPG>

<ESU 46(1).JPG>

<ESU 46(2).JPG>

<ESU 46(3).JPG>

<ESU 46(4).JPG>

<ESU 46(5).JPG>

<ESU 46(6).JPG>

<ESU 46(7).JPG>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 383977

CONDITIONS

Operator: AGUA SUCIA LLC 14605 South Memorial Drive Bixby, OK 74008	OGRID: 265779
	Action Number: 383977
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
amaxwell	Historical document upload.	9/16/2024