Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 452882

QUESTIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	452882
	Action Type:
	[NOTIFY] Notification Of Sampling (C-141N)

QUESTIONS

Prerequisites			
Incident ID (n#)	nAPP2210343535		
Incident Name	NAPP2210343535 CEDAR CANYON 16 8H @ 30-015-41596		
Incident Type	Produced Water Release		
Incident Status	Remediation Plan Approved		
Incident Well	[30-015-41596] CEDAR CANYON 16 STATE #008H		

Location of Release Source		
Site Name	CEDAR CANYON 16 8H	
Date Release Discovered	04/06/2022	
Surface Owner	Private	

Sampling Event General Information				
ease answer all the questions in this group.				
What is the sampling surface area in square feet	34,067			
What is the estimated number of samples that will be gathered	20			
Sampling date pursuant to Subparagraph (a) of Paragraph (1) of Subsection D of 19.15.29.12 NMAC	04/21/2025			
Time sampling will commence	08:00 AM			
Please provide any information necessary for observers to contact samplers	hgreen@ensolum.com			
Please provide any information necessary for navigation to sampling site	32.22251, -103.9826; possible H2S and wildlife			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 452882

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	452882
	Action Type:
	[NOTIFY] Notification Of Sampling (C-141N)

CONDITIONS

Created E	[*]	Condition Date
wdittric	Failure to notify the OCD of sampling events including any changes in date/time per the requirements of 19.15.29.12.D.(1).(a) NMAC, may result in the remediation closure samples not being accepted.	