

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 487418

**QUESTIONS**

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 487418
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

**QUESTIONS**

Prerequisites	
Incident ID (n#)	nAPP2202845563
Incident Name	NAPP2202845563 HARROUN EAST TANK BATTERY @ 0
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved
Incident Facility	[fAPP2129830694] Harroun Ranch East

Location of Release Source	
Site Name	HARROUN EAST TANK BATTERY
Date Release Discovered	01/27/2022
Surface Owner	Federal

Liner Inspection Event Information	
<i>Please answer all the questions in this group.</i>	
What is the liner inspection surface area in square feet	10,200
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/25/2025
Time liner inspection will commence	10:00 AM
Please provide any information necessary for observers to liner inspection	If any questions or concerns call Samantha Allen at (512) 788-2948 or email at <a href="mailto:samantha.allen@tetrattech.com">samantha.allen@tetrattech.com</a>
Please provide any information necessary for navigation to liner inspection site	FROM THE INTERSECTION OF NM-31 (POTASH MINES RD) AND S. DONALDSON FARM RD, TRAVEL WEST ON NM-31 FOR APPROXIMATELY 1.7 MILES. TURN RIGHT AND CONTINUE SOUTH ON UNNAMED LEASE RD FOR APPROXIMATELY 1.1 MILES. TURN LEFT AND CONTINUE EAST ON UNNAMED LEASE RD FOR APPROXIMATELY 2.78 MILES TO ARRIVE AT LOCATE AREA. TURN RIGHT AND HEAD SOUTH 300 FEET INTO PASTURE TO AREA FOR LOCATING.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 487418

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 487418
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
sallen	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/22/2025