Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 488112

QUESTIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	488112
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2307228945
Incident Name	NAPP2307228945 BRADLEY 8 FEE 3H BATTERY @ 30-015-39812
Incident Type	Release Other
Incident Status	Initial C-141 Approved
Incident Well	[30-015-39812] BRADLEY 8 FEE #003H

Location of Release Source		
Site Name	BRADLEY 8 FEE 3H BATTERY	
Date Release Discovered	03/12/2023	
Surface Owner	Private	

Liner Inspection Event Information		
Please answer all the questions in this group.		
What is the liner inspection surface area in square feet	9,500	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/28/2025	
Time liner inspection will commence	08:00 AM	
Please provide any information necessary for observers to liner inspection	tristan jones 575-318-6841	
Please provide any information necessary for navigation to liner inspection site	32.66834,-104.40259	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 488112

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	488112
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By		Condition Date
tristanjones	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/23/2025