Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 512775

## **QUESTIONS**

| ı | Operator:                      | OGRID:   |
|---|--------------------------------|--|
| ı | Civitas Permian Operating, LLC | 332195   |
| ı | 555 17th Street                | Action Number:                                     |
| ı | Denver, CO 80202               | 512775   |
| ı |                                | Action Type:                                       |
| ı |                                | [NOTIFY] Notification Of Liner Inspection (C-141L) |

## QUESTIONS

| Prerequisites    |  |  |  |
|------------------|--|--|--|
| Incident ID (n#) | nAPP2527929422   |  |  |
| Incident Name    | NAPP2527929422 QUEEN KEELY COM TANK BATTERY @ B-21-21S-33E |  |  |
| Incident Type    | Produced Water Release                                     |  |  |
| Incident Status  | Initial C-141 Received                                     |  |  |

| ocation of Release Source |                              |  |
|---------------------------|------------------------------|--|
| Site Name                 | Queen Keely Com Tank Battery |  |
| Date Release Discovered   | 10/05/2025                   |  |
| Surface Owner             | State                        |  |

| Liner Inspection Event Information  |  |  |
|---|--|--|
| ease answer all the questions in this group.  |  |  |
| What is the liner inspection surface area in square feet  | 17,180   |  |
| Have all the impacted materials been removed from the liner   | Yes  |  |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 10/10/2025   |  |
| Time liner inspection will commence   | 08:00 AM   |  |
| Please provide any information necessary for observers to liner inspection                              | Liner inspection will occur where the separators are located on the west side of the pad.  |  |
| Please provide any information necessary for navigation to liner inspection site                        | From the intersection of HWY 176 and Berry Booster Road (32.508757, -103.489131) drive south west on Berry Booster Road for 1.47 miles, turn left. Continue south for 0.71 miles, turn left. Continue southeast for 1.61 miles, turn right. Continue west for 4.80 miles, turn right. Continue north for 0.42 miles, turn left. Continue northwest for 0.41 miles, turn left. Continue west for 0.18 miles, turn right. Continue north for 1.36 miles, turn right. Continue east for 0.6 miles, turn right. Continue south for 0.15 miles and arrive onsite. |  |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 512775

## **CONDITIONS**

| Operator:                      | OGRID:   |
|--------------------------------|--|
| Civitas Permian Operating, LLC | 332195   |
| 555 17th Street                | Action Number:                                     |
| Denver, CO 80202               | 512775   |
|                                | Action Type:                                       |
|                                | [NOTIFY] Notification Of Liner Inspection (C-141L) |

## CONDITIONS

| Created By | Condition  | Condition<br>Date |
|------------|--|-------------------|
| mjones01   | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 10/7/2025         |