

### **C9+ Analysis**GPA 2172/API 14.5 Report with GPA 2145 Physical Properties

### Sample Information

		Sample Information
Sample Name		OCOTILLO 2H CHECK 6-19-25
Operator		Permian Resources
Lease		OCOTILLO 2H CHECK
Sample Date/Time:	Effective Date:	6-19-25 7:48 AM
Sample End Date		
Laboratory		Premier Measurement and Laboratory Services
Technician		AN
Analyzer Type		Gas Chromatograph - TCD
Analyzer Make & Model		Agilent Micro GC 3000
Last Calibration/Validation Date		6-16-2025
Sample Temperature		87 F
Sample Pressure		591 PSI
Sample Flow Rate		1426 MCF
Ambient Temperature		78 F
Heat Tracing		No
Sample Type		Spot
Sampling Method		Fill and Purge
Company Collecting Sample		LSM
Sampled By		TH
Cylinder #		1724
Mole, Weight, or Percent (For F	lowcal DON'T EDIT)	M
Sample Calculation Method(For	Flowcal DON'T EDIT)	GPA 2172/API 14.5 Report with GPA 2145 Physical Properties
Analysis Date		2025-06-20 10:30:51

### Component Results

Component Name	Un-Normalized Mole%	Norm Mole%
Nitrogen	1.0690	1.0589
Carbon Dioxide	0.0960	0.0951
Methane	83.2380	82.4498
Ethane	10.4870	10.3877
Propane	3.8340	3.7977
isobutane	0.5180	0.5131

Component Name	Un-Normalized Mole%	Norm Mole%
n-Butane	0.9570	0.9479
isopentane	0.2110	0.2090
n-Pentane	0.2030	0.2011
hexanes	0.2190	0.2169
heptanes	0.0870	0.0862
octanes	0.0270	0.0267
nonanes+	0.0100	0.0099
hydrogen sulfide	0.0000	0.0000
Total:	100.9560	100.0000

### **Results Summary**

Result	Dry	Wet/Sat	
Total Un-Normalized Mole%	100.9560		
Pressure Base (psia)	14.730		
Temperature Base (Deg. F)	60.00		
Gross Heating Value (BTU / Ideal cu.ft.)	1196.3	1175.5	
Gross Heating Value (BTU / Real cu.ft.)	1200.1	1179.7	
Relative Density (G), Ideal	0.6845	0.6834	
Relative Density (G), Real	0.6864	0.6856	
Compressibility (Z) Factor	0.9968	0.9965	
Total GPM	18.753	18.534	



Permian Resources meters all flared volumes, and volumes reported on C-129's in connection with flaring events are based on the available meter readings. While Permian Resources reports metered volumes on C-129 submissions, PR reviews the metered data for accuracy, reconciles any discovered discrepancies, and, where appropriate, submits amended C-129 reported volumes post-reconciliation to ensure accurate reporting.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

DEFINITIONS

Action 523156

#### **DEFINITIONS**

ı	Operator:	OGRID:
ı	Earthstone Operating, LLC	331165
ı	300 N. Marienfeld St Ste 1000	Action Number:
ı	Midland, TX 79701	523156
ı		Action Type:
ı		[C-129] Venting and/or Flaring (C-129)

#### **DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 523156

Q	UESTIONS	
Operator: Earthstone Operating, LLC		OGRID: 331165
300 N. Marienfeld St Ste 1000 Midland, TX 79701		Action Number: 523156
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve t	hese issues before continuing wit	h the rest of the questions.
Incident Well	Unavailable.	
Incident Facility	[fAPP2123833170] OCOTIL	LO 6-31 STATE COM BATTERY
Determination of Danastina Deminary		
Determination of Reporting Requirements	nd may prayida addianal ayidanaa	
Answer all questions that apply. The Reason(s) statements are calculated based on your answers an Was this vent or flare caused by an emergency or malfunction	No	
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes	
Is this considered a submission for a vent or flare event	Yes, minor venting and/or	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during vi		
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes	be a major of milital release under 15.10.25.7 NVIDO.
Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.	l	
Methane (CH4) percentage	82	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required speci	ifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	

Not answered.

Oxygen (02) percentage quality requirement

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
<a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 523156

QUESTI	ONS (continued)
Operator:	OGRID:
Earthstone Operating, LLC 300 N. Marienfeld St Ste 1000	331165 Action Number:
Midland, TX 79701	523156
	Action Type:  [C-129] Venting and/or Flaring (C-129)
QUESTIONS	, , , , ,
Date(s) and Time(s)	
Date vent or flare was discovered or commenced	10/28/2025
Time vent or flare was discovered or commenced	12:00 AM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	24
Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications   Pipeline (Any)   Natural Gas Flared   Released: 431 Mcf   Recovered: 0 Mcf   Lost: 431 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.
Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No.
Was notification of downstream activity received by this operator	No Not appuared
Downstream OGRID that should have notified this operator	Not answered.  Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.
Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Purging vessels and new equipment of O6
Steps taken to limit the duration and magnitude of vent or flare	Open valves to divert gas to a second midstream company to relieve pressure off the line
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Clear consistent communication with midstream provider

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 523156

### **ACKNOWLEDGMENTS**

Operator:	OGRID:
Earthstone Operating, LLC	331165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	523156
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

### ACKNOWLEDGMENTS

V	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be <b>a complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 523156

#### **CONDITIONS**

Operator:	OGRID:
Earthstone Operating, LLC	331165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	523156
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

#### CONDITIONS

Created By	Condition	Condition Date
jdoolingpr	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	11/4/2025