

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505**

QUESTIONS

Action 526169

**QUESTIONS**

|   |  |
|---|--|
| Operator:<br>DEVON ENERGY PRODUCTION COMPANY, LP<br>333 West Sheridan Ave.<br>Oklahoma City, OK 73102 | OGRID:<br>6137   |
|   | Action Number:<br>526169   |
|   | Action Type:<br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

**QUESTIONS**

|                      |  |
|----------------------|--|
| <b>Prerequisites</b> |  |
| Incident ID (n#)     | nAPP2523933948                         |
| Incident Name        | NAPP2523933948 ARENA ROJA 28 CTB 2 @ 0 |
| Incident Type        | Produced Water Release                 |
| Incident Status      | Initial C-141 Approved                 |
| Incident Facility    | [fAPP2328337819] ARENA ROJA 28 CTB 2   |

|                                   |                     |
|-----------------------------------|---------------------|
| <b>Location of Release Source</b> |                     |
| Site Name                         | ARENA ROJA 28 CTB 2 |
| Date Release Discovered           | 08/26/2025          |
| Surface Owner                     | Federal             |

|   |                             |
|---|-----------------------------|
| <b>Liner Inspection Event Information</b>   |                             |
| <i>Please answer all the questions in this group.</i>   |                             |
| What is the liner inspection surface area in square feet  | 16,300                      |
| Have all the impacted materials been removed from the liner   | Yes                         |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 11/18/2025                  |
| Time liner inspection will commence   | 12:00 PM                    |
| Please provide any information necessary for observers to liner inspection                              | Monty Wilson (505) 340-1905 |
| Please provide any information necessary for navigation to liner inspection site                        | 32.0186376, -103.3724479    |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 526169

**CONDITIONS**

|   |  |
|---|--|
| Operator:<br>DEVON ENERGY PRODUCTION COMPANY, LP<br>333 West Sheridan Ave.<br>Oklahoma City, OK 73102 | OGRID:<br>6137   |
|   | Action Number:<br>526169   |
|   | Action Type:<br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

**CONDITIONS**

| Created By | Condition  | Condition Date |
|------------|--|----------------|
| jraley     | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 11/13/2025     |