

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 530119

**QUESTIONS**

Operator:  DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID:  6137
	Action Number:  530119
	Action Type:  [NOTIFY] Notification Of Liner Inspection (C-141L)

**QUESTIONS**

Prerequisites	
Incident ID (n#)	nAPP2526823340
Incident Name	NAPP2526823340 MUSTANG 8 CTB 3 @ FAPP2510041275
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved
Incident Facility	[fAPP2510041275] MUSTANG 8 CTB 3

**Location of Release Source**

Site Name	MUSTANG 8 CTB 3
Date Release Discovered	09/24/2025
Surface Owner	Federal

**Liner Inspection Event Information***Please answer all the questions in this group.*

What is the liner inspection surface area in square feet	19,327
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	12/02/2025
Time liner inspection will commence	10:00 AM
Please provide any information necessary for observers to liner inspection	Sally Carttar 575.361.3561 scarttar@vertexresource.com
Please provide any information necessary for navigation to liner inspection site	At the intersection NM-128 and Orla Rd (C-1), turn south and continue for 2.4mi. Turn west onto the lease rd. and continue for 1.0mi. Turn south and continue for 2.5mi. Turn east onto County Rd 1-B and continue for 0.5mi. Turn east and continue for 0.87mi. Turn south onto the access road until you reach the site.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 530119

**CONDITIONS**

Operator:  DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID:  6137
	Action Number:  530119
	Action Type:  [NOTIFY] Notification Of Liner Inspection (C-141L)

**CONDITIONS**

Created By	Condition	Condition Date
jraleyley	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	11/26/2025