



Athens, TX (903) 677-0700 . Beeville, TX (361) 354-5200 . Midland, TX (432) 704-5351

## GAS ANALYSIS REPORT

LAB REPORT NUMBER: 8093-04-042921-22 - 04032021

### PHYSICAL CONSTANTS PER GPA 2145-16

CUSTOMER:	BTA OIL PRODUCERS LLC	DATE ANALYZED:	4/29/2021
STATION:	80939199	DATE ON:	4/3/2021
PRODUCER:	BTA OIL PRODUCERS	DATE OFF:	
LEASE:	OGDEN 6H CM	SAMPLED BY	JR
EFFECTIVE DATE:	4/1/2021		

<u>COMPONENT:</u>	<u>MOLE %</u>	<u>GPM</u>	<u>WT. %</u>
H2S	0.000		0.000
OXYGEN	0.009		0.012
NITROGEN	1.097		1.316
CARBON DIOXIDE	0.067		0.126
METHANE	73.253		50.313
ETHANE	12.593	3.364	16.211
PROPANE	6.673	1.836	12.598
I-BUTANE	0.884	0.289	2.200
N-BUTANE	2.243	0.706	5.581
I-PENTANE	0.532	0.194	1.643
N-PENTANE	0.631	0.229	1.949
HEXANE PLUS	<u>2.018</u>	<u>0.875</u>	<u>8.051</u>
<b>TOTAL</b>	<b>100.000</b>	<b>7.494</b>	<b>100.000</b>

**(ALL VALUES CALCULATED @ 14.65 PSIA + 60 DEG. F)**

REAL GRAVITY	0.8099	BTU WET BASIS	1361.08
MOL WT.	23.358	BTU DRY BASIS	1384.70
H2S PPM:	1.000	CO2 %:	
SAMPLE TYPE	SPOT	SAMPLE PRESS:	71
CYLINDER NO	WT-2032	SAMPLE TEMP:	86
NOTES	SOT	COUNTY/STATE:	LEA, NM

5/1/2021



Ogden 5-6 Flare Gas

12/12/2025

58

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS

Action 535447

**DEFINITIONS**

Operator:	OGRID: 260297
BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	Action Number: 535447
	Action Type: [C-129] Venting and/or Flaring (C-129)

**DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 535447

**QUESTIONS**

Operator:  BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 535447
	Action Type: [C-129] Venting and/or Flaring (C-129)

**QUESTIONS****Prerequisites**

*Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.*

Incident Well	Unavailable.
Incident Facility	[FAB1904636949] OGDEN 20509 SWD SUBSTATION TANK BATTERY

**Determination of Reporting Requirements**

*Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.*

Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.

*An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.*

Was there <b>at least 50 MCF</b> of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

**Equipment Involved**

Primary Equipment Involved	Dump Valve
Additional details for Equipment Involved. Please specify	<i>Not answered.</i>

**Representative Compositional Analysis of Vented or Flared Natural Gas**

*Please provide the mole percent for the percentage questions in this group.*

Methane (CH4) percentage	73
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0

*If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.*

Methane (CH4) percentage quality requirement	<i>Not answered.</i>
Nitrogen (N2) percentage quality requirement	<i>Not answered.</i>
Hydrogen Sulfide (H2S) PPM quality requirement	<i>Not answered.</i>
Carbon Dioxide (CO2) percentage quality requirement	<i>Not answered.</i>
Oxygen (O2) percentage quality requirement	<i>Not answered.</i>

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 535447

**QUESTIONS (continued)**

Operator:  BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 535447
	Action Type: [C-129] Venting and/or Flaring (C-129)

**QUESTIONS**

<b>Date(s) and Time(s)</b>	
Date vent or flare was discovered or commenced	12/12/2025
Time vent or flare was discovered or commenced	12:00 AM
Time vent or flare was terminated	01:00 AM
Cumulative hours during this event	1

<b>Measured or Estimated Volume of Vented or Flared Natural Gas</b>	
Natural Gas Vented (Mcf) Details	<i>Not answered.</i>
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure   Dump Valve   Natural Gas Flared   Released: 58 Mcf   Recovered: 0 Mcf   Lost: 58 Mcf.
Other Released Details	<i>Not answered.</i>
Additional details for Measured or Estimated Volume(s). Please specify	<i>Not answered.</i>
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

<b>Venting or Flaring Resulting from Downstream Activity</b>	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	<i>Not answered.</i>
Downstream OGRID that should have notified this operator	<i>Not answered.</i>
Date notified of downstream activity requiring this vent or flare	<i>Not answered.</i>
Time notified of downstream activity requiring this vent or flare	<i>Not answered.</i>

<b>Steps and Actions to Prevent Waste</b>	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Unexpected oil dump malfunction
Steps taken to limit the duration and magnitude of vent or flare	Will replace dump valve
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Will Monitor



Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 535447

**ACKNOWLEDGMENTS**

Operator:  BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID:  260297
	Action Number:  535447
	Action Type:  [C-129] Venting and/or Flaring (C-129)

**ACKNOWLEDGMENTS**

<input checked="" type="checkbox"/>	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a <b>complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
<input checked="" type="checkbox"/>	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emrrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 535447

**CONDITIONS**

Operator:  BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 535447
	Action Type: [C-129] Venting and/or Flaring (C-129)

**CONDITIONS**

Created By	Condition	Condition Date
vanessa king	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/16/2025