

GasCal - [mvolume]

File

## Gas Volume Calculations

<b>Meter Tube Size :</b>	<input type="text" value="16"/>	<b>Factors</b>	<b>Orifice Factor :</b>	<input type="text" value="12.58533"/>	
<b>PSIG</b>	<b>PSIA</b>	<b>Orifice Plate Size :</b>	<input type="text" value=".25"/>	<b>Temperature Factor :</b>	<input type="text" value="1.00000"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>Pressure: (PSIG) :</b>	<input type="text" value="56"/>	<b>Gravity Factor :</b>	<input type="text" value="1.24611"/>
<b>Static Pressure</b>		<b>Differential :</b>	<input type="text" value="1551"/>	<b>Fpv Factor :</b>	<input type="text" value="1.00508"/>
<b>Up</b>	<b>Down</b>	<b>Temperature :</b>	<input type="text" value="60"/>	<b>Reynolds Number :</b>	<input type="text" value="1.00035"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>Gravity :</b>	<input type="text" value="0.644"/>	<b>Expansion Factor :</b>	<input type="text" value=".75039"/>
<b>Hours</b>	<b>Minutes</b>	<b>Mole % CO<sub>2</sub> :</b>	<input type="text" value="0"/>	<b>C Prime :</b>	<input type="text" value="11.83199"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>Mole % N<sub>2</sub> :</b>	<input type="text" value="0"/>	<b>Beta Ratio :</b>	<input type="text" value=".0156"/>
		<b>Pressure Base :</b>	<input type="text" value="14.73"/>	<b>Pressure Base Factor :</b>	<input type="text" value="1.00000"/>
		<b>Temperature Base :</b>	<input type="text" value="60"/>		
		<b>Barometric Pressure :</b>	<input type="text" value="12"/>	<b>Volume ( MCF ) :</b>	<input type="text" value="7.685"/>
		<b>Flow Time: (Hours)</b>	<input type="text" value="2"/>	<b>Volume ( MMBTU ) :</b>	<input type="text" value="7.946"/>
		<b>BTU Value :</b>	<input type="text" value="1034.0"/>		
<b>Input Meter Tube Size</b>					
<b>Main Menu</b> <b>Diff/Volume</b> <b>Plate Change</b> <b>Weymouth</b> <b>Analysis</b> <b>Retro/Setpoint</b> <b>Blowdown Cal.</b>					

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 540651

**QUESTIONS**

Operator: Enterprise Field Services, LLC PO Box 4324 Houston, TX 77210	OGRID: 241602
	Action Number: 540651
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

<b>Prerequisites</b>	
Incident ID (n#)	nAPP2600647792
Incident Name	NAPP2600647792 TRUNK K #4 @ J-09-26N-07W
Incident Type	Natural Gas Release
Incident Status	Initial C-141 Received

**Location of Release Source**

*Please answer all the questions in this group.*

Site Name	Trunk K #4
Date Release Discovered	01/06/2026
Surface Owner	Federal

**Incident Details**

*Please answer all the questions in this group.*

Incident Type	Natural Gas Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

**Nature and Volume of Release**

*Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.*

Crude Oil Released (bbls) Details	<i>Not answered.</i>
Produced Water Released (bbls) Details	<i>Not answered.</i>
Is the concentration of chloride in the produced water >10,000 mg/l	<i>No</i>
Condensate Released (bbls) Details	<i>Cause: Corrosion   Pipeline (Any)   Condensate   Released: 5 BBL   Recovered: 0 BBL   Lost: 5 BBL.</i>
Natural Gas Vented (Mcf) Details	<i>Cause: Corrosion   Pipeline (Any)   Natural Gas Vented   Released: 8 MCF   Recovered: 0 MCF   Lost: 8 MCF.</i>
Natural Gas Flared (Mcf) Details	<i>Not answered.</i>
Other Released Details	<i>Not answered.</i>
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	<i>Not answered.</i>

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 540651

**QUESTIONS (continued)**

Operator: Enterprise Field Services, LLC PO Box 4324 Houston, TX 77210	OGRID: 241602
	Action Number: 540651
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

<b>Nature and Volume of Release (continued)</b>	
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this will be treated as a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	No
Reasons why this would be considered a submission for a notification of a major release	<i>Unavailable.</i>

*With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.*

<b>Initial Response</b>	
<i>The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.</i>	
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	none

*Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Philip Cowan Title: Field Environmental Scientist Email: <a href="mailto:plcowan@eprod.com">plcowan@eprod.com</a> Date: 01/06/2026
----------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 540651

**QUESTIONS (continued)**

Operator: Enterprise Field Services, LLC PO Box 4324 Houston, TX 77210	OGRID: 241602
	Action Number: 540651
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS****Site Characterization**

*Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.*

What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Between 26 and 50 (ft.)
What method was used to determine the depth to ground water	NM OSE iWaters Database Search
Did this release impact groundwater or surface water	No
<b>What is the minimum distance, between the closest lateral extents of the release and the following surface areas:</b>	
A continuously flowing watercourse or any other significant watercourse	Between 500 and 1000 (ft.)
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Between 1000 (ft.) and ½ (mi.)
An occupied permanent residence, school, hospital, institution, or church	Between 1 and 5 (mi.)
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Between 1000 (ft.) and ½ (mi.)
Any other fresh water well or spring	Between 1000 (ft.) and ½ (mi.)
Incorporated municipal boundaries or a defined municipal fresh water well field	Greater than 5 (mi.)
A wetland	Between 1000 (ft.) and ½ (mi.)
A subsurface mine	Greater than 5 (mi.)
An (non-karst) unstable area	Greater than 5 (mi.)
Categorize the risk of this well / site being in a karst geology	Low
A 100-year floodplain	Between 500 and 1000 (ft.)
Did the release impact areas not on an exploration, development, production, or storage site	No

**Remediation Plan**

*Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.*

Requesting a remediation plan approval with this submission	No
<i>The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.</i>	

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 540651

**CONDITIONS**

Operator:	OGRID: 241602
Enterprise Field Services, LLC PO Box 4324 Houston, TX 77210	Action Number: 540651
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**CONDITIONS**

Created By	Condition	Condition Date
nvelez	Volume calculation toward the soil quantity impacted must be addressed in future submittals.	1/7/2026