

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 570975

QUESTIONS

Operator: Delaware Basin Midstream LLC 9950 Woodloch Forest Drive The Woodlands, TX 77380	OGRID: 314437
	Action Number: 570975
	Action Type: [NOTIFY] Notification Of Sampling (C-141N)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2528638858
Incident Name	NAPP2528638858 NORTH BRUSHY DRAW 6-INCH PIPELINE @ L-36-25S-29E
Incident Type	Release Other
Incident Status	Remediation Plan Approved

Location of Release Source	
Site Name	NORTH BRUSHY DRAW 6-INCH PIPELINE
Date Release Discovered	10/07/2025
Surface Owner	State

Sampling Event General Information	
<i>Please answer all the questions in this group.</i>	
What is the sampling surface area in square feet	1,813
What is the estimated number of samples that will be gathered	16
Sampling date pursuant to Subparagraph (a) of Paragraph (1) of Subsection D of 19.15.29.12 NMAC	04/08/2026
Time sampling will commence	09:00 AM
Please provide any information necessary for observers to contact samplers	Please contact Blake Estep at 432-894-6038 with any questions.
Please provide any information necessary for navigation to sampling site	From the intersection of Pipeline Road 1 & Longhorn Road, travel NE for 3.63 miles. Turn S, travel 0.29 miles. Turn E, travel 0.44 miles. Turn S, travel 0.69 miles. Turn E, go 0.01 miles to the provided GPS coordinates.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oecd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 570975

CONDITIONS

Operator: Delaware Basin Midstream LLC 9950 Woodloch Forest Drive The Woodlands, TX 77380	OGRID: 314437
	Action Number: 570975
	Action Type: [NOTIFY] Notification Of Sampling (C-141N)

CONDITIONS

Created By	Condition	Condition Date
mgreen	Failure to notify the OCD of sampling events including any changes in date/time per the requirements of 19.15.29.12.D.(1).(a) NMAC, may result in the remediation closure samples not being accepted.	4/2/2026
mgreen	If confirmation sampling is going to take place over multiple days, individual C-141N applications must be submitted for each sampling date. Date ranges are not currently accepted on the C-141N application.	4/2/2026