

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 558263

QUESTIONS

Operator: XTO ENERGY, INC 3617 North Big Spring Street Midland, TX 79705	OGRID: 5380
	Action Number: 558263
	Action Type: [C-141] Cancellation Request (C-141C)

QUESTIONS

Prerequisites	
Incident ID (n#)	nGRL0936428422
Incident Name	NGRL0936428422 2009 CCRA OS @ 30-025-31465
Incident Type	Oil Release
Incident Status	Closure Not Approved
Incident Well	[30-025-31465] EUNICE MONUMENT SOUTH UNIT #626

Location of Release Source	
Site Name	Unavailable.
Date Release Discovered	08/26/2009
Surface Owner	Federal

Determination of Cancellation	
<i>Please answer all the questions in this group.</i>	
Incident Cancel Reason	Duplicate incident; reported more than once
What is the incident id (n#) that should cause this incident to be cancelled	NGRL0927453159 2009 I OS @ 30-025-31465
Please provide any additional details on why this incident should be cancelled	On August 26, 2009, during the removal of a below grade tank, when the discharge line was disconnected, a small amount of crude oil and produced water was incidentally released to surrounding soils. A Release Notification and Corrective Action form (C-141) was received on September 30, 2009, and associated the release with the nearest well, EMSU Well #626 (API 30-025-31465). On October 26, 2009, Larson and Associates, Inc. (Larson) submitted a Below Grade Tank Removal and Excavation Closure Report (Closure Report) to the NMOCD. Finally, a Below-Grade Tank Closure Final Report (Final Report) was submitted to the NMOCD on December 14, 2009, documenting the previous remedial activities as well as backfilling activities. The report is documented as received on December 16, 2009. The Closure Report details the tank removal and remediation activities completed and requested Closure of the Incident. The below grade tank removal was completed in tandem with another tank removal on the Site, again a minimal amount of crude oil and produced water was released and assigned Incident Number NGRL0927451742 and Remediation Permit (RP) Number 1RP-2285 remediation activities to address impacts were completed. A third Incident Number nGRL0927453159 is also documented, however the spill date, volumes released, description of the Incident Events, and location information is all identical. The only difference is that it appears the Incident nGRL0927453159 event description was added on October 1, 2009, following receipt of the C-141. An RP Number (1RP-2286) was assigned, and documentation of the report and C-141 was uploaded to the portal. The status for Incident Number nGRL0927453159 is listed as Incident Closure Approved. The subject Incident, Incident Number NGRL0936428422, notes the Incident Event update on December 30, 2009, after the Final Report was received, however, no RP number or document upload was completed. Based on the above, a request for cancellation appears reasonable

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 558263

ACKNOWLEDGMENTS

Operator: XTO ENERGY, INC 3617 North Big Spring Street Midland, TX 79705	OGRID: 5380
	Action Number: 558263
	Action Type: [C-141] Cancellation Request (C-141C)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I acknowledge that with this application I will be cancelling an existing incident file (assigned to this operator) for a release event, pursuant to 19.15.29 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that cancelling an incident file will require this operator to (re)file submission(s) of all/any C-141 forms (pursuant to 19.15.29 NMAC), and to create a new incident for the cancelled release event if necessary.
<input checked="" type="checkbox"/>	I hereby certify the statements in this cancelling report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-141 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-141 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 558263

CONDITIONS

Operator: XTO ENERGY, INC 3617 North Big Spring Street Midland, TX 79705	OGRID: 5380
	Action Number: 558263
	Action Type: [C-141] Cancellation Request (C-141C)

CONDITIONS

Created By	Condition	Condition Date
nvez	None	4/2/2026