<u>District I</u> State of New Mexico Form C-103 1625 N. French Dr., Hobbs, NM 88240 Permit67411 Energy, Minerals and Natural Resources Phone:(505) 393-6161 Fax:(505) 393-0720 WELL API NUMBER Oil Conservation Division 1301 W. Grand Ave., Artesia, NM 88210 30-039-27706 Phone:(505) 748-1283 Fax:(505) 748-9720 1220 S. St Francis Dr. **Santa Fe, NM 87505** Indicate Type of Lease 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 State Oil & Gas Lease No. Phone:(505) 476-3470 Fax:(505) 476-3462 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO RINCON UNIT A DIFFRENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 404 1. Type of Well:G 9. OGRID Number 2. Name of Operator CHEVRON MIDCONTINENT, L.P. 241333 3. Address of Operator 10. Pool name or Wildcat. 11111 S. WILCREST, HOUSTON, TX 77099 4. Well Location Unit Letter N 2635 feet from the feet from the line and Section Township 27N Range 06W NMPM Rio Amba County 11. Elevation (Show whether DR, KB, BT, GR, etc.) 6555 GR Pit or Below-grade Tank Application or Closure ____ Distance from nearest fresh water well____ __ Distance from nearest surface water_ Pit. Type _____ Depth to Groundwater___ Pit Liner Thickness: __ mil Below-Grade Tank: Volume____ bbls; Construction Material Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTER CASING TEMPORARILY ABANDON | CHANGE OF PLANS | COMMENCE DRILLING OPNS. 🗀 PLUG AND ABANDON PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB Other: Other: Spud X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/6/2007 Spudded well. Notified Steve Haydon w/ NMOCD and BLM 24hr Hotline of upcoming spud, surface casing, and cement, and BOP test. 1-6-2008 - Spud Rincon #404 @15:30hrs. Drilled 12:25" surface hole from 0' to 283'. 1-7-2008 - Contuined to drill surface hole from 283' to 411'. Ran 9 5/8" 36# J55 surface casing to 408'. Pumped 53bbl (245sx) of Class G 15.6ppg w/ 1.20 yld. Had returns of 28bbl (131sx) to surface. TOC 0' calculated by circulations. 1-8-2008 - Test Annular to 1500psi High / 250psi Low (10min/5min), test surface casing to 1000psi for 30 min. All test good. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has beenAvill be constructed or closed according to NMOCD guidelines 🗐 , a general permit 🗀 or an (attached) alternative OCD-approved plan 🛚

TITLE

E-mail address leakejd@chevron.com

TITLE District Supervisor

DATE 1/11/2008

Telephone No. 432-687-7375

DATE 1/16/2008

SIGNATURE Electronically Signed

Charlie Perrin

Type or print name Joy Pinkerton

<u>For State Use Only:</u> APPROVED BY: