

District I 1625 N. French Dr., Hobbs, NM 88240
District II 1301 W. Grand Ave., Artesia, NM 88210
District III 1000 Rio Brazos Rd., Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

WELL API NO. 30-021-20585
5. Indicate Type of Lease STATE [] FEE [x]
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well [] Gas Well [] Other CO2 Well

2. Name of Operator Reliant Exploration & Production, LLC.

3. Address of Operator 10817 West County Road 60 Midland, TX 79707

4. Well Location Unit Letter P : 660 feet from the South line and 660 feet from the East line Section 14 18 Township 19 N Range 31 E NMPM County Harding

11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4499

Pit or Below-grade Tank Application [] or Closure []
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] MULTIPLE COMPL []
OTHER: []
SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [x] P AND A [] CASING/CEMENT JOB [x]
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [x], a general permit [] or an (attached) alternative OCD-approved plan [].

SIGNATURE [Signature] TITLE Manager DATE 10-4-13

Type or print name For State Use Only Vance VanDerburg E-mail address: vance@reliantgas.com Telephone No. 432-559-7085

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 10/10/2013
Conditions of Approval (if any):

Libby Minerals LLC 1931 18-2-P

9/29/13

(06:00)MIRU Reliant Rig #1. KB = 10' AGL.

Inspected rig, drill collars, and drill pipe.

Spud in at (22:00) / Drill 12.25" surface hole from 0' to 80' / Average WOB 7 / 95-100 RTS / 360 gpm @ 900 psi.

9/30/13

Drill 12.25" surface hole from 80' to 724' / Average WOB 10 / 95-100 RTS / 370 gpm @ 900 psi.

(20:30) TOOH

10/01/13

(00:30)Ran 8.625, 24.0 lb/ft, J-55, ST&C, from 10' to 711'.

(05:00) MIRU O-Tex to pump surface cement job as follows:

Pressure tested lines to 2000 psi. Pumped 10 bbl spacer. Pumped 440 sks of Class C + 2% Calcium chloride cement at 14.8 ppg at 3.5 BPM and 100 psi. Dropped top plug and pumped 43 bbls displacement at 3.5 BPM and 100 psi. Bumped plug to 1000 psi. Float held. Circulated a total of 44 bbls to surface. Plug down at 06:45 hours on 10/01/2013. WOC

(10:00)Remove landing joint and nipple up BOP

(12:00)TIH

(13:30) Drilled 7 7/8 production hole from 724' to 1435' / Average WOB 7 / 100 RTS / 380 gpm @ 750 psi.

10/02/13

Drill 7 7/8 production hole from 1435' to 2277' / Average WOB 13 / 96 RTS / 390 gpm @ 1010 psi

(21:30) Circulate.

(22:30) TOOH

10/03/13

(04:00)MIRU Weatherford wire line to run open hole logs.

(10:30)Ran 5 ½ casing as follows: 5.5", 15.5#, J-55, 8 RD, casing from 8' to 2232'.

(16:00)Circulate and Condition hole

(16:30)MIRU O-TEX to pump cement as follows:

Pressure tested lines to 2000 psi. Pump 10 bbls spacer. Pumped 195 sks lead cement Class C + 2% GYP + 3%CaCl₂ + 2% SM + 1/8 lb per sk celloflake at 11.1 ppg at 4 bpm at 50 psi. Pumped 105 sks tail cement Class C + 2% GYP + 3%CaCl₂ + 2% SM + 1/8 lb per sk celloflake at 13.2 ppg at 4 bpm at 50 psi. Dropped top plug. Displaced cement with 53 bbls water at 4 bpm and 50 psi. Bumped plug at 1350 psi.. Float equipment held. Circulated 60 bbls to surface. Plug down at 18:40 hours on 10/3/13. Nipple down BOP equipment and clean pits and location.

(23:00) Nipple down BOP equipment and clean pits and location.

Rig released at 24:00 hours on 10/3/13.

RECEIVED OGD

2013 OCT -9 P 1:30



October 4, 2013

Mr. Ed Martin
District IV Supervisor
New Mexico Oil Conservation Division
1220 South St. Francis
Santa Fe, NM 87505

Re: Form C-103

Dear Mr. Martin:

Please find enclosed for your approval the sundry notice for the following well;

Libby Minerals LLC 1931 18-2-P.

Please send the approved notice to my attention at the following address;

7714 Georgetown Drive

Amarillo, TX 79119

Please let me know if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "Vance Vanderburg". The signature is fluid and cursive, with the first name "Vance" and last name "Vanderburg" clearly distinguishable.

Vance Vanderburg
vance@reliantholdingsltd.com
432-559-7085