

Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Jun 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-045-23618
5. Indicate Type of Lease STATE [] FEE [x]
6. State Oil & Gas Lease No. FEE
7. Lease Name or Unit Agreement Name Oshea
8. Well Number 1M
9. OGRID Number 372171
10. Pool name or Wildcat Blanco Mesaverde/Basin Dakota

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [x] Other
2. Name of Operator HILCORP ENERGY COMPANY
3. Address of Operator 382 Road 3100, Aztec, NM 87410
4. Well Location
Unit Letter F : 1450 feet from the North line and 1750 feet from the West line
Section 3 Township 31N Range 13W NMPM San Juan County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5838' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
[x] Location is ready for OCD inspection after P&A

- [x] All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
[x] Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
[x] A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It show the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKERS SURFACE.

- [x] The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
[x] Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
[x] If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
[x] All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
[x] Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Kandis Roland TITLE Operations/Reg Tech DATE 8/11/2020

Type or print name Kandis Roland E-mail address: kroland@hilcorp.com PHONE: 505-324-5149

For State Use Only

APPROVED BY: Jonathan D. Kelly TITLE Compliance Officer DATE 10/26/2020
Conditions of Approval (if any):



Final Reclamation Detail and Landowner Approval

Date Well P&A'd: 5/15/2020

Well Name: Oshea 1M

Location: Unit Letter F Footages 1450' FNL & 1750' FWL

Sec. 3; T- 31- N, R - 13 -W; County: San Juan; State: NM

Surface Owner Name: Charles R. Blassingame

Reclamation Detail: Completed 6/24/2020. Gas tap left on location per landowner request. Ground water monitor well remains on location per Harvest Pipeline Co. as required by NMOCD.

Equipment removed: yes no
(All wellhead surface equipment, tanks, meter runs, piping (removed or capped and abandoned below ground, as appropriate), cathodic equipment, fencing etc.)

Location and road have been re-contoured: yes no

Erosions / Drainage issues addressed with final reclamation: yes no

Location seeded according to Surface Owner request: yes no

I, Charles R. Blassingame, agree the final reclamation on the subject well has been satisfactorily performed.

(Surface Owner Name): Charles R. Blassingame

(Address): 1481 NM 170, PO Box 305, La Plata, NM 87418-0305

(Date): 10/26/2020

Signature:

Witness:

Ben Mitchell
Landman
Hilcorp

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 21952

CONDITIONS OF APPROVAL

Operator:	HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	OGRID:	372171	Action Number:	21952	Action Type:	C-103Z
OCD Reviewer	ahvermersch			Condition	None				