Received b	y OCD:	5/14/2021	6:35:48 AM
------------	--------	-----------	------------

Oil Conservation Division

This form is not to be used for reporting packer leakage tests in Southeast New Mexico

Northwest New Mexico Packer-Leakage Test

Page 1 Revised June 10, 2003

Operator Hilcorp Energy Company			Lease	e Name	THOMPS	NC			Well No.	7A	
Location of Well:	Unit Letter	F	Sec	34	Twp	031N	Rge	012W	API #	30-045-2332	0

	Name of Reservoir or Pool	Type of Prod	Method of Prod	Prod Medium
Upper Completion	FRS	Gas	Artificial Lift	Tubing
Lower Completion	MV	Gas	Flow	Tubing

Pre-Flow Shut-In Pressure Data

	Upper	Hour, Date, Shut-In		SI Press. PSIG	Stabilized?(Yes or No)
	Completion	5/10/2021	Length of Time Shut-In	20) Yes
L	Lower	Hour, Date, Shut-In	85	SI Press. PSIG	Stabilized?(Yes or No)
	Completion	5/10/2021		108	3 Yes

Flow Test No. 1									
Commenced at: 5/13	3/2021		Zone Producing (Upper or Lower): UPPER						
Time			Prod Zone						
(date/time)	Since*	Upper zone	Lower zone	Temperature	Remarks				
5/13/2021 12:07 PM	12	200	108		started vent to pit				
5/13/2021 12:12 PM	12	85	108		Crossover met				
5/13/2021 12:17 PM	12	50	108						
5/13/2021 12:22 PM	12	30	108						
5/13/2021 12:27 PM	12	20	108						
5/13/2021 12:32 PM	12	10	108						
5/13/2021 12:37 PM	12	5	108						
5/13/2021 12:42 PM	12	5	108						
5/13/2021 1:25 PM	13	55	108		30 min Build				

Production rate during test

OII: BPOD Based on: Bbis. In Hrs. Grav. GOR	Hrs. Grav. GOR				Oil:
---	----------------	--	--	--	------

Gas

MCFPD; Test thru (Orifice or Meter)

Mid-Test Shut-In Pressure Data

Upper Completion	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. PSIG	Stabilized?(Yes or No)
Lower Completion	Hour, Date, Shut-In		SI Press. PSIG	Stabilized?(Yes or No)

(Continue on reverse side)

Northwest New Mexico Packer-Leakage Test

•

		Flov	w Test No. 2					
Commenced at:			Zone Pro	ducing (Uppe	r or Lower)			
Time	Lapsed Time	PRESS	SURE	Prod Zone				
(date/time)	Since*	Upper zone	Lower zone	Temperature		Remarks		
Production rate during	test							
Oil:BPOD	Based on:	Bbls. In	Hrs.		Grav.	GOR		
Gas	MCFPD; Test th							
		,	,					
Remarks: Witness Monica Kuehl								
I hereby certify that the	information herein c	ontained is true	and complete	to the best of	my knowledge.			
Approved:		20	Operat	or: Hilcorp E	Energy Company	/		
New Mexico Oil Co	nservation Division		By:	Ned Hernand	dez			
By:			Title:	Multi-Skilled	Operator			
Title:				Date: Friday, May 14, 2021				
				T Tiday, May	14, 2021			
	NORTI	HWEST NEWMEXICO	PACKER LEAKAGE	TEST INSTRUCTIO	NS			
 A packer leakage test shall be comm completion of the well, and annually there Such tests shall also be commenced on all chemical or fracture treatment, and when 	eafter as prescribed by the order authori multiple completions within seven days	izing the multiple completion. s following recompletion and	for Flow Tes /or remain shut-i	t No. 2 is to be the same a		dicated during Flow Test No. 1. Procedure that the previously produced zone shall eed.		
the tubing have been disturbed. Tests sha requested by the Division.	Il also be taken at any time that commu	inication is suspected or when	7. Pressure			th a deadweight pressure gauge at time g of each flow period, at fifteen-minute		
 At least 72 hours prior to the common 	encement of any packer leakage test, th	e operator shall notify the	intervals duri immediately	ing the first hour thereof, prior to the conclusion of	and at hourly intervals thereaft each flow period. 7-day tests	ter, including one pressure measurement : immediately prior to the beginning of each		
Division in writing of the exact time the te			to the conclu		Other pressures may be taken	tely the midway point) and immediately prior as desired, or may be requested on wells		
 The packer leakage test shall commo stabilization. Both zones shall remain shu however, that they need not remain shut-i 	tt-in until the well-head pressure in each		24-hour with recordin once at the en completion, t	r oil zone tests: all pressur ng pressure gauges the acc nd of each test, with a dea	es, throughout the entire test, curacy of which must be check adweight pressure gauge. If a	shall be continuously measured and recorded ed at least twice, once at the beginning and well is a gas-oil or an oil-gas dual ly, with deadweight pressures as required		
4. For Flow Test No. 1, one zone of th while the other zone remains shut-in. Suc								
24 hours in the case of an oil well. Note: atmosphere due to lack of a pipeline conn	if, on an initial packer leakage test, a ga	as well is being flowed to the	8. The rest test. Tests sh Northwest N	hall be filed with the Azter www.Mexico Packer Leaka	c District Office of the New M ge Test Form Revised 10-01-7	e within 15 days after completion of the lexico Oil Conservation Division on 78 with all deadweight pressures indicated vity and GOR (oil zones only).		
5. Following completion of Flow Test 1 above.	No. 1, the well shall again be shut-in, in	accordance with Paragraph 3	5					

District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410

COMMENTS

Action 28226

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS							
Operator:				OGRID:	Action Number:	Action Type:	
	HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	37217	28226	PACKER LEAKAGE TEST (NW)	
Created B	у	Comment			Comme	nt Date	
kpickford		KP GEO Review 5/14/2021			05/14/2	021	

District I 1625 N. French Dr., Hobbs, NM 88240

Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV

CONDITION	s

Action 28226

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	28226	PACKER LEAKAGE TEST (NW)
OCD Reviewer			Condition		
kpickford			None		