

Submit a Copy To Appropriate District
Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-021-20114
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Bravo Dome Carbon Dioxide Gas Unit
8. Well Number 331
9. OGRID Number 16696
10. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas Unit 640

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

OXY USA Inc.

3. Address of Operator

P.O. Box 4294, Houston, TX 77210

4. Well Location

Unit Letter F : 1980 feet from the North line and 1980 feet from the West line
Section 33 Township 20N Range 32E NMPM County Harding

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4860'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

OXY USA INC respectfully requests a five year Temporarily Abandon Status Extension from the current TA expiration date of 9/30/2020. Plan forward is as follows:

1. Set retrievable bridge plug ~50' above top perf
2. Notify NMOCD of casing integrity test 24hours in advance to witness test
3. RU pump truck, circulate well with treated water, pressure test casing to 500 psi for 30 min

Please note this is a monitor well

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roni Mathew TITLE Regulatory Analyst Sr. DATE 8/23/2021

Type or print name Roni Mathew E-mail address: roni_mathew@oxy.com PHONE: 713-215-7827

For State Use Only

APPROVED BY: Monica Kuehling TITLE Deputy Oil and Gas Inspector DATE 9/10/2021

Conditions of Approval (if any):

Roni Mathew

8/23/2021

Current Wellbore

Bravo Dome CDGU #331


30-021-20114-0000

Harding

String 1
OD 8.625 in
TD 701 ft
TOC 0 ft

Prod Zone
2239 ft
2449 ft

String 2
OD 5.5 in
TD 2667 ft
TOC 0 ft
PBTD 2617 ft



Tubing Assembly
OD 2.375 in
Top 0 ft
Bot 2253 ft


Roni Mathew
8/23/2021

Proposed Wellbore
Bravo Dome CDGU #331
30-021-20114-0000
Harding

String 1
OD 8.625 in
TD 701 ft
TOC 0 ft

Prod Zone
2239 ft
2449 ft

String 2
OD 5.5 in
TD 2667 ft
TOC 0 ft
PBTD 2617 ft



District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 46039

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 46039
	Action Type: [C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	NMOCD witness required on all testing. Northwest bradenhead test required prior to MIT - performed day of MIT - all valves need to be dug out and plumbed to surface - do not bury till after testing - chart recorder with 1000 lb spring - 1 hour clock - chart should match spring and clock	9/10/2021