

**District II - Artesia**811 S. 1<sup>st</sup> Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

**State of New Mexico**  
**Energy, Minerals and Natural Resources Department**  
**Oil Conservation Division Artesia District Office**

**BRADENHEAD TEST REPORT**

|                                          |                            |
|------------------------------------------|----------------------------|
| Operator Name<br>BXP Operating, LLC      | API Number<br>30-015-10101 |
| Property Name<br>North Benson Queen Unit | Well No.<br>9              |

**7. Surface Location**

|               |               |                 |              |                   |               |                   |               |                |
|---------------|---------------|-----------------|--------------|-------------------|---------------|-------------------|---------------|----------------|
| UL - Lot<br>F | Section<br>28 | Township<br>18S | Range<br>30E | Feet from<br>2310 | N/S Line<br>N | Feet From<br>1980 | E/W Line<br>W | County<br>EDDY |
|---------------|---------------|-----------------|--------------|-------------------|---------------|-------------------|---------------|----------------|

**Well Status**

|                  |                                                                          |                                                                            |                     |                   |
|------------------|--------------------------------------------------------------------------|----------------------------------------------------------------------------|---------------------|-------------------|
| TA'D Well<br>YES | SHUT-IN<br><input checked="" type="radio"/> YES <input type="radio"/> NO | INJECTOR<br><input checked="" type="radio"/> INJ <input type="radio"/> SWD | PRODUCER<br>OIL GAS | DATE<br>6-22-2021 |
|------------------|--------------------------------------------------------------------------|----------------------------------------------------------------------------|---------------------|-------------------|

**OBSERVED DATA**

|                             | (A) Surf-Interm.                      | (B) Interm. (1) | (C) Interm. (2) | (D) Prod Casing                       | (E) Tubing                              |
|-----------------------------|---------------------------------------|-----------------|-----------------|---------------------------------------|-----------------------------------------|
| Pressure                    | 0                                     |                 |                 | 0                                     | 0                                       |
| <b>Flow Characteristics</b> |                                       |                 |                 |                                       |                                         |
| Puff                        | Y/ <input checked="" type="radio"/> N | Y/N             | Y/N             | Y/ <input checked="" type="radio"/> N | CO2 _____                               |
| Steady Flow                 | Y/ <input checked="" type="radio"/> N | Y/N             | Y/N             | Y/ <input checked="" type="radio"/> N | WTR <input checked="" type="checkbox"/> |
| Surges                      | Y/ <input checked="" type="radio"/> N | Y/N             | Y/N             | Y/ <input checked="" type="radio"/> N | GAS _____                               |
| Down to nothing             | <input checked="" type="radio"/> Y N  | Y/N             | Y/N             | <input checked="" type="radio"/> Y N  | If applicable type                      |
| Gas or Oil                  | Y/ <input checked="" type="radio"/> N | Y/N             | Y/N             | Y/ <input checked="" type="radio"/> N | fluid injected for                      |
| Water                       | Y/ <input checked="" type="radio"/> N | Y/N             | Y/N             | Y/ <input checked="" type="radio"/> N | Waterflood                              |

If Braden head flowed water, check all the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

|                                                                                                |                                  |
|------------------------------------------------------------------------------------------------|----------------------------------|
| Signature:  | <b>OIL CONSERVATION DIVISION</b> |
| Printed name: M. Y. Merchant                                                                   | Entered RBDMS                    |
| Title: Production Manager                                                                      | Re-test                          |
| E-mail Address: mymerch@Penrocoil.com                                                          |                                  |
| Date: 6-22-2021                                                                                | Phone: 575-492-1236              |
| Witness:                                                                                       |                                  |

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 33903

**CONDITIONS**

|                                                                      |                                                            |
|----------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>BXP Operating, LLC<br>P.O. Box 7227<br>Dallas, TX 75209 | OGRID:<br>329487                                           |
|                                                                      | Action Number:<br>33903                                    |
|                                                                      | Action Type:<br>[UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

**CONDITIONS**

| Created By | Condition                      | Condition Date |
|------------|--------------------------------|----------------|
| gcordero   | well to be repaired or plugged | 11/18/2021     |